For 3160-5 (August 2007)	DE B SUNDRY	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT NDRY NOTICES AND REPORTS ON WELL use this form for proposals to drill or to re-end			ECEIVED		FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMNM02391A		
abandoned well. Use form 3160-3 (APD) for such proposals AHTESIA						6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.						7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well Oil Well		JAN 2 2 2013 8. Well Name and No. /		7					
2. Name of Operat LINN OPERA			9. API Well No. 30-025-21856-0	9. API Well No. 30-025-21856-00-S1					
3a. Address3b. Phone N600 TRAVIS STREET SUITE 5100Ph: 281-8HOUSTON, TX 77002Ph: 281-8				b. (include area code) 10. Field 10-4272 QUA		10. Field and Pool, or QUAIL RIDGE	Field and Pool, or Exploratory QUAIL RIDGE		
4. Location of Wel	., R., M., or Survey Description	n)	11. County or Parish, and State						
Sec 21 T19S R34E NENW 660FNL 1980FWL						LEA COUNTY, NM			
12	2. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE	NATURE OF	NOTICE, RI	EPORT, OR OTHE	R DATA		
TYPE OF SU	TYPE OF SUBMISSION					TYPE OF ACTION			
Notice of Intent		□ Acidize	epen Product		ion (Start/Resume)	□ Water Shut-Off			
-		□ Alter Casing	□ Frac	ture Treat		ation	Well Integrity		
□ Subsequent	Report	Casing Repair		Construction		olete	Other		
☑ Final Abandonment Notice		Change Plans	. •	g and Abandon			Final Abandonment N tice		
		Convert to Injection	🗖 Plug	g Back	□ Water I	Disposal			
determined that 11-2-12 MIRU pluggin Tagged @ 9 11-5-12 POH w/ tbg t bbls mud lad 11-6-12 Rigged up ca 1/2 csg. Clos 11-7-12 NU BOP. RII	the site is ready for f ng equipment. D 536'. Circulated h o 8233'. Spotten en fluid.ND BOP asing jacks.Pulled aed well in.	ondonment Notices shall be fi inal inspection.) ug out cellar. ND wellhea iole w/ mud laden fluid. 25 sx class H cement @ .ND wellhead.Closed wel d stretch on csg. Free @ Spotted 50 sx class C ce otted 65 sx class C ceme	ad. NU BOP. 8233-7986'. I I in. 6100'. Cut cs ement @ 6050	Picked up 150' POH w/ tbg. Loa g @ 6000'. Laya D. Pulled out of	of tbg and R aded back sid ed down 187 cement. WO	Accepted as to p Liability under b H. ^{Intrine} restoration de w/130 jts 5 .DUE_ C. Tagged	lugging of the well have.		
14. Thereby certify	that the foregoing is	true and correct. Electronic Submission #	161529 verifie	d by the BLM W	ell Informatio	n System			
Name (Printed/)	Comm Typed) TERRY B	For LINN OPER itted to AFMSS for process	ATING INCOR	POŘATED, sent RAH MCKINNEY	to the Hobbs	2 (13DLM0830SE)	· ·		
Signature				Date 11/30/2012					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE									
<u>_</u>		5 Martine and 1							
Approved By ACCEPTED Conditions of approval, if any, are attached. Approval of this notice does not warrant or						GER	Date 01/07/2013		
Conditions of approv certify that the applic which would entitle t	Office Hobbs								
		U.S.C. Section 1212, make it a statements or representations as				ake to any department o	r agency of the United		
. ,	** BLM REV	ISED ** BLM REVISE	D ** BLM RI	EVISED ** BL		** BLM REVISE	D **		
						-			

Additional data for EC transaction #161529 that would not fit on the form

32. Additional remarks, continued

in. 11-8-12

ĩ.

Tagged plug @ 5341'. POH w/ tbg. ND BOP. RIH w/ 8 5/8 packer and set @ 34'. Pressured up on casing. Did not hold pressure. RIH and Perf'd 8 5/8 csg @ 3375'. RIH w 8 5/8 packer. Stuck @ 700'. POH w/ packer.

11-9-12

RIH w/ swedge, collar, jars and bumber sub. Work through tight spot. RIH to 3400'. POH w/ tools. RIH w/ 8 5/8 packer and set @ 3020'. Pressured up on csg to 1500 psi. Bled off pressure. POH w/ tbg and packer. Closed well in. 11-12-12

NU BOP. RIH w/ tbg to 3425'. Spotted 60 sx class C cement @ 3425-3203'. POH w/ 1800' tbg. WOC. Tagged plug @ 3215'. POH w tbg. Perf'd 8 5/8 csg @ 1894'. RIH and set packer @ 1618'. Established rate 1/2 bbl/min @ 500 psi. Sqz'd 55 sx class C cement. Displaced to 1774'. WOC. Tagged plug @ 1766'. POH to 180'. Set packer. Sqz'd 60 sx class C cement into bad spot @ 700' and displaced to 600' per Jim Amos. WOC. Tagged plug @ 549'. POH to 94'. Perf'd csg @ 475'. Sqz'd 75 sx class C cement and displaced to 375'.

11-14-12

Did not tag plug. Re-Sqz'd 75 sx cement. Displaced to 375'. WOC. Tagged plug @ 360'. POH. Perf'd csg @ 60'. Sqz'd 40 sx cement and circluated to surface. Topped off surface plug. Rigged down moved off.

11-15-12

Moved in backhoe and welder. Cut out cellar. Cut off wellhead. Welded on Ground Level Dry Hole Marker. Backfilled cellar. Removed deadmen. Cleaned location and moved off.