SUNDRY Do not use th abandoned we	EPARTMENT OF THE I SUREAU OF LAND MANA NOTICES AND REPO is form for proposals to U. Use form 3160-3 (AP	GEMENT	2 3 2013	Expires: July 31, 2010 5. Lease Serial No. NMLC059152B 6. If Indian, Allottee or Tribe Name		
	IPLICATE - Other instruc		RECEIVED	<ol> <li>If Unit or CA/Agreement, Name and/or No. NMNM91009X</li> </ol>		
Type of Well	······································		RECLI	8. Well Name and No.		
☑ Oil Well □ Gas Well □ Oth	her			CAPROCK MALJAMAR UNIT 266		
Name of Operator LINN OPERATING, INC.	Contact: E-Mail: tcallahan@	TERRY B CALLAHAN ⊉linnenergy.com		9. API Well No. 30-025-33821		
3a. Address 600 TRAVIS STREET SUITE 5100 HOUSTON, TX 77002		3b. Phone No. (include area code Ph: 281-840-4272	e)	10. Field and Pool, or Exploratory LEONARD;QUEEN, SOUTH		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		n)		11. County or Parish, and State		
Sec 24 T17S R32E Mer NMP SWNW 1828FNL 569FWL 32.822247 N Lat, 103.726663 W Lon		VL /		LEA COUNTY, NM		
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE NATURE OF	NOTICE, RE	EPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION					
- Notice of Intent	□ Acidize	Deepen	Producti	on (Start/Resume) Water Shut-Off		
□ Notice of Intent	Alter Casing	Fracture Treat				
Subsequent Report	Casing Repair	□ New Construction		lete Other		
G Final Abandonment Notice	Change Plans	Plug and Abandon		arily Abandon		
. Describe Proposed or Completed Ope	Convert to Injection	Plug Back	□ Water D	□ Water Disposal		
12/12/2012 - MIRU plugging e	inal inspection.) equipment. Dug out cell.	ND WH, NU BOP, RIH w/ 10	04 jts, 2-3/8" \	NS &		
tagged CIBP @ 3271'. Circ 79 sxs Class "C" cmt & displaced 12/13/2012 - RIH w/ tbg & tag "C" cmt from 720 to 63'. POH LD 2 its. RDPU & equipment	equipment. Dug out cell. 9 bbls brine water w/ 20 s 9 to 1367'. POH w/ 20 sto 9 de plug @ 1312'. POH 1 LD 23 jts tbg. Spot 15 s and moved out. Moved 1	xs salt gel. POH to <u>1620'</u> , LE ds & SION. to 720' & displaced to 63'. S <u>xs Class "C" cmt from 63' to</u> n welder and backhoe. Dug	0 53 jts Spot pot 65 sxs Cl surface. POF & cut off well	<u>25</u>		
tagged CIBP @ 3271'. Circ 79 sxs Class "C" cmt & displaced	equipment. Dug out cell. 9 bbls brine water w/ 20 s 1 to 1367'. POH w/ 20 sto <u>ged plug @ 1312'. POH</u> 1 LD 23 jts tbg. Spot 15 s and moved out. Moved i Hole Marker. Backfill cell	xs salt gel. POH to <u>1620'</u> , LE ds & SION. to 720' & displaced to 63'. S <u>xs Class "C" cmt from 63' to</u> n welder and backhoe. Dug lar, removed dead men. Move	D 53 jts Spot pot 65 sxs Cl surface. POI & cut off welli ed off.	<u>25</u> a <u>ss</u> 1 nead.		
tagged CIBP @ 3271'. Circ 79 sxs Class "C" cmt & displaced 12/13/2012 - RIH w/ tbg & tag "C" cmt from 720 to 63'. POH LD 2 its. RDPU & equipment	equipment. Dug out cell. 9 bbls brine water w/ 20 s 1 to 1367'. POH w/ 20 sto 1 to 1367'. POH w/ 20 sto 1 to 23 its tbg. Spot 15 s and moved out. Moved 1 Hole Marker. Backfill cell	xs salt gel. POH to <u>1620'</u> , LE ds & SION. to 720' & displaced to 63'. S <u>xs Class "C" cmt from 63' to</u> n welder and backhoe. Dug	D 53 jts Spot pot 65 sxs Cl. surface. POF & cut off welli ed off.	<u>25</u>		
tagged CIBP @ 3271'. Circ 79 sxs Class "C" cmt & displaced 12/13/2012 - RIH w/ tbg & tag "C" cmt from 720 to 63'. POH LD 2 its. RDPU & equipment	equipment. Dug out cell. 9 bbls brine water w/ 20 s 1 to 1367'. POH w/ 20 sto 1 do 1367'. POH w/ 20 sto 1 do 1367'. POH 1 LD 23 jts tbg. Spot 15 s and moved out. Moved 1 Hole Marker. Backfill cell REC DUE true and correct. Electronic Submission # For LINN ( Committed to AFMSS for	xs salt gel. POH to <u>1620</u> ', LE to 720' & displaced to 63'. S <u>xs Class "C" cmt from 63' to</u> n welder and backhoe. Dug lar, removed dead men. Move LAMATION <u>6-//-/3</u> 178800 verified by the BLM We OPERATING, INC., sent to the or processing by KURT SIMMC	D 53 jts Spot pot 65 sxs Cl surface. POF & cut off well ed off.	25 Accepted as to plugging of the well bon Liability under bond is retained until Surface restoration is completed. System 2013 ()		
tagged CIBP @ 3271'. Circ 79 sxs Class "C" cmt & displaced 12/13/2012 - RIH w/ tbg & tag "C" cmt from 720 to 63'. POH LD 2 its. RDPU & equipment Welded on above ground Dry 4. Thereby certify that the foregoing is Name(Printed/Typed) TERRY B	equipment. Dug out cell. bbls brine water w/ 20 s to 1367'. POH w/ 20 sto ged plug @ 1312'. POH LD 23 its tbg. Spot 15 s and moved out. Moved T Hole Marker. Backfill cell REC DUE true and correct. Electronic Submission # For LINN Committed to AFMSS for CALLAHAN	xs salt gel. POH to <u>1620</u> ', LE to 720' & displaced to 63'. S <u>xs Class "C" cmt from 63' to</u> n welder and backhoe. Dug lar, removed dead men. Move LAMATION <u>6-//-/3</u> 178800 verified by the BLM We OPERATING, NC., sent to the or processing by KURT SIMMC Title REGUL	D 53 jts Spot	25 Accepted as to plugging of the well bon Etability under bond is retained until Surface restoration is completed. System 2013 () ICIALIST III		
tagged CIBP @ 3271'. Circ 79 sxs Class "C" cmt & displaced 12/13/2012 - RIH w/ tbg & tag "C" cmt from 720 to 63'. POH LD 2 its. RDPU & equipment Welded on above ground Dry	equipment. Dug out cell. 9 bbls brine water w/ 20 s 1 to 1367'. POH w/ 20 sto 1 to 1367'. POH w/ 20 sto 1 to 1367'. POH 1 LD 23 its tbg. Spot 15 s and moved out. Moved 1 Hole Marker. Backfill cell REC DUE. 1 true and correct. Electronic Submission # For LINN 6 Committed to AFMSS for CALLAHAN Submission)	xs salt gel. POH to <u>1620</u> ', LE to 720' & displaced to 63'. S <u>xs Class "C" cmt from 63' to</u> n welder and backhoe. Dug lar, removed dead men. Move LAMATION <u>6-//-/3</u> 178800 verified by the BLM We OPERATING, INC., sent to the or processing by KURT SIMMC	2013	25 Accepted as to plugging of the well bon Liability under bond is retained until Surface restoration is completed. System 2013 () CIALIST III		
tagged CIBP @ 3271'. Circ 79 sxs Class "C" cmt & displaced 12/13/2012 - RIH w/ tbg & tag "C" cmt from 720 to 63'. POH LD 2 its. RDPU & equipment Welded on above ground Dry 4. Thereby certify that the foregoing is Name(Printed/Typed) TERRY B Signature (Electronic S	equipment. Dug out cell. 9 bbls brine water w/ 20 s 1 to 1367'. POH w/ 20 sto 1 to 1367'. POH w/ 20 sto 1 to 1367'. POH 1 LD 23 its tbg. Spot 15 s and moved out. Moved 1 Hole Marker. Backfill cell REC DUE. 1 true and correct. Electronic Submission # For LINN 6 Committed to AFMSS for CALLAHAN Submission)	xs salt gel. POH to <u>1620</u> ', LE to 720' & displaced to 63'. S <u>xs Class "C" cmt from 63' to</u> n welder and backhoe. Dug lar, removed dead men. Move LAMATION <u>6-11-13</u> 178800 verified by the BLM We OPERATING, NC., sent to the or processing by KURT SIMMC Title REGUL Date 01/08/2 DR FEDERAL OR STATE	2013	25 ass head. Accepted as to plugging of the well bon Liability under bond is retained until Surface restoration is completed. System 2013 () CIALIST III <u>DTED FOR RECORD</u> ELTED FOR RECORD		
tagged CIBP @ 3271'. Circ 79 sxs Class "C" cmt & displaced 12/13/2012 - RIH w/ tbg & tag "C" cmt from 720 to 63'. POH LD 2 its. RDPU & equipment Welded on above ground Dry 4. Thereby certify that the foregoing is Name(Printed/Typed) TERRY B Signature (Electronic S pproved By ditions of approval, if any, are attached	equipment. Dug out cell. bbls brine water w/ 20 st to 1367'. POH w/ 20 sto ged plug @ 1312'. POH LD 23 its tbg. Spot 15 s and moved out. Moved T Hole Marker. Backfill cell RECI DUE true and correct. Electronic Submission # For LINN Committed to AFMSS for CALLAHAN Submission) THIS SPACE FC	xs salt gel. POH to <u>1620</u> ', LE to 720' & displaced to 63'. S <u>xs Class "C" cmt from 63' to</u> n welder and backhoe. Dug lar, removed dead men. Move LAMATION <u>6-11-13</u> 178800 verified by the BLM We OPERATING, NC., sent to the or processing by KURT SIMMC Title REGUL Date 01/08/2 DR FEDERAL OR STATE Title s not warrant.or	2013	25 Accepted as to plugging of the well bon Liability under bond is retained until Surface restoration is completed. System 2013 () CIALIST III		
tagged CIBP @ 3271'. Circ 79 sxs Class "C" cmt & displaced 12/13/2012 - RIH w/ tbg & tag "C" cmt from 720 to 63'. POH LD 2 its. RDPU & equipment Welded on above ground Dry 4. Thereby certify that the foregoing is Name ( <i>Printed/Typed</i> ) TERRY B Signature (Electronic S pproved By ify that the applicant holds legal or con- ify that the applicant holds legal or con- ch would entitle the applicant of condu- tion condu-	equipment. Dug out cell. bbls brine water w/ 20 s to 1367'. POH w/ 20 sto ged plug @ 1312'. POH LD 23 its tbg. Spot 15 s and moved out. Moved T Hole Marker. Backfill cell RECI DUE true and correct. Electronic Submission # For LINN Committed to AFMSS f CALLAHAN Submission) THIS SPACE FC d. Approval of this notice does itable title to these rights in the provident of the second seco	xs salt gel. POH to <u>1620</u> ', LE to 720' & displaced to 63'. S <u>xs Class "C" cmt from 63' to</u> n welder and backhoe. Dug lar, removed dead men. Move LAMATION <u>6-11-13</u> 178800 verified by the BLM We OPERATING, NC., sent to the or processing by KURT SIMMC Title REGUL Date 01/08/2 DR FEDERAL OR STATE S not warrant or subject lease Office Office	2013 4 Control of the second s	25 ass head. Accepted as to plugging of the well bon Liability under bond is retained until Surface restoration is completed. System 2013 () CIALIST III <u>DTED FOR RECORD</u> ELTED FOR RECORD		