• Form 3160-5	INITE	ED STATES			I FOR	M APPROVED			
(August 2007)		OF THE INTERIOR			OMB	NO. 1004-0137			
	BUREAU OF LAND MANAGEMENT OCD Hobbs				Expires July 31, 2010 5. Lease Serial No.				
SUNDRY NOTICES AND REPORTS ON WELLS						NM18640			
Do not use this form for proposals to drill or to re-enter an						6. If Indian, Allottee or Tribe Name			
a	bandoned well. Use Form :		•••						
	SUBMIT IN TRIPLICATE	- Other instructions of	on page ² OCT 1 6	2012	7. If Unit or CA/ Red Hills N	Agreement, Name a	nd/or No.		
Type of Well Oil Well Oil Well Off	VED	8. Well Name and No. Red Hills North 811							
2. Name of Operator EOG Resources	Inc		• • • • • •		Unit 9. API Well No.				
3a. Address		3b.	Phone No. (include are	ea code)	9. API Well No. 30-025-3298	0 -			
	Midland, Texas 79702	/	432-686-3689		10. Field and Pool, or Exploratory Area				
S/L 6620FSL&	otage, Sec., T., R., M., or Survey Des 509 FWL, Sec 8, T25S, 2400 FEL, Sec 18, T25S	R34E 🖊			Red Hills;		/		
					Lea	NM			
12.	CHECK APPROPRIATE	BOX(ES) TO INDICA	TE NATURE OF N	OTICE, REPO	RT, OR OTHER	R DATA			
TYPE OF	SUBMISSION		TYI	PE OF ACTION					
X Notice	of Intent	Acidize	Deepen	Production	(Start/Resume)	Water Shut-Off			
		Alter Casing	Fracture Treat	Reclamation	on	Well Integrity			
Subsec	quent Report	Casing Repair	New Construction	Recomple	te	X Other			
Final A	Abandonment Notice	Change Plans	Plug and Abandon	Temporari	ly Abandon				
		Convert to Injection	Plug Back	Water Dis	posal				
following complet testing has been c determined that th EOG Resourc The Red Hil	inder which the work will be perfor ion of the involved operations. If the ompleted. Final Abandonment Not e final site is ready for final inspection es is unable to comply 1 North Unit #811 is cu A workover to repair	ne operation results in a m ices shall be filed only af on.) at this time with rrently shut-in,	ultiple completion or re ler all requirements, inc the attached B pending workove	completion in a soluting reclamation or density or density or density of the solution of the s	new interval, a For on, have been com ated 9/4/12.	m 3160-4 shall be fi apleted, and the oper	led once rator has		
	See	g toches SUBJECT TO APPROVAL B	LIKE						
14. I hereby certify that	the foregoing is true and correct								
Name (Printed Typed) Stan Wagner			Title Regulatory Analyst						
Signature	- 21/2-		Date 9/19/12		ED FOR R	FCOPD			
	THISS	PACE FOR FEDERA	·····						
Approved by			Title		CT 1 2 2012				
	y, are attached. Approval of this notice	does not warrant or certify the	t Office		CT 1 2 2092	· · · · · · · · · · · · · · · · · · ·			
the applicant holds legal or e entitle the applicant to condu	equitable title to those rights in the subject operations thereon.	t lease which would	onnet / P	WESI	LEY W. INGR	AM			
Title 18 U.S.C. Section 100 fictitious or fraudulent state	I, and Title 43 U.S.C. Section 1212, mak ments or representations as to any matter	es it a crime for any person k	nowingly and willfully to m	ake to any departu	LEU VILENGU	United States any false,	7		
	is a separation of the any matter								

•	F	R	Ω	A	21	۱1	X	

Order of the Authorized Officer

EOG Resources Inc. Red Hills North Unit - 811 API 30-025-32980 September 4, 2012

On or before October 15, 2012, provide BLM with an electronic copy (Adobe Acrobat Document) of an injection profile survey taken within the last six months and verify water is being injected only into the 3rd Bone Spring sand interval 11,334' to 12,259' TVD.

Well with a Packer – Operations

- 1) Conduct a Mechanical Integrity Test of the tubing/casing annulus after a tubing, packer or casing seal is established. Repair that seal any time more than five barrels of packer fluid is replaced within 30 days.
- 2) The minimum test pressure should be 500 psig for 30 minutes or 300 psig for 60 minutes, with 200 psig differentials between tubing and casing pressure (at test time) but no more than 70% of casing burst pressure as described by Onshore Order 2.III.B.1.h. (The tubing or reservoir pressure may need to be reduced). An alternate method for a BLM approved MIT is to have the fluid filled system open to atmospheric pressure and have a loss of less than five barrels in 30 days witnessed by a BLM authorized officer.
- 3) Document the pressure test on a calibrated recorder chart registering within 25 to 85 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed MIT. Less than 10% pressure leakoff will be evaluated site specifically and may restrict injection approval.
- 4) Make arrangements 24 hours before the test for BLM witness: email Andy Cortez <u>acortez@blm.gov</u>, (phone 575-393-3612 or 575-631-5801). If no answer, leave a voice mail with the API#, workover purpose, and a call back phone number. Note the contact, time, & date in your subsequent report.
- 5) Submit a subsequent Sundry Form 3160-5 relating the MIT activity. Include a copy of the recorded MIT pressure chart. List the name of the BLM witness or the notified person and date of notification. NMOCD is to retain the original recorded MIT chart.
- 6) Use of tubing internal protection, tubing on/off equipment just above the packer, a profile nipple, and an in line tubing check valve below the packer or between the on/off tool and packer is a "Best Management Practice". The setting depths and descriptions of each are to be included in the subsequent sundry. List (by date) descriptions of daily activity of any previously unreported wellbore workover.

- 7) Submit the original subsequent sundry with three copies to BLM Carlsbad.
- 8) Compliance with a NMOCD Administrative Order is required, submit documentation of that authorization. Approved injection pressure compliance is required. If injection pressure exceeds the approved pressure you are required to reduce that pressure and notify the BLM within 24 hours.
- 9) When injection pressure is within 50 psig of the maximum pressure, install automation equipment that will prevent exceeding that maximum. Submit a subsequent report (Sundry Form 3160-5) describing the installed automation equipment within 30 days.
- 10) Unexplained significant variations of rate or pressure to be reported within 5 days of notice.
- The casing/tubing annulus is required to be monitored for communication with injection fluid or loss of casing integrity. A BLM inspector may request verification of the annular fluid level at any time.
- 12) A "Best Management Practice" is to maintain the annulus full of packer fluid at atmospheric pressure. Equipment that will display on site, continuous open to the air fluid level is necessary to achieve this goal.
- 13) Loss of packer fluid above five barrels per month indicates a developing problem. Notify BLM Carlsbad Field Office, Petroleum Engineering within 5 days.
- 14) A suggested format for monthly records documenting that the casing annulus is fluid filled is available from the BLM Carlsbad Field Office.
- 15) Gain of annular fluid requires notification within 24 hours. Cease injection and maintain a production casing pressure of 0psia. Notify the BLM's authorized officer ("Paul R. Swartz" <<u>pswartz@blm.gov></u>, cell phone 575-200-7902). If there is no response phone 575-361-2822.
- 16) Submit a (Sundry Form 3160-5) subsequent report (daily reports) describing all wellbore activity and Mechanical Integrity Test as per item 1) above. Include the date(s) of the well work, and the setting depths of equipment: internally corrosive protected tubing, tubing on/off equipment just above the packer, and an in line tubing check valve below the packer or between the on/off tool and packer. The setting depths and descriptions of each are to be included in the subsequent sundry. List the daily descriptions of any previously unreported wellbore workover(s).

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil and gas.html

§ 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.

Order of the Authorized Officer

EOG Resources Inc. Red Hills North Unit - 811 API 30-025-32980 T25S-R34E, Sec 08 October 12, 2012

This well's recorded activity has been inactive/shut-in for more than 30 days without authorization and was shut in due to failure on 05/01/2012.

This well's recorded activity has been inactive/shut-in for more than 30 days without authorization. An inactive/shut-in well bore is a non-producing completion that is capable of production in **paying quantities** or of service use.

Consider the beneficial use prospects and the wellbore integrity of this well. Submit your plan for BLM approval on the Sundry Notice Form 3160-5 (an original and 3 copies).

As the operator you are required to: Prove the production casing integrity from no more than 100 feet above the perforations or open hole with a documented minimum pressure test of 500 psig for 30 minutes. Return the well to production or beneficial use on or before 11/15/2012.

Document the pressure test on a calibrated recorder chart registering within 25 to 85 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed MIT. Pressure leakoff will be evaluated site specifically and may restrict continued operation approval. Twenty four hours before the test contact BLM to witness; email Andy Cortez <u>acortez@blm.gov</u> or phone 575-393-3612 or 575-631-5801. If no answer, leave a voice mail with the API#, workover purpose and a call back phone number. Note the contact, time, & date in your subsequent report.

Should the mechanical integrity test fail or <u>not be conducted</u> submit a procedure to plug and abandon the well for BLM approval on or before 11/15/2012.

A detailed justification is required to receive and extension of this date.

PRS/WWI 101012