

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Hobbs
HOBBS

FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

5. Lease Serial No.

6. If Indian, Allottee, or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

9. API Well No.

10. Field and Pool, or Exploratory Area

11. County or Parish, State

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
CHISOS LTD.

3a. Address

670 DONA ANN ROAD, S.W.

3b. Phone No. (include area code)

432-238-5470

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FSL. & 1980' FEL.

SEC. 26, T17S - R32E

N/A

N/A

John's B. #3

30-025-00698

UNDESIGNATED QUEENS

LEA, NEW MEXICO

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☒ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Accepted as to plugging of the well here.
Liability under bond is retained until
Surface restoration is completed.



SEE BACK PAGE

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

JASON ROBINSON

Title CONSULTANT

Signature

JASON ROBINSON

Date 8-12-2012

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Date

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

Chm

CHISOS Ltd.

11-22-2011 – Move in and rig up pulling unit, R.U. BOP, TIH w/ tubing to tag cement @ 3465', circulate hole w/ plugging fluid, shut in tubing and BOP, shut down for night.

11-23-2011 – TOH w/ tubing, TIH w/ perforating gun to 2340', TOH w/ perforating gun, TIH w/ packer to test to 1000#, held fine, TOH w/ packer, TIH w/ tubing to spot 23 sacks @ 2397', TOH w/ tubing, WOC, TIH w/ tubing and tagged up @ 2160', TOH w/ tubing, TIH w/ perforating gun to perforate @ 1375', TIH w/ packer to pressure test @ 1421' to 1000#, held fine, TOH w/ packer, TIH w/ tubing to 1421' to spot 30 sacks cement, TOH w/ tubing, shut in BOP, S.D.F.N.

11-28-2011 – TIH w/ tubing and tagged cement @ 1060', TOH w/ tubing, TIH to perforate @ 1040', TIH w/ packer and pressure tested to 1000#, held fine, TOH w/ packer, TIH and pumped 27 sacks of cement, circulated to *Per insp.* surface. S.D.F.N. *perf @ 60' and circ. to surf.*

11-29-2011 – Cut off wellhead, welded on marker, Rigged down pulling unit.

11-30-2011 – Cleaned location, removed all caliche, disk location and planted BLM seed on location and road.