	F 0 103			
Submit 3 Copies To Appropriate District State of New Mexico Office Discrete State of New Mexico	Form C-103 / May 27, 2004			
District I 1625 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natural Resources	WELL API NO.			
District II HOBBS OCH CONSERVATION DIVISION	30-025-25365			
	5. Indicate Type of Lease			
District III 1000 Rio Brazos Rd., Aztec, NM 87410 R 2 0 2013 District IV	STATE FEE 6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM				
87505 SUNDRY NOTHEES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	West Pearl Queen Unit			
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other 🗌	8. Well Number 169			
2. Name of Operator	9. OGRID Number			
State of New Mexico formerly Xeric Oil & Gas Corporation 3. Address of Operator	25482			
1625 N. French Drive Hobbs NM 88240	Pearl Queen			
4. Well Location				
Unit Letter N : 1305 feet from the South line and 2565 feet from	the West line			
	County Lea			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
Nidau Dalamanda Tarab Asadiantina Dian Clauma				
Pit or Below-grade Tank Application or Closure	a farme manufacto matan Ni/A			
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance Pit Liner Thickness: mil Below-Grade Tank: Volume bbls: Constru				
	uction Material			
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WO				
	RILLING OPNS. 🗌 PAND A 🖊 🛛 🛛			
PULL OR ALTER CASING	NT JOB			
OTHER: OTHER:				
13 Describe proposed or completed operations (Clearly state all pertinent details and				
	d give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 2/26/13Pulled 76 jts out of well, RIH w/ gauge ring & Tag @ 2377'.	tach wellbore diagram of proposed completion			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 2/26/13Pulled 76 jts out of well, RIH w/ gauge ring & Tag @ 2377'. 2/27/13RIH w/ pkr & tried to get pumping rate, could not pump into well, ran in op	tach wellbore diagram of proposed completion			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 2/26/13Pulled 76 jts out of well, RIH w/ gauge ring & Tag @ 2377'. 2/27/13RIH w/ pkr & tried to get pumping rate, could not pump into well, ran in op 1700'.	tach wellbore diagram of proposed completion			
 of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 2/26/13Pulled 76 jts out of well, RIH w/ gauge ring & Tag @ 2377'. 2/27/13RIH w/ pkr & tried to get pumping rate, could not pump into well, ran in op 1700'. 2/28/13RIH w/ tbg & Tag @ 1747'. 	tach wellbore diagram of proposed completion en ended & spot 65 sxs cmt from 2361' to			
 of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 2/26/13Pulled 76 jts out of well, RIH w/ gauge ring & Tag @ 2377'. 2/27/13RIH w/ pkr & tried to get pumping rate, could not pump into well, ran in op 1700'. 2/28/13RIH w/ tbg & Tag @ 1747'. Spot 30 sxs @ 250' to surface. 	tach wellbore diagram of proposed completion en ended & spot 65 sxs cmt from 2361' to			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 2/26/13Pulled 76 jts out of well, RIH w/ gauge ring & Tag @ 2377'. 2/27/13RIH w/ pkr & tried to get pumping rate, could not pump into well, ran in op 1700'. 2/28/13RIH w/ tbg & Tag @ 1747'. Spot 30 sxs @ 250' to surface. Approved for pluggtm Liability under bond i of C-103 (Subsequent which may be found a	en ended & spot 65 sxs cmt from 2361' to			
 of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 2/26/13Pulled 76 jts out of well, RIH w/ gauge ring & Tag @ 2377'. 2/27/13RIH w/ pkr & tried to get pumping rate, could not pump into well, ran in op 1700'. 2/28/13RIH w/ tbg & Tag @ 1747'. Spot 30 sxs @ 250' to surface. 	en ended & spot 65 sxs cmt from 2361' to			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 2/26/13Pulled 76 jts out of well, RIH w/ gauge ring & Tag @ 2377'. 2/27/13RIH w/ pkr & tried to get pumping rate, could not pump into well, ran in op 1700'. 2/28/13RIH w/ tbg & Tag @ 1747'. Spot 30 sxs @ 250' to surface. Approved for pluggtm Liability under bond i of C-103 (Subsequent which may be found a	en ended & spot 65 sxs cmt from 2361' to			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 2/26/13Pulled 76 jts out of well, RIH w/ gauge ring & Tag @ 2377'. 2/27/13RIH w/ pkr & tried to get pumping rate, could not pump into well, ran in op 1700'. 2/28/13RIH w/ tbg & Tag @ 1747'. Spot 30 sxs @ 250' to surface. Approved for pluggtm Liability under bond i of C-103 (Subsequent which may be found a Forms, www.cmnrd.st	en ended & spot 65 sxs cmt from 2361' to rot well bore only. s retained pending receipt Report of Well Plugging) t OCD Web Page under ate.nm.us/ocd.			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 2/26/13Pulled 76 jts out of well, RIH w/ gauge ring & Tag @ 2377'. 2/27/13RIH w/ pkr & tried to get pumping rate, could not pump into well, ran in op 1700'. 2/28/13RIH w/ tbg & Tag @ 1747'. Spot 30 sxs @ 250' to surface. Approved for pluggtm Liability under bond i of C-103 (Subsequent which may be found a	tach wellbore diagram of proposed completion en ended & spot 65 sxs cmt from 2361' to rot well bore only. s retained pending receipt Report of Well Plugging) it OCD Web Page under ate.nm.us/ocd.			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 2/26/13Pulled 76 jts out of well, RIH w/ gauge ring & Tag @ 2377'. 2/27/13RIH w/ pkr & tried to get pumping rate, could not pump into well, ran in op 1700'. 2/28/13RIH w/ tbg & Tag @ 1747'. Spot 30 sxs @ 250' to surface. I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines ⊠, a general permit □	tach wellbore diagram of proposed completion en ended & spot 65 sxs cmt from 2361' to rot well bore only. s retained pending receipt Report of Well Plugging) t OCD Web Page under ate.nm.us/ocd.			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 2/26/13Pulled 76 jts out of well, RIH w/ gauge ring & Tag @ 2377'. 2/27/13RIH w/ pkr & tried to get pumping rate, could not pump into well, ran in op 1700'. 2/28/13RIH w/ tbg & Tag @ 1747'. Spot 30 sxs @ 250' to surface. I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines ⊠, a general permit □	tach wellbore diagram of proposed completion en ended & spot 65 sxs cmt from 2361' to rot well bore only. s retained pending receipt Report of Well Plugging) it OCD Web Page under ate.nm.us/ocd.			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 2/26/13Pulled 76 jts out of well, RIH w/ gauge ring & Tag @ 2377'. 2/27/13RIH w/ pkr & tried to get pumping rate, could not pump into well, ran in op 1700'. 2/28/13RIH w/ tbg & Tag @ 1747'. Spot 30 sxs @ 250' to surface. I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines ⊠, a general permit □ SIGNATURE	tach wellbore diagram of proposed completion en ended & spot 65 sxs cmt from 2361' to rot well bore only. s retained pending receipt Report of Well Plugging) t OCD Web Page under ate.nm.us/ocd.			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 2/26/13Pulled 76 jts out of well, RIH w/ gauge ring & Tag @ 2377'. 2/27/13RIH w/ pkr & tried to get pumping rate, could not pump into well, ran in op 1700'. 2/28/13RIH w/ tbg & Tag @ 1747'. Spot 30 sxs @ 250' to surface. I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines 🖾, a general permit SIGNATURE	tach wellbore diagram of proposed completion en ended & spot 65 sxs cmt from 2361' to gof well bore only. s retained pending receipt Report of Well Plugging) t OCD Web Page under ate.nm.us/ocd. e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan []. Basic Energy Services) DATE _3/11/13_ Telephone No. 432-563-3355			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 2/26/13Pulled 76 jts out of well, RIH w/ gauge ring & Tag @ 2377'. 2/27/13RIH w/ pkr & tried to get pumping rate, could not pump into well, ran in op 1700'. 2/28/13RIH w/ tbg & Tag @ 1747'. Spot 30 sxs @ 250' to surface. I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines ⊠, a general permit □ SIGNATURETITLEP&A Tech(I Type or print name: Greg Bryant E-mail address: For State Use Only	tach wellbore diagram of proposed completion en ended & spot 65 sxs cmt from 2361' to gof well bore only. s retained pending receipt Report of Well Plugging) t OCD Web Page under ate.nm.us/ocd. e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan []. Basic Energy Services) DATE _3/11/13_ Telephone No. 432-563-3355			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 2/26/13Pulled 76 jts out of well, RIH w/ gauge ring & Tag @ 2377'. 2/27/13RIH w/ pkr & tried to get pumping rate, could not pump into well, ran in op 1700'. 2/28/13RIH w/ tbg & Tag @ 1747'. Spot 30 sxs @ 250' to surface. I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines ⊠, a general permit □ SIGNATURE	tach wellbore diagram of proposed completion en ended & spot 65 sxs cmt from 2361' to gof well bore only. s retained pending receipt Report of Well Plugging) t OCD Web Page under ate.nm.us/ocd. e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan []. Basic Energy Services) DATE _3/11/13_ Telephone No. 432-563-3355			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 2/26/13Pulled 76 jts out of well, RIH w/ gauge ring & Tag @ 2377'. 2/27/13RIH w/ pkr & tried to get pumping rate, could not pump into well, ran in op 1700'. 2/28/13RIH w/ tbg & Tag @ 1747'. Spot 30 sxs @ 250' to surface. I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines ⊠, a general permit □ SIGNATURE	tach wellbore diagram of proposed completion en ended & spot 65 sxs cmt from 2361' to cof well bore only. s retained pending receipt Report of Well Plugging) t OCD Web Page under ate.nm.us/ocd.			

MAR	2,1	2013
	7	