## New Mexico Oil Conservation Division, District I


	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			1625 N. F Hobbs, I		OMB No. 1004-0137 Expires: October 31, 2014		
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals?				)	NM 02218 6. If Indian, Allottee or Tribe Name N/A			
SUBMIT IN TRIPLICATE - Other instructions on page 2. @ 2012					7. If Unit of CA/Agr	eement, Name and/or No.		
1. Type of Well				,	8. Well Name and N	o	<del></del>	
2. Name of Operator	<del></del>	·	RECEIVED		9. API Well No.	EDERAL #001 /		
HALCON HOLDINGS, INC  3b. Phone No. (include area code)					30-041-20423  10. Field and Pool or Exploratory Area			
5100 E. SKELLY DRIVE, SUITI TULSA, OK 74135	ALLISON, SAN ANDRES, EAST							
1. Location of Well (Footage, Sec., T/,R.,M., or Survey Description) 660' FSL & 1980' FEL SEC. 28, T08S, R37E					11. County or Parish, State ROOSEVELT COUNTY, NM			
12. CHEC	CK THE APPROPRIATE BOX(I	ES) TO INDI	CATE NATURE (	OF NOTIC	CE, REPORT OR OT	HER DATA		
TYPE OF SUBMISSION TYPE OF ACT					ION			
Notice of Intent	Acidize Alter Casing	Fractu	Deepen Fracture Treat		uction (Start/Resume) amation	Water Shut-Off Well Integrity		
Subsequent Report Change Plans		<ul><li>New Construction</li><li>✓ Plug and Abandon</li></ul>			Recomplete Other Temporarily Abandon			
		Plug I			r Disposal			
determined that the site is ready for WELL WAS COMPLETED IN THE REVIEW INDICATES THERE ARE ABANDON, PROPOSED WELLBO WORK IS APRIL 15, 2013. ALL WO	SAN ANDRES ON 12/30/1970 NO OTHER POTENTIAL UPI PRE DIAGRAM AND A CURRE	HOLE ZON	ES. PLEASE SEI BORE DIAGRAM.	E ATTAC THE ES	CHED THE PROPOS STIMATED STARTI	SED SUMMARY TO PL NG DATE TO PERFOR	UG AND	
		•				,		
Halcon Holdings Inc. BLM Operator But Is Downhole Plugging C Energy Inc. Approval Is Contigent On Halco	Approved To Do The Of This Well For Ram I To Change Operato	e : า - !	•	NDIN	dini A	3_MONTH PEI 2 2013	QOIS	
<u> 46</u>					·			
4. I hereby certify that the foregoing is t STEPHEN MIL		rped)	Title SR. OPER	ATIONS	ENGINEER			
Signature Signature	Munich		Date 02/21/2013	··········	ENGINEER			
9	THIS SPACE FO	R FEDEI	RAL OR STAT	TE OFF	ICE USE			
pproved by /S/ DAVII	D R. GLASS	,	PETRO	LEUM	ENGINEER	Date MAR 122	013	
onditions of approval, if any, are attached at the applicant holds legal or equitable t atifle the applicant to conduct operations	title to those rights in the subject lea	warrant or ce	rtify		ROSWELLFI			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,

## El Zorro E Federal #1 P&A Summary

- 1. Contact local BLM and NMOCD representatives at least 24 hours before starting operations. If available, have CBL for depth and collar correlation.
- 2. MIRU plugging company ng. MI 5000' 23%" tubing for workstring.
- 3. If necessary, kill well by loading hole with produced water. ND production wellhead. NU 5000 psig WP BOP w/side port. Test BOP to 300 psig and 3000 psig.
- 4. TOOH & LD BHP and rods. Release tubing anchor. TOOH & LD 2 1/6" production string.
- 5. MIRU Wireline Service. RIH w/ 5½" gauge ring and junk basket to top of perforations @ 4850'KB. POOH. PU & RIH w/ 5½" CIBP to 4800'KB. Set CIBP. PU & TIH w/glass bottom dump bailer w/ 5 sx Class H cement to top of plug. Spot cement on plug (Plug #1: 4800'KB).
- 6. PU & TIH w/ 2 %" workstring to top of cement @ 4760'KB. Circulate hole with 115 bbls 9.0 ppg drilling mud. 5 pot 40 5%. Cement Plug F/2368-2218'-Tag
- 7. TOOH to 421'KB. Circulate hole w/12 bbls fresh water. TOOH.
- 8. MIRU Wireline, RIH w/ string shot and perforate 5 ½" casing at 421'KB w/ 2 shots.
- 9. Establish injection into holes via 5 ½" casing with fresh water.
- MIRU Cementing Services (NMC Certified Cementer). MI transport loaded with 200 bbls fresh water.
- 11. Mix and pump 50 sx Class "H" cement into holes via 5 ½" casing (Plug #2: 321'-421'KB). Stage squeeze cement to standing pressure of 500 psi. Displace cement slurry w/8 bbls fresh water.
- 12. SI well overnight to allow cement to cure.
- 13. RIH w/ tubing and tag cement top @ 321'KB. Displace hole with drilling mud.
- 14. TOOH & LD tubing string. ND BOP's from 5 1/2" casing.
- 15. Spot final 10 sx Class "H" cement plug from 3'-50'KB (Plug #3). RD cementers.
- 16. Cutoff casing(s) 3' below ground level.
- 17. Weld on ID plate with API number and date plugged (vent ID plate).
- 18. Grade location and remove all remaining surface equipment.

Proposed



Engineer

Stephen Milinichik

Office#: Cell#:

(918) 714-1806


(918) 632-0608

Prepared By: SJM

Date: 2/26/2013

Updated: 2-26-2013 SJM

Current



Stephen Milinichik (918) 632-0608

Office#:

(918) 714-1806

Prepared By: SJM Date: 2/26/2013

Updated: 2-26-2013 SJM

## BUREAU OF LAND MANAGEMENT Roswell Field Office

Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 (575) 627-0272

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

- 1. Plugging operations shall commence within ninety (90) days from the approval date of this Notice of Intent to Abandon. If you are unable to plug the well by the 90<sup>th</sup> day provide the BLM Roswell Field Office (RFO), prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when the BLM Roswell Field Office can expect the well to be plugged. Failure to do so will result in enforcement action. Unless the well has been properly plugged, the rig shall not be removed from over the hole without prior approval.
- 2. <u>Notification</u>: Contact the BLM Roswell Field Office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.
- 3. <u>Blowout Preventers:</u> A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9090 feet; a 3M system for a well not deeper than 13636 feet; and a 5M system for a well not deeper than 22727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at a rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 50 feet of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" for up to 7500 feet of depth, mixed at 14.8 lbs./gal with 6.3 gallons of fresh water per sack or class "H" for deeper than 7500 feet plugs, mixed at 16.4 lbs./gal with 4.3 gallons of fresh water per sack.

- 6. Monument: Upon abandonment of the well, all casing shall be cut-off at the base of the cellar or 3-feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).
- 7. Timing Limitation Lease Stipulation / Condition of Approval For Lesser Prairie-Chicken: Oil and gas activities including 3-D geophysical exploration, and drilling will not be allowed in lesser prairie-chicken habitat during the period from March 1 through June 15 annually. During that period, other activities that produce noise or involve human activity, such as the maintenance of oil and gas facilities, geophysical exploration other than 3-D seismic operations, and pipeline, road, and well pad construction, will be allowed except between 3:00 am and 9:00 am. The 3:00 am to 9:00 am restriction will not apply to normal, around-the-clock operations, such as venting, flaring, or pumping, which do not require a human presence during this period. Additionally, no new drilling will be allowed within up to 200 meters of leks known at the time of permitting. Normal vehicle use on existing roads will not be restricted. Exhaust noise from pump jack engines must be muffled or otherwise controlled so as not to exceed 75 db measured at 30 feet from the source of the noise.
- 8. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to the BLM Roswell Field Office. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

Following the submittal and approval of the Subsequent Report of Abandonment, a Notice of Intent for Final Abandonment with the proposed surface restoration procedure must be submitted for approval.