Form 3160-5 (August 2007)

1. Type of Well

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

CHORRANDCD	
------------	--

FORM APPROVED OMB No. 1004-0137

APR 11 201

Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS	(Aran	
not use this form for proposals to drill or to re-enter	上 と に EIVE	

D Do not use this form for proposals to abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.

NM 71021X

Oil Well Gas	Well Other		Reed Sanderson		
2. Name of Operator Devon Energy Production Co., LP	<i></i>		9. API Well No. 30-025-04183		
3a. Address 333 W Sheridan Avenue, Oklahoma City, OK	73102	3b. Phone No. (include area co	′	10. Field and Pool or Exploratory Area EUMONT;YATES-7 RVRS-QUEEN	
4. Location of Well (Footage, Sec., T 660' FSL & 1980' FWL; Sec 3-T20S-R36E	,R.,M., or Survey Description	)	I1. Country or Paris Lea County, NM	h, State	
12. CHE	CK THE APPROPRIATE BO	X(ES) TO INDICATE NATUR	RE OF NOTICE, REPORT OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION				
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (Start/Resume) Reclamation	Water Shut-Off Well Integrity	
Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon	Recomplete Temporarily Abandon	Other	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		
13. Describe Proposed or Completed (	Operation: Clearly state all per	tinent details, including estimat	ed starting date of any proposed we	ork and approximate duration thereof. If	

- the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)
- 1. 3/4/13-MIRU. Tagged existing CIBP @ 3,592' with 2-3/8" production tubing.
- 2. Circulate hole w/9# mud.
- 3. Spot 25 sx cement on CIBP @ 3,592'. (calc PBD @ 3,352')

- 4. Spot 25 sx cement @ 2,801'. Tagged TOC @ 2,560'.
  5. Spot 30 sx cement @ 1,420'. Tagged TOC @ 1,108'.
  6. Perfed squeeze holes @ 375'. Pumped 130 sx cement in/out on 8-5/8" X 5-1/2" casing to surface.
- 7. 3/13/13-Cut wellhead off and set dry hole marker. Wellbore plugged & abandoned.

RECLAMATION DUE 9.9-13

Accepted as to plugging of the well hore. Liability under bond is retained until Surface restoration is completed.

14. I hereby certify that the foregoing is true and correct.  Name (Printed/Typed)  Ronnie Slack	Title Operations Technician		
Signature Rounie Spek	Date 3/18/13		
THIS SPACE FOR FEDE	RAL OR STATE OFFICE US	E	
Approved by  Conditions of approval, if any, are attached. Approval of this notice does not warrant or contact the applicant holds legal or equitable title to those rights in the subject lease which wo entitle the applicant to conduct operations thereon.	Title SE AS  ertify uld  Office	Date	4-2-13
Title 18 U.S.C. Section 1001 and Title 43 C.S.C. Section 1212, make it a crime for any per ficting or fraudulent statements or representations as tryany matter in the first purpose of the control of th	rson knowingly and willfully to make to an	y department or age	ency of the United States any false

(Instructions on page 2)

APR 1.8 2013

