Submit 3 Copies To Appropriate District	. Chata of Nove Marrian		Form C-103
Office • District I •	State of New Mexico	esources WELL API NO.	October 25, 2005
1625 N. French Dr.,Hobbs, NM 88240	Energy, Minerals and Natural Re	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	NE 05500
	OIL CONSERVATION DIV	/ISION	25-05568
District II 1301 W. Grand Ave., Artesia, NM 8821685 OCD District III	OIE GONGERVATION DIV	5. Indicate Type of Lea	
1000 Rio Brazos Rd. Aztec, NM 87410	1220 South St. Francis D		☑ FEE ∐
District IV APR 08 LO	\ Santa Fe, NM 87505	6. State Oil & Gas Leas	se No.
1220 O. Ot. I laticis Di., Calita I C, Mis	Ì	В	-2656
87505 SUNDRY NOTICES AND	D REPORTS ON WELLS	7. Lease Name or Uni	t Agreement Name
(DO NOT USE THIS FORM FOR PROPOSAL		BACK TO	/
A DIFFERENT RESERVIOR. USE "APPLICA	FION FOR PERMIT" (FORM C-101) F	OR SUCH NORTH WORLD	nt G/SA Unit: Blk 01
PROPOSALS.)		8. Well Number	
1. Type of Well: Oil Well Gas Well Gas Well	Other	O OCRID Number	9 /
2. Name of Operator	Corporation /	9. OGRID Number	0873
3. Address of Operator	orporation /	10. Pool Name	0073
· ·	Ste. 3000, Midland, TX, 79705		nument;G/SA
4. Well Location		•	/
Unit Letter :		line and 660 feet from th	· · · · · ·
	ownship 19S Range evation (Show whether DR, RKB,RT,	37E NMPM	County Lea /
11. =1	3716' GR	GR, etc.)	
			* 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
12. Check Appropriate Box To Indicate N	ature of Notice, Report, or Other D)ata	
NOTICE OF INTEN	TION TO:	SUBSEQUENT RE	PORT OF:
	AND ABANDON REMEDIAL W		
	= 1	DRILLING OPNS. P AND A	7
	PLE COMPL CASING/CEM		<u></u>
DOWNHOLE COMMINGLE		_	
OTHER:		Location is ready for OCD inspection	after D&A
✓ All pits have been remediated in compliance v			alter FOA
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
A steel marker at least 4" in diameter and at le	ast 4' above ground level has been set in	concrete. It shows the	
OPERATOR NAME, LEASE N	AME, WELL NUMBER, API NUMBE	R. QUARTER / QUARTER LOCAT	ION OR
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and			
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.			
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from the lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.)	cinoved. I ottable bases have been ferri	Sved. (1 dured briske concrete bases de	5 Hot have
All other environmental concrens have been a	ddressed as per OCD rules.		
Pipelines and flow lines have been abandoned	in accordance with 19.15.9.714.B(4)(b) N	IMAC. All fluids have been removed fro	m
non-retrieved flow lines and pipelines.			
When all work has been completed, return this	form to the appropriate District office to	schedule an inspection. If more than on	ė.
inspection has to be made to a P&A location b		The state of the s	
000			
SIGNATURE ten Sulling	TITLEP&	A Technician DATE	4/4/13
TVDE OD DDINT WARE			100 000 000
TYPE OR PRINT NAME Leon Selic	rs E-MAIL <u>leon.seller</u>	s@apachecorp.com PHONE:	432-208-0349
For State Use Only	Λ	100	
APPROVED BY: Wash Wh	TITLE Ouplie	nce Officer DATE	05/06/2013
Conditions of Approval (if any):	•		/
			,