Form 3160-5 (March 2012)

UNITED STATES DEPARTMENT OF THE INTERIOR

OCD Hobbs

FORM APPROVED

OMB No. 1004-0137
Expires: October 31, 20

BUR	EAU OF LAND MAN	AGEMENT	5. Lease Serial No. NM 86710		
SUNDRY N	OTICES AND REPO	RTS ON WELLS	HOBBS Offindian, Allottee	or Tribe Name	
Do not use this t	form for proposals to	o drill or to re-enter a			
abandoned well.	Use Form 3160-3 (A	PD) for such proposa			
	T IN TRIPLICATE – Other	instructions on page 2.	APR 1 7. If Unit of CA/Ag	eement, Name and/or No.	
1. Type of Well Oil Well X Gas W	Vell Dother		RECE 8/Well Name and N Bilbrey 33 Fe	o.	
2. Name of Operator			9. API Well No. 30-025-3078		
ConocoPhillips Company 3a. Address		3h Phone No. (include area o	o. Phone No. (include area code) 10. Field and Pool or Exploratory Area		
P. O. Box 51810 Midland TX 79710		·	(432)688-9174 Bilbrey; Morrow/Atoka		
4. Location of Well (Footage Sec. T.R.M., or Survey Description) UL C, 660' FNL & 1980' FWL, Sec 33, 21S, 32E				11. County or Parish, State	
——————————————————————————————————————	VL, Sec 33, 213, 32E		Lea		
12. CHEC	K THE APPROPRIATE BO	X(ES) TO INDICATE NATU	RE OF NOTICE, REPORT OR OT	HER DATA	
TYPE OF SUBMISSION		T	YPE OF ACTION	OF ACTION	
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	Other extension for	
	Change Plans	Plug and Abandon	Temporarily Abandon	work to be	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	performed	
determined that the site is ready for ConocoPhillips would like to NOI submitted 10/8/12, of 93/21/13 to 6/21/13.	o request for an exter				
0/2 / 10 to 0/2 / 10.					
		•		•	
			·	,	
		· · · · · · · · · · · · · · · · · · ·	SEE ATTA CONDITIONS	CHED FOR OF APPROVAL	
				·	
14. I hereby certify that the foregoing is tr	ue and correct. Name (Printed)	(Typed)	· · · · · · · · · · · · · · · · · · ·		
Rhonda Rogers		Title Staff Regulatory Technician			
Signature Mon	John	Date 02/20/	2013	VED	
	THIS SPACE F	OR FEDERAL OR ST	TATE OFFICE USE KU	VEU	
Approved by			ADD -6	2013	
Canditions of approval if any are attached	Approval of this nation does a	Title	<u> </u>	Date ·	

Office

(Instructions on page 2)

that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct obstations thereon

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department

of the United States any false,

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

Extension of time is approved
Well is to be plugged by 6/21/2013

- 1. The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.
- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon. (9# **brine is not mud**)
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). **The BLM is to be notified a minimum of 4 hours**

prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. All prior COAs apply.