1			New	Mexico Of	l Conse	rvation Divisio	om, Mistrie: 1	
		1625 N. French Drive						
Form 3160-5 (March 2012)	UNITED STATES DEPARTMENT OF THE INTERIOR				houw,	NDA SUNZARD	OMB No. 1004-0137 Expires: October 31, 2014	
	GEMENT			5. Lease Serial No. NM-04385				
		TICES AND REPOI rm for proposals to				6. If Indian, Allottee	or Tribe Name	
		se Form 3160-3 (AF						
	nstructions of	OB35 OCD 1 page 2.	OCD 7. If Unit of CA/Agreement, Name and/or No.					
1. Type of Well	Gas We	l X Other	MA	Y 1 7 2013		8. Well Name and No)	
2. Name of Operator				P. API Well No.				
Celero Énergy I 3a. Address	I, LP	r	ECEIVED	de)	30-005-00888 10. Field and Pool or Exploratory Area			
400 W. Illinois,		586-1883	6-1883 Caprock; Queen					
4. Location of Well (Fa Sec 27, Unit I,		11. County or Parish, State			State			
1980' FSL & 660' FEL					Chaves, NM CATE NATURE OF NOTICE, REPORT OR OTHER DATA			
			(ES) 10 IND	·····				
	YPE OF SUBMISSION				PE OF ACT	ION uction (Start/Resume) Water Shut-Off		
X Notice of Intent		Alter Casing	Deep	ure Treat		amation	Well Integrity Workover	
Subsequent Report		Casing Repair		Construction	 4	omplete	Other Convert from monitor to	
Final Abandonment Notice		Change Plans	Plug	and Abandon Back		porarily Abandon er Disposal	producing well	
testing has been con determined that the 1. Pressure test 2. Kill well, if ne 3. PU workstring 4. RIH with proof tubinghead, and 5. Run 2-3/8", 4 clearance. Pun again every 10 pressure indicat 6. Circulate hole ND BOPE and i	npleted. Final Al site is ready for f t tubing-by-ca cessary, and g and RIH to duction packed NU BOPE. 7#, J-55, 8rd np through ea joints or so w tes either 1⁄4" e with inhibite nstall top flar	oandonment Notices must be inal inspection.) asing annulus. ND well head, NU E TD w/ bit, 1-DC, gau er w/plug in place if n	C production ROPE, and Decessary a C production n the spoor and record RIH. fluid and t d flowtee.	POOH w/tub mill, 3-DC's. and recover k on tubing and I and record pump presso est casing.	s, including bing and Circulate kill fluid. I 1/4" cap pump pr ure. Pull Space ou uction.	packer. e clean & POOH POOH, ND BOF o strings. RIH ve essure. Pump th I out and check e	PE, install CO2 ery slowly due to limited nrough each string each string if pump nd test cap strings.	
14. 1 hereby certify that the	he foregoing is true	and correct. Name (Printed)	(Typed)	I				
Lisa Hunt Title Regulatory Analyst								
signature Rusa Hunt				Date 05/03/2013				
		THIS SPACE F	OR FEDE	RAL OR ST	ATE OF	FICE USE		
Approved by /S/ DAVID R. GLASS				PETROLEUM ENGINEER Date MAY 1 4 2013				
Conditions of approval, if that the applicant holds leg entitle the applicant to con		ertify						
Title 18 U.S.C. Section 10 fictitious or fraudulent star	01 and Title 49 U. tements or represe	S.C. Section 1212, make in a contractions as to any matter with	rime for any po in its jurisdictio	erson knowingly ar 1.	nd willfully t	o make to any departme	nt or agency of the United States any false,	
(Instructions on page 2)				· · · · · · · · · · · · · · · · · · ·				
						NA 1 14	e . 'oodo'	

.)

MAY 2 1 2013