Submit 1 Copy To Appropriate District	State of New Me	xico		Form C-103
$\frac{\text{Office}}{\text{District I}} \xrightarrow{5} 575) 393-6161 \qquad \qquad \text{Energ}$	Energy, Minerals and Natural Resources			Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88249S OCD			WELL API NO. 30-025-25314	
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION			5. Indicate Type of L	ease
District III – (505) 334-6178 III A 7 2013 1000 Rio Brazos Rd., Aztec, NM 874 10 7 2013 District IV – (505) 476-3460 1220 South St. Francis Dr. Santa Fe, NM 87505			STATE 🖂	FEE 🔲 🖊
<u>District 11</u> (200) 110 2100			6. State Oil & Gas Le	ease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505 PFCEIVED				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Un	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Scratchy Ranch A	QC State
PROPOSALS.)			8. Well Number	(
1. Type of Well: Oil Well Gas Well				
Name of Operator EnerVest Operating, LLC			9. OGRID Number 143199	
3. Address of Operator			10. Pool name or Wildcat	
1001 Fannin Street, Suite 800 Houston TX	77002		Feather; Upper Penn,	East
4. Well Location		····		
Unit LetterJ:2030f	eet from theSouth	line and198)feet from the _	Eastline
Section 14 Township				inty Lea
11. Elevat	ion (Show whether DR,			
	4226'	GR		
	Den te Indiante N	ture of Mation	Domo <i>nt</i> on Othon Do	t
12. Check Appropriate	e Box to Indicate Na	ature of Notice,	Report or Other Da	ta
NOTICE OF INTENTION	I TO:	SUB	SEQUENT REPO	RT OF:
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WOR			K 🔲 ALTERING CASING 🗌	
—				ND A
PULL OR ALTER CASING 🛛 MULTIPLE		CASING/CEMENT	ЈОВ 🗌	
OTHER:		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
EnerVest Operating, L.L.C. respectfully request to Temporarily Abandon this well due to it being uneconomical at the present				
time. During the TA period, if approved, we will continue to evaluate the well for further potential. The procedure for TA is				
outlined below:				
	z 1.111. 1 1 .	•	1	
 Kill well if necessary w/2% KCL. Keep kill truck on location to use as needed. POOH w/rods and pump. 				
- NDWH, NUBOP and test.				
- MIRU wireline & RIH w/4-1/2" CBP, set $@ \sim 10,486$ '.				
- Bail ~20° cmt on top of plug.				
 Notify NMOCD of intent to demonstrate mechanical integrity. Load csg w/2% KCL & test to 600 psi. Chart test & wait for for approval from NMOCD. 				
- Load csg w/2% KCL & test to 600 - TROMPConservation Division	psi. Chart test & wait i	or for approval from	I NMOCD.	
				-
MUST BE NOTIFIED 24 Hours	י ך `		proval: Notify OCD	
Spud Daprior to the beginning of operatio	ns Rig Release	office 24 hours	prior to running MIT	Test & Chart
ŧ		L	J	
I hereby certify that the information above is true	and complete to the be	st of my knowledge	and belief.	
SIGNATURE	TITLE	Regulatory A	nalyst DATE	6/05/2013
_				
Type or print nameBart Treviño	E-mail address	:btrevino@ene	ervest.net PHO	NE:713-495-5355_
For State Use Only		/		
APPROVED BY: Competer	TITLE /	J. Maz	DATE	610-2012
Conditions of Approval (if any):				
	<r .<="" td=""><td></td><td>11</td><td></td></r>		11	
	. ک		J	JN 1 0 2013

