	Submit 1 Copy To Appropriate District State of New Mexico Office	Form C-103 October 13, 2009
	District I – (575) 393-6161 Energy, Minerals and Natural Resources District II – (575) 748-1283 District II – (575) 748-1283	WELL API NO. 30-025-10546
	District III         - (575) 746-1263           811 S. First St., Artesia, NM 88210         OIL CONSERVATION DIVISION           District III         - (505) 334-6178           1000 Rio Brazos Rd., Aztec, NM 87410         1 2 2013           1220 South St. Francis Dr.           Santa Fe           NM 87505	5. Indicate Type of Lease STATE FEE
	<u>District IV</u> – (505) 476-3460 Santa FC, 19191 87505 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No. 307841
.**.	87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C.101) FOR SUCH	7. Lease Name or Unit Agreement Name SKELLY PENROSE B UNIT
	1. Type of Well: Oil Well Gas Well Other TA inj.	8. Well Number 003
	2. Name of Operator PROVIDENCE ENERGY SERVICES, INC. dba KELTON OPERATING	9. OGRID Number 01244 😫
	3. Address of Operator P.O. BOX 928, ANDREWS, TEXAS, 79714-0928	10. Pool name or Wildcat LANGLIE MATTIX (37240)
	4. Well Location	
	Unit LetterD: 660feet from the NORTHline and 99Section32Township22SRange37EN	
	Interview     Interview     Interview     Interview     Interview     Interview       11. Elevation (Show whether DR, RKB, RT, GR, etc.)	MPM County LEA
	12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
	NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
	TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRI         PULL OR ALTER CASING       MULTIPLE COMPL       CASING/CEMENT         DOWNHOLE COMMINGLE       O	—
	OTHER: D OTHER:	
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.</li> <li>1. MIRU plugging equipment.</li> <li>2. Tag CIBP @ 3541' -</li> <li>3. Circulate hole w/ mud laden fluid.</li> <li>4. Spot 25 sx cement on top of CIBP 3541-3291.</li> <li>5. Spot 25 sx cement @ 2650-2400 WOC &amp; Tag. (Btm of Salt)</li> <li>6. Spot 25 sx cement @ 2650-2400 WOC &amp; Tag. (Btm of Salt)</li> <li>6. Spot 25 sx cement @ 1450-1300 (top of salt).</li> <li>7. Spot 65 sx cement @ 360- surface.</li> <li>8. Cut off wellhead and install Dry Hole Marker.</li> </ul>		
Ä	FThis well in R5003 area. Cement regulied a	cross entire solt section
	Spud Date: Rig Release Date:	
-	I hereby certify that the information above is true and complete to the best of my knowledge	e and belief.
	SIGNATURE C. Dem Kot TITLE FRESIDENT	DATE 6.11-13
		A un and un to un and
	Type or print name CDALE, KELTONE-mail address: PEDVIOENCE	energy Phone: 432-661-1369
	APPROVED BY Gongeho TITLE DET MGF	DATE-13-2013
$\int$	Willst be Notified	Forms On-A-Disk · (214) 340-9429 · FormsOnADisk.com
' 1	24 hours prior to the beginning of Plugging Operations begin.	JUN 1 3 2013



