

Submit 1 Copy To Appropriate District Office District 1 – (575) 393-6161 State of New Mexico HOBBEnergy, Minerals and Natural Resources	Form C-103 October 13, 2009
1625 N French Dr. Hobbs NM 88240	WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 JUN 1012 CONSERVATION DIVISION	3002510673       5. Indicate Type of Lease
District III – (505) 334-6178 1220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 <b>RECEIVED</b> Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	301940
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	<ul> <li>7. Lease Name or Unit Agreement Name</li> <li>SKELLY PENROSE B UNIT</li> <li>8. Well Number 056</li> </ul>
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other	9. OGRID Number
<ol> <li>Name of Operator</li> <li>PROVIDENCE ENERGY SERVICES, INC. dba KELTON OPERATING</li> <li>Address of Operator</li> <li>P.O. BOX 928, ANDREWS, TEXAS, 79714-0928</li> </ol>	12444 10. Pool name or Wildcat LANGLIE MATTIX (37240)
4. Well Location	
Unit Letter L : 1980 feet from the <u>SOUTH</u> line and <u>660</u> feet from the <u>WEST</u> line	
Section 8 Township 23S Range 37E NMPM LEA County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK 📋 PLUG AND ABANDON 🛛 REMEDIAL WORK 🔲 ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A	
	ГЈОВ 🗌
OTHER: OTHER:	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.</li> <li>MIRU plugging equipment.</li> <li>Tag CIBP @ 3,459'.</li> <li>Circulate hole with mud laden fluid.</li> <li>Spot 25 sx cenebt @ 3,459' on top of CIBP.</li> <li>Spot 25 sx cement @ 2,450' 2,200'. WOC &amp; Tag (btm of salt).</li> <li>Spot 25 sx cement @ 1,400' 1,150'. WOC &amp; Tag (top of salt).</li> <li>Spot 25 sx cement @ 360'-surface.</li> <li>Cut off well head and dry hole marker.</li> </ol>	
IF This well in R5003 and. Cement required across entire salt section	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge	e and belief.
SIGNATURE CLARK TITLE RESIDENT DATE 6-11-13	
Type or print name CDALE KELTON E-mail address: PHONE:	
APPROVED BY: Arm TITLE DIST. MAR DATE 6-15-2013 Conditions of Approval (If any):	
Oil Conservation Division - Hobbs office: Must be Notified	r Forms On-A-Disk · (214) 340-9429 · FormsOnADisk.com
24 hours prior to the beginning of Plugging Operations begin.	JUN 1 3 2013 7000





·