Office	State of New Mexi	ico	•	Form C-103
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 Energy. 1025 N. French Dr., Hobbs, NM 88240	Dr., Hobbs, NM 88240 RECEIVED		WELL API NO. 30-025-03295	Revised August 1, 2011
OIL CONSERVATION DIVISION District III – (505) 334-6178 APR 2 2 2022 South St. Francis Dr.		is Dr.	5. Indicate Type of Lease	
District IV – (505) 476-3460 Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.		
87505			E-8184	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name East Pearl Queen Unit	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other		8. Well Number 3		
Name of Operator State of New Mexico formerly Xeric Oil & Gas			9. OGRID Number	
3. Address of Operator			10. Pool name or Wildcat	
1625 N. French Drive Hobbs, New Mexico 88240			Pearl Queen	
4. Well Location Unit Letter A : 660 feet	from the North line	and 660	feet from the East	line
		lange 35E	NMPM Lea	County
II. Elevatio	on (Show whether DR, R	RKB, RT, GR, etc.)		
12. Check Appropriate	Box to Indicate Nat	ture of Notice,	Report or Other D	ata
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON ☑ TEMPORARILY ABANDON □ CHANGE PLANS □ COMMENCE DRILLING OPNS.□ P AND A PULL OR ALTER CASING □ MULTIPLE COMPL □ CASING/CEMENT JOB □ DOWNHOLE COMMINGLE □				LTERING CASING 🗌
OTHER:		OTHER:		П
 Describe proposed or completed operatio of starting any proposed work). SEE RU proposed completion or recompletion. 	ns. (Clearly state all per	rtinent details, and		
SEE ATTACHMENTS: PROCEDURE & SCHEMATIC				
Spud Date:	Rig Release Date	:		
I hereby certify that the information above is true	and complete to the best	of my knowledge	e and belief.	
SIGNATURE Mah Whitale	TITLE_Complia	nce Officer	DATE_	_04/19/2013
		E-mail address:		
APPROVED BY:	TITLE		DATI	E

JUN 1 8 2013

State of New Mexico formerly Xeric Oil & Gas Corp East Pearl Queen Unit No. 39

Go in hole and tag CIBP @ 4628'. Cap w/ 25 sx. Pressure test csg. Circulate hole w/ 9.5 ppg brine w/ 25 sx salt gel per 100 bbls. Perf at 3400'. Attempt to sqz w/ 25 sx cmt. WOC and Tag. Perf at 1800'. Attempt to sqz w/ 25 sx cmt. WOC and Tag. Perf at 157'. Circulate cmt to surface. Cut off wellhead and install dry hole marker.

