



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

SUSANA MARTINEZ

Governor

David Martin

Cabinet Secretary - Designate

Brett F. Woods, Ph.D.

Deputy Cabinet Secretary

Jami Bailey

Director

Oil Conservation Division

Response Required – Deadline Enclosed

Field Inspection Program

"Preserving the Integrity of Our Environment"

20-Jun-13

ENERVEST OPERATING L.L.C.

1001 FANNIN STREET SUITE 800

HOUSTON TX 77002

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

BRITT-LAUGHLIN COM No.005

O-5-20S-37E

30-025-05907-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/19/2013	Routine/Periodic	Mark Whitaker	Yes	No	7/31/2013	iMAW1317125065
Violations						
Surface Damage/Restoration						

Comments on Inspection: Operator has failed to complete restoration within 1 year of plugging date (Rule 19.15.25.10.D). Well sign, power disconnect, and conduit protruding from ground west of marker should be removed. Remove transformers, meter base, and meter from power pole if not in use. Two joints of flowline just off location to the north should also be removed. OPERATOR SHOULD COMPLETE RESTORATION AND SUBMIT C103 FORM FOR RELEASE OF LOCATION. LOCATION WILL NOT BE RELEASED UNTIL WORK HAS BEEN COMPLETED AND RE-INSPECTED. 1st notice.

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/19/2013	Routine/Periodic	Mark Whitaker	Yes	No	7/31/2013	iMAW1317125594
Violations						
Surface Damage/Restoration						

Comments on Inspection: Operator has failed to complete restoration within 1 year of plugging date (Rule 19.15.25.10.D). Please note that three power poles that originate on north side of location will need to be removed when final well on lease is abandoned. OPERATOR SHOULD COMPLETE RESTORATION AND SUBMIT C103 FORM FOR RELEASE OF LOCATION. LOCATION WILL NOT BE RELEASED UNTIL WORK HAS BEEN COMPLETED AND RE-INSPECTED. 1st notice.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,


COMPLIANCE OFFICER


Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240

ENERVEST OPERATING L.L.C
1001 FANNIN STREET
SUITE 800
HOUSTON, TX 77002



HASLER
015H14150977
\$0.46
06/20/13
Mailed From 88240
US POSTAGE