Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

| OCD-HOBBS | |
|-----------|--|
| HOBBS | |

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

| | Expires, Jui |
|---|------------------|
| _ | Lease Serial No. |
| | NIMI COCCOCAD |

| SUNDRY | NMLC068281E | NMLC068281B | | | |
|--|--|---|--|----------------------|--|
| Do not use the abandoned we | 6. If Indian, Allottee | 6. If Indian. Allottee or Tribe Name | | | |
| SUBMIT IN TRI | 7. If Unit or CA/Agro | 7. If Unit or CA/Agreement, Name and/or No. | | | |
| 1. Type of Well | | 8. Well Name and No. BUCK 20 FEDERAL 6H | | | |
| Oil Well Gas Well Oth Name of Operator CONOCOPHILLIPS COMPAN | 9. API Well No. 30-025-40902- | 00-X1 | | | |
| 3a. Address | 3b. Pl | none No. (include area code) | 10. Field and Pool, or | | |
| 3300 N "A" ST BLDG 6 MIDLAND, TX 79705 | Ph: 4 | 432-688-6913 | JENNINGS Bone So | upper Shalp | |
| 4. Location of Well (Footage, Sec., T | · / | | 11. County or Parish, | | |
| Sec 20 T26S R32E NWNE 55 | FNL 2659FEL | | LEA COUNTY, | NM / | |
| 12. CHECK APPR | ROPRIATE BOX(ES) TO INDI | CATE NATURE OF N | IOTICE, REPORT, OR OTHE | ER DATA | |
| TYPE OF SUBMISSION TYPE OF ACTION | | | | | |
| Notice of Intent | ☐ Acidize | □ Deepen | ☐ Production (Start/Resume) | ■ Water Shut-Off | |
| ☐ Subsequent Report | _ = | Fracture Treat | ☐ Reclamation | ☐ Well Integrity | |
| ☐ Final Abandonment Notice | _ 。 | □ New Construction□ Plug and Abandon | ☐ Recomplete ☐ Temporarily Abandon | | |
| - Pinai Abandonment Notice | | ☐ Plug Back | ☐ Water Disposal | | |
| following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) A ConocoPhillips Company representative spoke with Chris Walls, BLM on Thursday, 27-June-2013 regarding this remediation. We respectfully propose to remediate the top of cement for the 7? production casing on Buck 20 Federal 6H as follows: 1. Establish Injection down annulus between 7? production casing and 9-5/8? intermediate casing with fresh water. Limit the injection pressure to a maximum of 2500 psi and a maximum of 4 bbl/min. 2. Mix and pump cement down the backside of the 7? casing in a Bullhead Squeeze operation as follows: a. Pump fluid to ensure fluid movement. b. Pump 50 BBL water spacer | | | | | |
| | Electronic Submission #212376 | PS COMPÅNY, sent to th CHRISTOPHER WALLS o | ne Hobbs | | |
| | | | | | |
| Signature (Electronic S | Submission) | Date 07/02/20 |)13 | | |
| | THIS SPACE FOR FE | DERAL OR STATE (| OFFICE USE | | |
| Approved By CHRISTOPHER WA | NLLS | TitlePETROLE | JM ENGINEER | Date 07/02/2013 | |
| Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent to conduct the conduction of the conduct | itable title to those rights in the subject | | | | |
| Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictious or frameulents | U-S.C. Section 1212, make it a crime fo statements or representations at 10 and in | r any person knowingly and natter within its jurisdiction. | willfully to make to any department or | agency of the United | |

Additional data for EC transaction #212376 that would not fit on the form

32. Additional remarks, continued

c. Mix and Pump - 390 sks (10.5 ppg, 2.67 cuft/sk, 186 bbls of slurry) Tuned Lite cement (100% excess in open hole volume)

d. Displace with 3 bbls of water to clear the cement lines

Note: Limit the pump pressure to a maximum of 2500 psi and a maximum rate of 4 bbl/min during the Bullhead Squeeze operation.

- 3. Close the casing valve to isolate the well and to help hold the cement from falling away.RDMO
- 4. Run a Cement Bond Log from 6000? to surface. Repeat the Cement Bond Log under 500 psi pressure if necessary. A copy of this log will be sent via email to Chris Walls, BLM, Carlsbad, NM.
- 5. Confirm that the top of cement(TOC) is above 3980? MD and determine location of the Bottom of Cement from Braiden Head squeeze job and make note of the distance or gap between the Bottom of Cement from the Braiden Head squeeze job and the TOC from the original cement job.
- 6. Report this to the BLM, Carlsbad, NM.