
State of New Mexico Energy, Minerals and Natural Resources Department


FILE IN TRIPLICATE	HOBBS OCOIL CONSERV	ATION DIVISION		Revised 5-27-2004
DISTRICT I	1220 Sout	h St. Francis Dr.	WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240	JUL 2 5 2013 Santa Fe	, NM 87505	30-025-23207	
DISTRICT II 1301 W. Grand Ave, Artesia, NM 88210	JUL DO		5. Indicate Type of Lease STATE X	FEE
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410	RECEIVED			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreen	nent Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			North Hobbs (G/SA) Unit	
DIFFERENT RESERVOIR. USI	E "APPLICATION FOR PERMIT" (Form C	-101) for such proposals.)	Section 33 8. Well No. 114	
Oil Well	Gas Well Other	femporarily Abandoned	0. (10.110. 114	
2. Name of Operator			9. OGRID No. 157984	
Occidental Permian Ltd. 3. Address of Operator	/		10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City,	TX 79323			10003 (0/3A)
4. Well Location				
Unit Letter <u>D</u> : <u>660</u>	Feet From The North	Line and <u>660</u> Fee	t From The West	_ Line
Section 33	Township 18-S	Range 38-E	E NMPM	Lea County
	11. Elevation (Show whether DF, 13652' KB	KB, RT GR, etc.)		
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil	Below-Grade Tank: Volume	bbls; Construction Ma	terial	
12. Cł	neck Appropriate Box to Indicate N	ature of Notice, Report, or (		
	NTENTION TO:		SEQUENT REPORT O	F:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		G CASING
	CHANGE PLANS	COMMENCE DRILLING OPI	NS. DLUG & A	
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN		
OTHER:		OTHER: TA wellbore	/TA status request	X
13 Describe Proposed or Completed	Operations (Clearly state all pertinent		····	starting any
proposed work) SEE RULE 11	03. For Multiple Completions: Attach			
<ol> <li>RUPU &amp; RU.</li> <li>PU wire line &amp; perforate</li> </ol>	tubing @3035' PD wire line			
<ol> <li>RU wire line &amp; perforate tubing @3935'. RD wire line.</li> <li>ND wellhead/NU BOP.</li> </ol>				
4. POOH and lay down ESP equipment.				
5. RIH w/bit. Tag @4020'. 6. RIH w/CIBP set @3926'	. POOH w/bit. '. RU wire line & dump bail 35' of c	ement on ton of CIBP_RD w	ire line	
7. RIH and tag top of ceme			ne me.	
	or 30 minutes and chart for the NMO	CD.		
9. ND BOP/NU TA wellhes 10. RDPU & RU. Clean loc		This Appro	oval of Temporary	5 Zala
		Abandonn	nent Expires	1-1018
	······································		5/14/2013 RDPU 06/20/20	
I hereby certify that the information above constructed or	e is true and complete to the best of my kno	wledge and belief. I further certify	that any pit or below-grade tank h	has been/will be
closed according to NMOCD guideli	nes , a general permit	or an (attached) alternative	e OCD-approved	1
Thomas	, Albert	plan		j
SIGNATURE	+ Upphon	TITLE Administrative		
	Johnson E-mail address:	mendy_johnson@oxy.com	TELEPHONE NO.	806-592-6280
For State Use Only		not "	1NZ	721701-
APPROVED BY	maker	TITLE	DAT	TE 7 <u>31-2013</u>
CONDITIONS OF APPROVAL IF ANY				
				$\sim$

1

JUL 31 2013

Form C-103






## Work Plan Report for Well:NHSAU 114-33

## **Special Objects**

No Data found for Section - SpecialObjects

## Wellbore Diagram



## **Survey Viewer**