HOBBS OCD

Submit 2 Copies To Appropriate District 01 2013 State of New Mexico Office District 01 2013 State of New Mexico	Form C-103
District I Ellergy, Minerals and Natural Resources	WELLAPINO /
District II 1301 W. Grand Ave., Artesia, NM 88240	30-025-39954
1301 W. Grand Ave., Artesia, NM 882109 UNISION District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE 🛛 FEE 🗌
1000 Rio Brazos Rd., Aztec, NM 874 1 0 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	V-8232
87505 SUNDRY NOTICES AND REPORTS ON WELLS (do not use this form for proposals to drill or to deepen or plug back to a different reservoir. use "application for permit" (form C-101) for such	7. Lease Name or Unit Agreement Name
PROPOSALS.)	Paint State 8. Well Number 1
1. Type of Well: Oil Well Gas/Well Other	9. OGRID Number
Mack Energy Corporation	013837
3. Address of Operator	10. Rounners Wildcat
P.O. Box 960 Artesia, NM 88211-0960	Wildeat; Bone Springs
4. Well Location Unit Letter \underline{E} <u>1650</u> feet from the <u>North</u> line and <u>990</u> feet from the <u>North</u> line and <u>990</u> feet from the <u>North</u> line and <u>1650</u> feet from the <u>North</u> line and <u>1650 feet from the prove feet feet from the prove feet feet feet feet feet feet feet fe</u>	the West line
	the lea
I 1. Elevation (Show whether DR, RKB, RT, GR 3889' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Otl	her Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL	
	E DRILLING OPNS 🔲 P AND A 🗌
PULL OR ALTER CASING MULTIPLE COMPL	MENT JOB
	ion is ready for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the	
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have A steel marker at least 4" in diameter and at least 4' above ground level has been 	
	i set in concrete. At shows the
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBE	
<u>UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORM</u> PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	ATION HAS BEEN WELDED OK
The location has been leveled as nearly as possible to original ground contour ano other production equipment.	d has been cleared of all junk, trash, flow lines and
Anchors, dead men, tie downs and risers have been cut off at least two feet below	ground level.
If this is a one-well lease or last remaining well on lease, the battery and pit locat	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, from lease and well location.	production equipment and junk have been removed
All metal bolts and other materials have been removed. Portable bases have been	removed. (Poured onsite concrete bases do not have
to be removed.)	
 All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B 	(4)(h) NMAC All fluids have been removed from
non-retrieved flow lines and pipelines.	
When all work has been completed, return this form to the appropriate District office	
inspection has to be made to a P&A location because it does not meet the criteria above	
SIGNATURE Cherry D. Shern Cler	L DATE 7/31/13
TYPE OR PRINT NAME Jerry W. SherrellE-MAIL: jerrys@mec	.com PHONE: (575)748-1288
For State Use Only M. J. M.	
APPROVED BY: THE OMOL	and UKfler DATE 8/5/7013
Conditions of Approval (if any):	
V	AUG 0 6 2013

/	
	,
	Man
١.	KIMAN