State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 MOEBS OCD 1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO. 30-025-26834
	5. Indicate Type of Lease
DISTRICT II 1301 W. Grand Ave, Artesia, NM 88210 AUG 0 3 2013	STATE FEE X
<u>DISTRICT III</u>	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	
SUNDRY NOTICE'S AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA Unit)
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 33
1. Type of Well: Oil Well Gas Well Other Injector	8. Well No. 232
Name of Operator Occidental Permian Ltd.	9. OGRID No. 157984
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	<u> </u>
N 1373	et From The West Line
Section 33 Township 18-S Range 38-	E NMPM Lea County
3647' KB	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or	Other Data
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME	NT JOB
OTHER: OTHER: Coiled Tub	ng Job X
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed	
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU coiled tubing unit. 2. RIH & clean out to 4396'. Circulate clean. 3. Wash perfs from 4044-4186' w/2500 gal of 15% NEFE acid. Flush w/fresh water. Circulate clean.	completion or recompletion.
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU coiled tubing unit. 2. RIH & clean out to 4396'. Circulate clean. 3. Wash perfs from 4044-4186' w/2500 gal of 15% NEFE acid. Flush w/fresh water. Circul. 4. POOH and RD coiled tubing unit.	completion or recompletion.
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU coiled tubing unit. 2. RIH & clean out to 4396'. Circulate clean. 3. Wash perfs from 4044-4186' w/2500 gal of 15% NEFE acid. Flush w/fresh water. Circulate clean.	completion or recompletion.
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU coiled tubing unit. 2. RIH & clean out to 4396'. Circulate clean. 3. Wash perfs from 4044-4186' w/2500 gal of 15% NEFE acid. Flush w/fresh water. Circul. 4. POOH and RD coiled tubing unit. 5. Return well to injection. RU 07/31/2013	completion or recompletion.
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU coiled tubing unit. 2. RIH & clean out to 4396'. Circulate clean. 3. Wash perfs from 4044-4186' w/2500 gal of 15% NEFE acid. Flush w/fresh water. Circul. 4. POOH and RD coiled tubing unit. 5. Return well to injection.	completion or recompletion.
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU coiled tubing unit. 2. RIH & clean out to 4396'. Circulate clean. 3. Wash perfs from 4044-4186' w/2500 gal of 15% NEFE acid. Flush w/fresh water. Circul. 4. POOH and RD coiled tubing unit. 5. Return well to injection. RU 07/31/2013	completion or recompletion.
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU coiled tubing unit. 2. RIH & clean out to 4396'. Circulate clean. 3. Wash perfs from 4044-4186' w/2500 gal of 15% NEFE acid. Flush w/fresh water. Circul. 4. POOH and RD coiled tubing unit. 5. Return well to injection. RU 07/31/2013 RD 07/31/2013	completion or recompletion.
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU coiled tubing unit. 2. RIH & clean out to 4396'. Circulate clean. 3. Wash perfs from 4044-4186' w/2500 gal of 15% NEFE acid. Flush w/fresh water. Circul. 4. POOH and RD coiled tubing unit. 5. Return well to injection. RU 07/31/2013 RD 07/31/2013 Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify	completion or recompletion.
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU coiled tubing unit. 2. RIH & clean out to 4396'. Circulate clean. 3. Wash perfs from 4044-4186' w/2500 gal of 15% NEFE acid. Flush w/fresh water. Circul. 4. POOH and RD coiled tubing unit. 5. Return well to injection. RU 07/31/2013 RD 07/31/2013 RD 07/31/2013 Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative.	that any pit or below-grade tank has been/will be
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU coiled tubing unit. 2. RIH & clean out to 4396'. Circulate clean. 3. Wash perfs from 4044-4186' w/2500 gal of 15% NEFE acid. Flush w/fresh water. Circul. 4. POOH and RD coiled tubing unit. 5. Return well to injection. RU 07/31/2013 RD 07/31/2013 Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan	that any pit or below-grade tank has been/will be
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU coiled tubing unit. 2. RIH & clean out to 4396'. Circulate clean. 3. Wash perfs from 4044-4186' w/2500 gal of 15% NEFE acid. Flush w/fresh water. Circul. 4. POOH and RD coiled tubing unit. 5. Return well to injection. RU 07/31/2013 RD 07/31/2013 Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan. SIGNATURE Madministrative	that any pit or below-grade tank has been/will be re OCD-approved Associate DATE 08/08/2013
Proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU coiled tubing unit. 2. RIH & clean out to 4396'. Circulate clean. 3. Wash perfs from 4044-4186' w/2500 gal of 15% NEFE acid. Flush w/fresh water. Circul. 4. POOH and RD coiled tubing unit. 5. Return well to injection. RU 07/31/2013 RD 07/31/2013 RD 07/31/2013 Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE TYPE OK PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com	that any pit or below-grade tank has been/will be re OCD-approved Associate DATE 08/08/2013
1. RU coiled tubing unit. 2. RIH & clean out to 4396'. Circulate clean. 3. Wash perfs from 4044-4186' w/2500 gal of 15% NEFE acid. Flush w/fresh water. Circul 4. POOH and RD coiled tubing unit. 5. Return well to injection. RU 07/31/2013 RD 07/31/2013 RD 07/31/2013 Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com	that any pit or below-grade tank has been/will be re OCD-approved Associate DATE 08/08/2013 TELEPHONE NO. 806-592-6280
Proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU coiled tubing unit. 2. RIH & clean out to 4396'. Circulate clean. 3. Wash perfs from 4044-4186' w/2500 gal of 15% NEFE acid. Flush w/fresh water. Circul. 4. POOH and RD coiled tubing unit. 5. Return well to injection. RU 07/31/2013 RD 07/31/2013 RD 07/31/2013 Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE TYPE OK PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com	that any pit or below-grade tank has been/will be re OCD-approved Associate DATE 08/08/2013