Submit 1 Copy To Appropriate District	State of New Mex	xico	Form C-		
District I – (575) 393-6161	Energy, Minerals and Natui	ral Resources	Revised August 1, WELL API NO.	2011	
Office District I – (575) 393-6161 Energy, Minerals and Natural Resources District II – (575) 748-1283 OH. CONSERVATION DIVISION		30-025-40462			
811 S. First St., Artesia, NM 88210		DIVISION	5. Indicate Type of Lease		
1000 Big Barrage Bd. Agree NM 97410			STATE STATE FEE		
<u>District IV</u> – (505) 476-3460 Santa Fe, INIVI 87303		303	6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505 RECE	IVED				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name CENTRAL VACUUM UNIT		
PROPOSALS.) 1. Type of Well: Oil Well ✓ Gas Well □ Other		8. Well Number 251			
2. Name of Operator		9. OGRID Number 4323			
CHEVRON U.S.A. INC.			<u> </u>		
3. Address of Operator 15 SMITH ROAD, MIDLAND, TEXAS 79705		10. Pool name or Wildcat VACUUM GRAYBURG SAN ANDRES			
4. Well Location					
Unit Letter A: 704 feet from	the NORTH line and 311 fee	t from the EAST li	ne		
	Township 17-S Range		MPM County LEA		
11. Elevation (Show whether DR, RKB, RT, GR, etc.		RKB, RT, GR, etc.)		in '	
NOTICE OF INTE PERFORM REMEDIAL WORK ☐ PI TEMPORARILY ABANDON ☐ CI	ropriate Box to Indicate Na NTION TO: LUG AND ABANDON HANGE PLANS ULTIPLE COMPL		SEQUENT REPORT OF: <		
OTHER:			LETION FOR NEW WELL		
 Describe proposed or completed of starting any proposed work). proposed completion or recomp PLEASE FIND ATTACHED, REPO COMPLETION OF THIS NEW 	SEE RULE 19.15.7.14 NMAC pletion. ORTS FOR WORK DONE FRO	. For Multiple Cor	I give pertinent dates, including estimate npletions: Attach wellbore diagram of ROUGH 02/22/2013 FOR THE	d date	
04/06/2013: ON 24 HR OPT. PUM	ADING 45 OH ROGAS & 143	WATER COR	1777		
04/00/2013. ON 24 HR OFT. FOW	iring 43 Oil, 80 GAS, & 143	WATER. GOR-	1 / / /		
Spud Date:	Rig Release Da				
I hereby certify that the information above	ve is true and complete to the be	est of my knowledge	e and belief.		
SIGNATURE ALUSE THE	TITLE: REGU	JLATORY SPECIA			
Type or print name: DENISE PINKERT	Type or print name: DENISE PINKERTON E-mail address: leakejd@chevron.com PHONE: 432-687-7375				
APPROVED BY: Conditions of Approval (if any):	TITLE P	etroleum Engine	per DATE AUG 16	<u>201</u> 3	



Summary Report

Completion Complete

Job Start Date: 2/5/2013 Job End Date: 2/22/2013

Well Name
CENTRAL VACUUM UNIT 251
Central Vacuum Unit
Count Elevation (ft)
3,993.00
Current RKB Elevation
A,011.50, 1/8/2013
Clarent RKB Elevation
A,011.50, 1/8/2013

Elevation Field Name
Vacuum
Vacuum
Mid-Continent/Alaska

Mud Line Elevation (ft)
Water Depth (ft)

Report Start Date: 2/5/2013

crew travel

road rig from cvu 26 to cvu 251

review isa's.

ru workover unit 336, move in pipe racks, reverse unit, tanks, hydrowalk

take out back pressure valve and install bop, load and test blind rams to 500 psi, held

move in and rig up Baker Atlas and SD and gih and run gyro from surface to TD 5020' wireline measument, rd wireline

nipple down bop and nu 5000 psi frac valve

mi ru Nabors kill truck and load and test casing to 4000 psi for 30 minutes, secure well

crew travel

Report Start Date: 2/6/2013

Com

orovy troyed

review jsa's on wireline safety

mi ru Baker Atlas E-line, conduct safety meeting, goih with logging tools, run GR-RAL-CCL from 5020 to surface, make pass with 1000 psi on casing from 5020 to surface

wait on guns to arrive on location, lots of miscommunication within Baker Atlas., secure well,

crew travel

Report Start Date: 2/7/2013

Com :

crew travel

review jsa's on working around wireline, prejob safety mtg

wait on Baker Atlas to get top sub out of Odessa, didn't bring sub with guns

ru Baker Atlas to start perfing, Tried to load and test lubercator and it wouldn't test, had to lay down lubercator and replace o-rings. Picked up lubercator and retested, held 1000 psi, perf zones 4757-64, 4772-77, 4782-90, 4795-98, 4850-60, 4878-95, 4897-4910, 4912-20, 4922-42, 4944-48, 4951-71, 4971-79, in 6 runs, with 3 3/8 predator guns w/2 jspf@120 degree phasing, 35 gram charges, see perf report, rd wireline at last, secure well, prepare to acidize

crew travel

Report Start Date: 2/8/2013

The state of the s

crew travel

review jsa's, prejob safety mgt,

mi ru Petro-plex and pro wireline, put acid in tanks and mix chemical, install blow back lines to frac tank

acid job as follows: load and test lines to 4800 psi, start on water and break down perfs @ 2766 psi @ 3.1 bpm, start on acid and increase rate to 10.4 bpm, pump 24 bbls acid and drop 10 balls very 7.7 bbls acid total drop of balls 37 drops, no ball action during acid job, pump acid and balls at 10.4 bpm at 3100 psi, flush with 115 bbls water, average rate 10.4 bpm, average pressure 3100 psi, total load 426 bbls, isip 2666 psi, 5 min 2373, 10 min 2171, 15 min 1980, shut in well, rd acid crew

leave well closed in for 1 hour, for acid to spend

open well at 1200 psi on wellhead, open to frac tank on 1/4 choke, well flowed back 35 bbls water and acid gas, close well in, secure well

crew changed out drilling line on workover rig

crew travel

Report Start Date: 2/11/2013

crew travel

review jsa's, check tubing elevators for correct size

nu bop, tried to gih with rbp, wouldn't go passed 5 1/2 head, picked up 4 3/4 bit wouldn't go either gih with 4.50 retrieving head, it would go.

pump 120 bbls 10# brine down well to pump RCN balls to bottom, Pumped 3.5 bpm @ 1200 psi. secure well, prepare to run injection logs in the morning

stand down OSHA, over wire rope, hazard hunt,

crew travel

Report Start Date: 2/12/2013

Com

crew travel

safety mtg, review jsa's on working around E-line

mi ru Schlumberger E-line, prejob safety mtg,

load and test lubercator to 1000 psi,gih with 4.20 guage ring and junk basket to 5012, found tight spot at 4936, pooh with gauge ring and junk basket gih with injection profile tools with spinners and log injection thru perfs, pooh with logging tools and lay down tools and lubercator, secure well

crew travel

Report Start Date: 2/13/2013

crew travel

COIII,

Page 1/3 Report Printed: 5/17/2013



Summary Report

Completion Complete

Job Start Date: 2/5/2013 Job End Date: 2/22/2013

Field Name Business Uni **CENTRAL VACUUM UNIT 251** Central Vacuum Unit Vacuum Mid-Continent/Alaska Current RKB Elevation Mud Line Elevation (ft) Water Depth (ft) Ground Elevation (ft) 3,993.00 4,011.50 4,011.50, 1/8/2013

review jsa's, check tubing elevators for correct size

mi ru Schlumberger E-line, pre job safety mtg, gih with 5 1/2 composite plug, checked OD on all tools run in hole. Composite plug checked out at 4.44 OD, set first composite @ 4500' load and test plug to 1000 psi, pooh with setting tool, gih with 5 1/2 composite @ 500' pooh with wireline and rd wireline company

rig up tubing running equipment and gih with jts tubing and tag composite @ 500' gih with 16 jts and circ hole clean, well bore had some oil in well, circ hole

pooh with tubing

nd bop and frac valve

nd 5 1/2 tubing head to expose 5 1/2 cut casing at top of well, calibered casing at 4.67 id, looks like 23 lb casing, not matching 17# in well

nu wellhead and install bop, close blind rams and test wellhead and bop to 500 psi, held secure well

crew travel

Report Start Date: 2/14/2013

crew travel

review jsa's, check tubing elevators for correct size

gih with 5 stands tubing and lay down tubing

wait on new drilling line to change workover rig to 6 lines, change out drilling line, secure well

crew travel

Report Start Date: 2/15/2013

Com

review safety share on how to adjust rig brakes, check tubing elevators for correct size for power swevel

wait on mill from Odessa, shut down due to mill arriving late to welder, secure well

Report Start Date: 2/18/2013

Com

crew travel

review jsa's, check tubing elevators for correct size

wait on mill to arrive on location

pick up 3 1/2 drill collar with smith mill 4.62 od tapered to 4.892 od, and one 3 1/2 drill collar, pick up power swevel and install stripper rubber and start milling on 23 LB casing sub at 9 inches below surface with 90 rpm at 1 bpm circ rate

milled thru top joint, worked mill thru milled spot, found no restriction in pipe,

remove stripper head and pooh with mill and collars, installed 4 3/4 mill tooth bit and run thru milled casing, layed down mill,

gih with 4 3/4 mill tooth bit, 6 drill collars and 10 jts and tag sand @508, load and test casing to 700 psi held, release pressure, install stripper rubber and power swevel and start washing sand and drilling composite

wash sand off of composite and drill composite at 517' drill thru,

circ hole clean,

lay down power swevel and take off stripper head, prepare to run pipe in morning, secure well

crew travel

Report Start Date: 2/19/2013

Com

travel time

hsm, discuss tenet #9, discuss hazard id wheel #9, discuss e-colors #9, review jsa's and sop's caliper tbg, elevators and document on daily sheet in doghouse

compolete pu tbg. and rih to 4510' tag pu swivel and break circ

drill on cbp for 1 1/2 hrs. fell thru chased to bottom set down 5030

circ clean

ld swivel pull bha above top perf sdon

travel time

Report Start Date: 2/20/2013

Com travel time

hsm, discuss tenet #10, discuss hazard id wheel #10; discuss e-colors #10, review jsa's and sop's caliper tbg. elevators and document on daily sheet in dog

pooh w/ tbg. l.d. dc. and bit

pu 5.5. cibp rih and set at 5029

pooh and l.d. w.s

pu prod tbg. rih to 4600'

Page 2/3

Report Printed: 5/17/2013



Summary Report

Completion Complete Job Start Date: 2/5/2013 Job End Date: 2/22/2013

			OOD Ella	Date. Lillilo
Well Name	Lease	Field Name	Business Unit	
CENTRAL VACUUM UNIT 251	Central Vacuum Unit	Vacuum	Mid-Continent/Alaska	
Ground Elevation (ft) Original RKB (ft)	Current RKB Elevation		Mud Line Elevation (ft)	Water Depth (ft)
3,993.00 4,011.50	4,011.50, 1/8/2013			

Section of the sectio
pooh w/ 300' of prod in derrick left 700' in well sdon
travel time
Report Start Date: 2/21/2013
Com results of the second of t
travel time
hsm, discuss tenet #1, discuss hazard id wheel, discuss e-colors, review jsa's and sop's caliper tbg. elevators and document on daily sheet in doghouse
centri-lift did not want to run esp because high winds sd
travel time
Report Start Date: 2/22/2013
Compared to the control of the contr
TRAVEL TIME
HSM, DISCUSS TENET #2, DISCUSS HAZARD ID WHEEL #2, DISCUSS E-COLORS #2, REVIEW JSA'S AND SOP'S CALIPER TBG. ELEVATORS AND DOCUMENT ON DAILY SHEET IN DOGHOUSE
POOH W/ 700' OF TBG
PU ESPEQUIPMENT
RIH W/ NEW TBG. AND ESP TO 4751.7' LAND IN QCI HEAD
ND BOP NU WELL VALVE
RIG DOWN MOVE TO NEXT WELL