Form 3160-5 (March 2012) DEP BUR		HOBBS	FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014 520case Serial No.					
SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an RECEIVED								
	Use Form 3100-3 (A	PD) for suc	n proposais.		7. If Unit of CA/Ag	reement, Name	and/or No.	
SUBMIT IN TRIPLICATE – Other instructions on page 2. I. Type of Well								
Oil Well Gas Well Other					8. Well Name and No. SHINNERY 1 FEDERAL 1			
2. Name of Operator Devon Energy Production Company, L.P.					9. API Well No. 30-025-30627			
3a. Address 333 W. Sheridan Avenue	3b. Phone No. <i>(include area code)</i> 405-235-3611			10. Field and Pool or Exploratory Area QUEEN; DELAWARE				
Oklahoma City, Oklahoma 73102-0510 4. Location of Well <i>(Footage, Sec., T.,</i>				11. County or Parish. State				
1750 FSL & 990 FEL, UNIT I, SEC 1 T18S R32		LEA COUNTY, NM						
. 12. CHEC	K THE APPROPRIATE BC	X(ES) TO INDI	CATE NATURE	OF NOTIC	CE, REPORT OR OT	HER DATA		
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF AC					ГІОN		
Notice of Intent	Acidize	Deepe		=	uction (Start/Resume)	=	er Shut-Off	
	Alter Casing		re Treat Construction		amation mplete		l Integrity _{er} Queen	
Subsequent Report	Change Plans	_	nd Abandon		porarily Abandon			
Final Abandonment Notice	Convert to Injection	🗌 Plug E	Back	Wate	er Disposal			
following completion of the involvent testing has been completed. Final determined that the site is ready for 7/5/13 – 7/16/13 - MIRU WOR & re- w/gauge ring to 6800' & POOH. <u>RI</u> good. RIH to 6,330'; displ w/150bb 4,061' to 4,090', 34 holes. RD WL, job. Pump 2,500 gal 15% acid, RD off, ND BOP, NU cap flange, Pkr in	Abandonment Notices must r final inspection.) v. unit. POOH & LD rods; <u>H.w/CIBP and set @ 6,700</u> Is FW & spot cmt plug w/1 RU testers, PU PKR, test acid crew, bled well off to compression, PT @ 500 p	ne filed only after ND WH, unset D' <u>; POOH. Dum</u> 2 sx CI H cmt, I tbg in hole @ 5 flowback tank. si on csg, held	TAC, NU BOP 8 p bailer 4 sx cm POOH. RU WL, i,800 psi, set Pkr Release Pkr & I good. Prep to s	POOH w RD WL. RD WL. ran Gamr @ 4,149 OOH w/3 wab well.	reclamation, have be // 2 7/8" tbg, seat n Load hole w/15 b ma Ray to correlate ', test csg @ 3,000 3 stands, set Pkr @ Swabbed, no oil s	ipple & mud j bls WTR, tes e, tag TOC @ psi, move Pk) 3,961; PT to sign, decision	and the operator has Int. RU WL, RIH t csg to 500psi/30 min. – 0 6,150'. Perf from r up to 3,961', start acid o 500psi – good. Bled to frac.	
7/17/13 - 7/19/13 - RU to frac, PT li 46,690# 20/40 WS; flushed w/1,032 7/20/13 - 7/21/13 - Flowback well, r	ecovered 61 bbls of water?) frac crew and	prepare to flow	back.				
@ 6,031'. POOH and layed down F 7/22/13 – 7/23/13 - RIH w/ bull plug Set rod pump @ 4,188'; EOT @ 4,2	, mud joint, tbg/sandscree	n, SN, blast joi ng stroke, picke	nt, tbg, anchor/c d up pumping he	atcher & t ead & har	tbg. Set TAC @ 3, ng it on. RDPU & T	829'. NU Wł 'OP.	H; TIH w/rods & pump.	
14. I hereby certify that the foregoing is	rue and correct. Name (Printe	d/Typed)		u u				
DAVID H. COOK								
Signature	2		Date 08/19/201	13	Aliu	EPTED	FOR RECORD	
	THIS SPACE	FOR FEDE	RAL OR STA	TE OF	FICE USE			
Approved by Conditions of approval, if any, are attache that the applicant holds legal or equitable entitle the applicant to conduct operations	title to those rights in the subje				SUR	AUG Date	ND MANAGEMENT	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false fictitious or fraudulent statements or representations as to any matter within its jurisdiction.								
(Instructions on page 2) PA	Young Bor			4h		,AU(3 2.8 2013	