## OCD Hobbs

**UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

HOBBS OCD

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

Expires, J	u I
. Lease Serial No. NMNM104050	

	SUNDRY	NOTICES	AND REPOR	RTS ON WELLS	
_				.1 111	

Do not use this form for proposals to drill or to re-enter an CED

abandoned wel	I. Use form 3160-3 (APD)	) for such p	roposals.3EP	V 3 2013	o. If Indian, Anottee o.	1 Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well			888	CIVED	8. Well Name and No.		
Oil Well Gas Well Oth	er				WEST CORBIN FED 1		
Name of Operator EOG RESOURCES INCORPO		STAN WAGN r@eogresourd			9. API Well No. 30-025-24744-00-S1		
3a. Address	(include area code) 6-3689		10. Field and Pool, or Exploratory CORBIN				
MIDLAND, TX 79702	D. M. C. D. D. M. C.				11. County or Parish,	and Ctata	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)							
Sec 18 T18S R33E SENE 1980FNL 660FEL					LEA COUNTY, NM		
12. CHECK APPR	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF 1	NOTICE, RI	EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION			ТҮРЕ ОІ	FACTION			
☐ Notice of Intent	☐ Acidize	☐ Deep	oen	□ Product	ion (Start/Resume)	■ Water Shut-Off	
_	☐ Alter Casing	☐ Frac	ture Treat	□ Reclam	ation	■ Well Integrity	
Subsequent Report	□ Casing Repair	□ New	Construction	□ Recomp	olete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	🛛 Plug	-		arily Abandon		
	☐ Convert to Injection	Plug			Disposal		
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  7/28/13 MIRU to P&A. POOH w/ pump and rods. 7/29/13 Release TAC at 6937'. 7/31/13 RIH and jet cut 2-3/8" tubing at 11164'. POOH w/ tubing to 7339'. Rig up wireline. RIH and locate top of TAC at 11207'. Attempt to cut. Did not cut. Attempt to pull. Sheared off jet cutter and tubing at 11164'. Fish left in hole: mud anchor, seating nipple, TAC, tubing. Total fish 144'. Top of fish at 11164'. Slowly POOH w/ 2-3/8" tubing from 11164' to 7754'. 8/01/13 Finish POOH and laydown. 8/02/13 Consulted w/ Jim Amos - BLM Carlsbad. Decision made to spot cement plugs from top of Wolfcamp to 6000'. 8/13/13 Spot 150 sx Class H cement plug at 11160'. 8/05/13 RIH and tag cement plug at 10087'. BLM on location to witness.							
	Electronic Submission #2 For EOG RESOUF nitted to AFMSS for process	RCES INCOR	PORATED, sent INY DICKERSON	to the Hobbs on 08/16/201	i 3 (13JLD0344S)		
Name (Printed/Typed) STAN WA	GNER		Title REGUL	ATORY AN	ALYST		
Signature (Electronic S	Submission)		Date 08/16/2	013			
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE		
Approved By ACCEPTED			(BLM Approver Not Specified) Title			Date 08/26/2013	
Conditions of approval, if any, are attache ertify that the applicant holds legal or equalish would entitle the applicant to condu	litable title to those rights in the		Office Hobbs				
itle 18 U.S.C. Section 1001 and Title 43 States any false, fictitions or fraudicient s	U.89. Section 1212, make it acstatements by representations as	ne for any pe	rson knowingly and thin its jurisdiction.	willfully to m	ake to any department or	agency of the United	

\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*

## Additional data for EC transaction #217289 that would not fit on the form

## 32. Additional remarks, continued

Well P&A.

Spot 150 sx Class H cement plug at 10084'. WOC. 8/06/13 RIH and tag cement plug at 8726'.
Pump 150 sx Class H cement plug at 8723'. BLM on location to witness. WOC. 8/07/13 RIH and tag cement plug at 7403'. BLM on location to witness. Spot 150 sx Class H cement plug at 7399'. WOC. 8/08/13 RIH and tag cement plug at 6042'. BLM on location to witness. Spot 50 bbls 10 ppg mud. Prep to pull 5-1/2" parted casing.

Determine free point of casing.

8/09/13 POOH and recover 5115' of 5-1/2" casing. Consult with BLM.

Instructed to spot cement plug at 5165'. Instructed to spot cement plug at 5165'.
8/10/13 RIH to top of casing stub at 5115'.
Pump 325 sx Class H cement plug at 5043'. WOC.
8/12/13 RIH and tag cement plug at 4188'. BLM on location to witness.
Spot 83 bbls 10 ppg mud.
Pump 70 sx Class C cement plug at 2880'. WOC.
8/13/13 RIH and tag cement plug at 2606'. Notified BLM, given permission to proceed. Spot 95 bbls 10 ppg mud.
Pump 70 sx Class C cement plug at 1673'. WOC. Pump 70 sx Class C cement plug at 1673'. WOC. Pump 70 sx Class C cement plug at 1673; WOC.

8/14/13 RIH and tag cement plug at 1389'. BLM on location to witness.

Spot 100 bbls 10 ppg mud.

Pump 330 sx Class C cement plug at 602'. WOC.

8/15/13 DIG out cellar. Cut 13-3/8" casing and 8-5/8" casing. Fill 8-5/8" casing and 8-5/8" casing X 13-3/8" annulus with 8 sx cement. Cement top off

witnessed by BLM. WOC. Weld on P&A marker, clean and restore location.