

Submit 1 Copy To Appropriate District  
Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD  
SEP 05 2013  
RECEIVED

WELL API NO. 30-025-05498
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit Section 25
8. Well Number 231
9. OGRID Number: 157984
10. Pool name or Wildcat Hobbs (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other Injector

2. Name of Operator  
Occidental Permian Ltd.

3. Address of Operator  
2611 State Hwy 214 Denver City, TX 79323

4. Well Location

Unit Letter K : 2310 feet from the South line and 2310 feet from the West line

Section 25 Township 18S Range 37E NMPM County

5. Elevation (Show whether DR, KKB, KI, GR, etc.)  
3666' DF

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐ Convert to Production

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) POOH with tbg and pkr.
- 2) Clean out to 4350
- 3) Perforate from 4253-61', 4266-72', 4282-4304'
- 4) Acid treat with 2400 gallons
- 5) RIH with ESP equipment
- 6) Turn well to production

During this procedure we plan to use  
the closed-loop system with a steel  
tank and haul contents to the required  
disposal per ODC Rule 19.15.17

Spud Date:

Rig Release Date:

This work considered to be recompletion.  
After work is done the forms required are:  
C-103 Subsequent report  
C-105 Completion report  
C-102 Dedicated Acreage for pool producing from  
C-104 Request for Allowable & Authorization to Transport

I hereby certify that the information above is true and complete to the best of my

SIGNATURE Steve Sneed TITLE Lift Specialist DATE 9/3/2013

Type or print name Steve Sneed E-mail address steve\_sneed@oxy.com PHONE: 806-592-6312

For State Use Only

APPROVED BY: [Signature] TITLE Petroleum Engineer DATE SEP 09 2013

Conditions of Approval (if any):