``.		DEPARTMENT OF THE INTERIOR			FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007		
	BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS HOBBS (5. Lease Serial No. CD NMNM-111242			
	Do not use this form for proposals to drill or to recenter an 6. If Indian Allottee or Tribe Name						
	abandoned well. Use Form 3160-3 (APD) for such proposals 0 3 2013						
	SUBMIT IN TRIPLICATE- Other instructions on reverse side.					CA/Agreement, Name	and/or No.
	1. Type of Well Gas Well Other				8. Well Nar	ne and No. d 6 Federal #1	(305050)
	2. Name of Operator NADEL AN	2. Name of Operator NADEL AND GUSSMAN HEYCO, LLC				ll No.	· · · ·
	3a. Address PO BOX 1936 ~ ROSWELL	3b. Phone No. (include 575/623/6601	Phone No. (include area code)		30-025-35680 10. Field and Pool, or Exploratory Area		
	4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit F, 1830' FNL \$950' FWL Sec 6: T18S, R32E				Young Morrow NW 11. County or Parish, State Lea, New Mexico		
	12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE,						
	TYPE OF SUBMISSION TYPE OF ACTION						
		Acidize	Deepen	Production (Sta	Well Integrity		
	Notice of Intent		Fracture Treat	Reclamation			
	Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon	Recomplete			
	Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal			
	If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)						
	BLM Bond No. NMB00520 Surety Bond NO. B004230						
Ser (6A	 Release and retrieve the Tubing Conveyed Perforation bottom hole assembly. RIH & set CIBP at ±12,660° - Performation bottom hole assembly. RIH & set CIBP at ±12,660° - Performation bottom hole assembly. RIH & set CIBP at ±12,660° - Performation bottom hole assembly. RIH & set CIBP at ±8,720°. Dump bail 35° of Class H cement on top of CIBP. Pressure test plug and casing to 2,500 psi. Perforate C Bench of 2nd Bone Spring interval from 8,558° to 8,628° at 2 SPF (36 total holes). Spot and break down perforations with 15% HCl acid. Swab test for oil cut and inflow. Stimulate interval with hydraulic fracture stimulation if swab tests indicate a productive interval. Place well on pumping production. 						
	14. I hereby certify that the fore	going is true and correct					
	Name (<i>Printed/Typed</i>) Tamm y R. Link	Title Pr	roduction Tech				
	Signature	y P. Lik	Date	0	8/14/201B	ROVED	1
	THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
	Approved by Conditions of approval, if any, are a certify that the applicant holds legal which would entitle the applicant to	loes not warrant or	itle ffice	Ilenn	LAND MANAGEME	NT N	
	Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.						of the United C
	(Instructions on page 2)						
				M		UBJECT TO PPROVAL E ZUI3	LIKE SY STATE
				ر St	=P 0 9	20 I 3	

.

`

Conditions of Approval

Nadel and Gussman Heyco, LLC. Pearsall 6 Federal 1 API: 30-025-35680 T18S-R32E, Sec 06 August 29, 2013

Notify BLM at 575-393-3612 a minimum of 24 hours prior to commencing work.

Work to be completed by November 29, 2013.

- 1. Operator shall place a CIBP at 12,570' and place a minimum of 25 sx of Class H cement on top. Tag required.
- 2. Operator shall place a balanced Class H cement plug from 12,105'-11,885' to isolate the top of the Morrow formation.
- 3. Operator shall place a balanced Class H cement plug from 9,281'-9,089' to isolate the top of the Wolfcamp formation.
- 4. CIBP can be set at 8,720' with 35' cement bailed on top.
- 5. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails.
- 6. Surface disturbance beyond the existing pad must have prior approval.
- 7. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 8. Functional H_2S monitoring equipment shall be on location.

- **9.** A minimum of 3000 (3M) BOPE shall be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M) Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 10. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- **11.** Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 12. See attached for general requirements.
- 13. Submit subsequent sundry required detailing work done and completion report for the new formation. Operator to include well bore schematic of current well condition when work is complete.

JAM 082913

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

General Requirements for Plug Backs

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

1. j. j. 1

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. **Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class** "C", for up to 7,500 feet of depth or **Neat Class** "H", for deeper than 7,500 feet plugs.

6. <u>Subsequent Plug back Reporting</u>: Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed</u>.

7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.