Form 3160-5 (March 2012)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD Hobbs

FORM APPROVED OMB No. 1004-0137

Expires: October 31, 2014 5. Lease Serial No. NM84651, NM84652, NMNM129733

HOBBS OCD 6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter any abandoned well. Use Form 3160-3 (APD) for such proposals.

13				
	7. If Unit of CA/Agreement, Name and/or No.			
	/			
	8. Well Name and No. HAMON FED COM A #3H			
	9. API Well No. 30-025-41305			
	10. Field and Pool or Exploratory Area			
	TEAS EAST; BONE SPRINGS			
	11. County or Parish, State			

SUBMIT IN TRIPLICATE - Other instructions on page CEIVED			7. If Unit of CA/Agreement, Name and/or No.			
1. Type of Well						
☑ Oil Well ☐ Gas W	/ell			8. Well Name and No. HAMON FED CO		
2. Name of Operator LEGACY RESE	RVES OPERATING LP	/		9. API Well No. 30-025-41305		
3a. Address PO BOX 10848 MIDLAND, TX 79702		3b. Phone No. (include area co 432-689-5200	ode)	10. Field and Pool or E TEAS EAST; BO	•	
<ol> <li>Location of Well (Footage, Sec., T., SHL: 474' FSL &amp; 2004' FEL</li> <li>BHL: 330' FSL &amp; 1880' FEL, SEC. 6, T20S,</li> </ol>	R.,M., or Survey Description) R34E			11. County or Parish, S LEA CO., NM	State	
12. CHEC	CK THE APPROPRIATE BO	X(ES) TO INDICATE NATUR	E OF NOTIC	E, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION		TY	PE OF ACT	ION		
✓ Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	=	uction (Start/Resume) Water Shut-Off amation Well Integrity		
Subsequent Report	☐ Casing Repair  ✓ Change Plans	New Construction Plug and Abandon	_	mplete oorarily Abandon	Other	
Final Abandonment Notice	Convert to Injection	Plug Back	☐ Wate	r Disposal		
13. Describe Proposed or Completed O the proposal is to deepen direction. Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready for	ally or recomplete horizontally vork will be performed or pro ed operations. If the operation Abandonment Notices must be	y, give subsurface locations and vide the Bond No. on file with E on results in a multiple completion	measured an BLM/BIA. R on or recomp	d true vertical depths o lequired subsequent rep letion in a new interval,	f all pertinent markers and zones. orts must be filed within 30 days , a Form 3160-4 must be filed once	
LEGACY RESERVES IS REQUEDVIOL AND PACKER DUE THE PROPOSED DEPTH OF TWO STAGES.	TO LOST CIRCULATION.	THE LOST CIRCULATION S	STARTED W	VITH PARTIAL LOSS	ES AT 4084' MD.	

THE FIRST STAGE WILL BE RUN FROM CASING TD 5515'-3993' MD. IT WILL CONSIST OF 715CU-FT OF 12.5PPG LEAD (340SX) YIELD 2.13 CF/SX 35:65 POZ: CLASS "C" + ADDITIVES, FOLLOWED BY 265CU-FT OF 14. 8PPG TAIL (200SX) YIELD 1.33 CF/SX CLASS "C", CALCULATED ON 100% EXCESS IN 12.25" HOLE, THE PLUG WILL BE DISPLACED BY 414BBLS OF WATER WHERE WE WILL BUMP THE PLUG AND TEST THE FLOAT. THE PACKER WILL THEN BE INFLATED AND THE BOMB DROPPED AND THE ANNULUS ABOVE THE PACKER WILL BE OPENED AND CIRCULATED FOR 1.5X CASING CAPACITY.

THE SECOND STAGE OF CEMENT WILL BE DONE FROM 3963' MD-SURFACE. IT WILL CONSIST OF 1828CU-FT OF 12.5PPG LEAD (860SX) YIELD 2.13 CF/SX 35:65 POZ: CLASS "C" + ADDITIVES, FOLLOWED BY 265CU-FT 14.8PPG TAIL (200SX) YIELD 1.33 CF/SX CLASS "C", CALCULATED ON 100% EXCESS IN 12.25" HOLE, FOLLOWED BY THE PLUG AND 300.5BBLS OF WATER TO DISPLACE THE CASING. PLUG WILL BE BUMPED AND THE FLOAT WILL BE TESTED.

SEE ATTACHED FOR	ORPAR.	APPRO					
14. I hereby certify that the foregoing is true and coconditions of AFFR	O A STEE	7013					
BLAIN LEWIS Title	SENIOR ENGINEER I	SEP					
Signature Sein Hours Date	. 09/03/2013	BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE CARLSBAD							
Approved by							
	Title	Date					
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office						
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1217 Make it a crime for any person lifetitious or fraudulent statements or representations as to any matter within its austicition.	knowingly and willfully to make to any departn	nent or agency of the United States any false,					

## CONDITIONS OF APPROVAL

Date: 09/02/2013

OPERATOR'S NAME:
WELL NAME & NO.:
SURFACE HOLE FOOTAGE:
BOTTOM HOLE FOOTAGE
LOCATION:
COUNTY:
Legacy Reserves Operating LP
3H Hamon Fed Com A 30-025-41305
474' FSL & 2004' FEL
330' FSL & 1880' FEL, Sec. 7
Section 6, T.20 S., R.34 E., NMPM
Lea County, New Mexico

## Original COA still applies with the following changes: R-111- Potash and Capitan Reef

1. The minimum required fill of cement behind the 9-5/8 inch intermediate casing is:

Operator has proposed DV tool at depth of approximately 3963'-3993'. Operator is to submit sundry if DV tool depth varies by more than 100' from approved depth.

- a. First stage to DV tool:
  - Ement to circulate. If cement does not circulate, contact the appropriate BLM office before proceeding with second stage cement job. Operator should have plans as to how they will achieve circulation or approved top of cement on the next stage.
- b. Second stage above DV tool:
  - Cement to surface. If cement does not circulate, contact the appropriate BLM office. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry due to Potash.

Formation below the 9-5/8" shoe to be tested according to Onshore Order 2.III.B.1.i. Test to be done as a mud equivalency test using the mud weight necessary for the pore pressure of the formation below the shoe (not the mud weight required to prevent dissolving the salt formation) and the mud weight for the bottom of the hole. Report results to BLM office.

- 2. Whenever a casing string is cemented in the R-111-P potash area, the NMOCD requirements shall be followed.
- 3. After the cement job has been pump a copy of the service company cement report shall be provide to the BLM.
- 4. Operator shall be required to run a CBL from TD to surface. The CBL shall be run at ZERO psi and again at 1,000 psi. Both runs are to be from TD to surface. The 1000 psi run will have to be done before drilling out the shoe.