
BU SUNDRY N Do not use this abandoned well. SUBMIT IN TRIP 1. Type of Well Coll Well Gas Well of the 2. Name of Operator OXY USA INC. 3a. Address P.O. BOX 50250 MIDLAND, TX 79710 4. Location of Well (Footage, Sec., T., Sec 21 T25S R32E SWSW 660 32.110470 N Lat, 103.686530 N	Contact: [E-Mail: david_stewa R., M., or Survey Description] DFSL 660FWL	EMENT TS ON WELLS frill or to re-enter an) for such proposals. ions on reverse side. OAVID STEWART Int@oxy.com 3b. Phone No. (include area Ph: 432-685-5717 Fx: 432-685-5717 Fx: 432-685-5717 INDICATE NATURE TYF Deepen Fracture Treat	OF NOTICE PE OF ACTION	OMB N Expires 5. Lease Serial No. NMLC061869 6. If Indian, Allottee 7. If Unit or CA/Agree 8. Well Name and No COTTON DRAW 9. API Well No. 30-025-08211 10. Field and Pool, or PADUCA DELA 11. County or Parish, LEA COUNTY, , REPORT, OR OTHE	Exploratory WARE and State		
SUNDRY N Do not use this abandoned well. SUBMIT IN TRIP 1. Type of Well Oil Well Gas Well Othe 2. Name of Operator OXY USA INC. 3a. Address P.O. BOX 50250 MIDLAND, TX 79710 4. Location of Well (Footage, Sec., T., Sec 21 T25S R32E SWSW 660 32.110470 N Lat, 103.686530 N I2. CHECK APPR TYPE OF SUBMISSION I2. Notice of Intent Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Oper	Acidize Acidize Acidize Casing Repair Acidize Contact: Contact: Contac	ATS ON WELLS drill or to re-enter an) for such proposals. ions on reverse side. DAVID STEWART ut@oxy.com 3b. Phone No. (include area Ph: 432-685-5717 Fx: 432-685-5717 Fx: 432-685-5717 INDICATE NATURE TYF Deepen Fracture Treat	OF NOTICE PE OF ACTION	NMLC061869 6. If Indian, Allottee 7. If Unit or CA/Agree 8. Well Name and No COTTON DRAW 9. API Well No. 30-025-08211 10. Field and Pool, or PADUCA DELA 11. County or Parish, LEA COUNTY, , REPORT, OR OTHE	Exploratory WARE and State		
Do not use this abandoned well. SUBMIT IN TRIP SUBMIT IN TRIP Oil Well Gas Well Othe Name of Operator OXY USA INC. Sa. Address P.O. BOX 50250 MIDLAND, TX 79710 Location of Well (Footage, Sec., T., Sec 21 T25S R32E SWSW 660 32.110470 N Lat, 103.686530 N I2. CHECK APPRO TYPE OF SUBMISSION Notice of Intent Subsequent Report Final Abandonment Notice I3. Describe Proposed or Completed Oper	s form for proposals to 6 Use form 3160-3 (APD PLICATE - Other instruct E-Mail: david_stewa R., M., or Survey Description) DFSL 660FWL W Lon OPRIATE BOX(ES) TO	drill or to re-enter an b) for such proposals. bions on reverse side. DAVID STEWART Int@oxy.com 3b. Phone No. (include area Ph: 432-685-5717 Fx: 432-685-5717 INDICATE NATURE TYF Deepen Fracture Treat	OF NOTICE PE OF ACTION	 7. If Unit or CA/Agree 8. Well Name and No COTTON DRAW 9. API Well No. 30-025-08211 10. Field and Pool, or PADUCA DELA 11. County or Parish, LEA COUNTY, , REPORT, OR OTHE 	Exploratory WARE and State		
	r E-Mail: david_stewa R., M., or Survey Description) DFSL 660FWL W Lon OPRIATE BOX(ES) TO Acidize Alter Casing Casing Repair	DAVID STEWART Int@oxy.com 3b. Phone No. (include area Ph: 432-685-5717 Fx: 432-685-5717 INDICATE NATURE TYF Deepen Fracture Treat	OF NOTICE PE OF ACTION	8. Well Name and No COTTON DRAW 9. API Well No. 30-025-08211 10. Field and Pool, or PADUCA DELA 11. County or Parish, LEA COUNTY, , REPORT, OR OTHE	UNIT 37 Exploratory AWARE and State NM		
Oil Well Gas Well Othe 2. Name of Operator OXY USA INC. 3a. Address P.O. BOX 50250 MIDLAND, TX 79710 4. Location of Well (Footage, Sec., T., Sec 21 T25S R32E SWSW 660 32.110470 N Lat, 103.686530 N 12. CHECK APPRO TYPE OF SUBMISSION X Notice of Intent Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Oper	Contact: [E-Mail: david_stewa R., M., or Survey Description] DFSL 660FWL W Lon OPRIATE BOX(ES) TO	art@oxy.com 3b. Phone No. (include area Ph: 432-685-5717 Fx: 432-685-5717 INDICATE NATURE TYF Deepen Fracture Treat	OF NOTICE PE OF ACTION	COTTON DRAW 9. API Well No. 30-025-08211 10. Field and Pool, or PADUCA DELA 11. County or Parish, LEA COUNTY, , REPORT, OR OTHE	Exploratory WARE and State		
 2. Name of Operator OXY USA INC. 3a. Address P.O. BOX 50250 MIDLAND, TX 79710 4. Location of Well (Footage, Sec., T., Sec 21 T25S R32E SWSW 660 32.110470 N Lat, 103.686530 N 12. CHECK APPRO TYPE OF SUBMISSION I2. CHECK APPRO TYPE OF SUBMISSION I2. Notice of Intent Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Oper 	Contact: [E-Mail: david_stewa R., M., or Survey Description] DFSL 660FWL W Lon OPRIATE BOX(ES) TO	art@oxy.com 3b. Phone No. (include area Ph: 432-685-5717 Fx: 432-685-5717 INDICATE NATURE TYF Deepen Fracture Treat	OF NOTICE PE OF ACTION	30-025-08211 10. Field and Pool, or PADUCA DELA 11. County or Parish, LEA COUNTY, , REPORT, OR OTHE	and State		
P.O. BOX 50250 MIDLAND, TX 79710 4. Location of Well (Footage, Sec., T., Sec 21 T25S R32E SWSW 660 32.110470 N Lat, 103.686530 N 12. CHECK APPRO TYPE OF SUBMISSION ☑ Notice of Intent □ Subsequent Report □ Final Abandonment Notice 13. Describe Proposed or Completed Oper	DFSL 660FWL W Lon OPRIATE BOX(ES) TO Acidize Alter Casing Casing Repair	Ph: 432-685-5717 Fx: 432-685-5717 INDICATE NATURE TYF Deepen Fracture Treat	OF NOTICE PE OF ACTION	PADUCA DELA 11. County or Parish, LEA COUNTY, , REPORT, OR OTHE	and State		
 4. Location of Well (Footage, Sec., T., Sec 21 T25S R32E SWSW 660 32.110470 N Lat, 103.686530 V 12. CHECK APPR(TYPE OF SUBMISSION X Notice of Intent Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Oper 	DFSL 660FWL W Lon OPRIATE BOX(ES) TO Acidize Alter Casing Casing Repair	INDICATE NATURE TYF Deepen Fracture Treat	PE OF ACTION	LEA COUNTY, , REPORT, OR OTHE	NM		
32.110470 N Lat, 103.686530 N 12. CHECK APPRO TYPE OF SUBMISSION Notice of Intent Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Oper	W Lon OPRIATE BOX(ES) TO Acidize Alter Casing Casing Repair	TYF Deepen Fracture Treat	PE OF ACTION	, REPORT, OR OTHE	/		
TYPE OF SUBMISSION Notice of Intent Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Oper	 Acidize Alter Casing Casing Repair 	TYF Deepen Fracture Treat	PE OF ACTION	N	R DATA		
 Notice of Intent Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Oper 	 Alter Casing Casing Repair 	DeepenFracture Treat					
 Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Oper 	 Alter Casing Casing Repair 	Fracture Treat	🗖 Proc				
 Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Oper 	Casing Repair	-		luction (Start/Resume)	UWater Shut-Off		
 Final Abandonment Notice 13. Describe Proposed or Completed Oper. 			_	amation	□ Well Integrity		
13. Describe Proposed or Completed Oper		New Constructio Plug and Abando	_	omplete porarily Abandon	Other		
13. Describe Proposed or Completed Oper	Convert to Injection	Plug Back		Water Disposal			
8-5/8" 24# csg @ 397' w/ 325sx 4-1/2" 9.5# csg @ 4778' w/ 150	sx cmt, 7-7/8" hole, TOC		s OCD v 2 2013	RECLAMATION PRO Attached	LEDUKE		
Circulate 10# MLF between plu 1. RIH & set CIBP @ 4560', M8 2. Perf @ 2785', sqz 45sx cmt t 3. Perf @ 1150', sqz 40sx cmt t 4. Perf @ 447', sqz 160sx cmt t	-	C-Tag RE		SEE ATTACHED FOR CONDITIONS OF APPROVAL			
<u>Fround</u> Level Dry 14. Thereby certify that the foregoing is to	Hole Macker	Required					
	Committed to AFMSS for p	Y USA INC., sent to the i ocessing by JOHNNY DI	Hobbs CKERSON on	-			
Signature (Electronic Su	bmission)	Date 09/	Date 09/09/2013				
	THIS SPACE FOR	R FEDERAL OR STA	TE OFFICE	USE			
Approved By	2. Comes_	Title	SEA_	5	9-24- Date		
Conditions of approval, if any, are attached. certify that the applicant holds legal or equit which would epittle the applicant to conduct	able title to those rights in the s		(70				
Title 18 U.S.C. Section 1001 and Title 43 U. States any false, fictitious of fraudulenysta	S.C. Section 1212, make it a craterious or representations as to	ime for any person knowingl any matter within its jurisdic	y and willfully to stion.	make to any department or	agency of the United		
** OPERAT(DR-SUBMITTED ** OP	ERATOR-SUBMITTE					
				OCT 0 3 20	Bh. L		

Additional data for EC transaction #219502 that would not fit on the form

32. Additional remarks, continued

•

Above ground steel tanks will be utilized.



OXY USA Inc. - Current Cotton Draw Unit #37 API No. 30-025-08211

د •

						12-1/4" hole @ 397' 8-5/8" csg @ 397' w/ 325sx-TOC-Surf-Circ
						7-7/8" hole @ 4784' 4-1/2" csg @ 4784' w/ 150sx-TOC-4125'-Calc
PB-4747'	TD-4784'	E	Perfs @	4610-	4654	4'



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Inspection & Enforcement

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909, 575-361-2648 (Cell)

Mike Burton Environmental Protection Specialist 575-234-2226

Jeffery Robertson Natural Resource Specialist 575-234-2230

Jennifer Van Curen Environmental Protection Specialist 575-234-5905

Doug Hoag Civil Engineering Technician 575-234-5979

Linda Denniston Environmental Protection Specialist 575-234-5974

Solomon Hughes Natural Resource Specialist 575-234-5951

Permitting

Cody Layton Natural Resource Specialist 575-234-5959

Trishia Bad Bear Natural Resource Specialist 575-393-3612

Todd Suter Surface Protection Specialist 575-234-5987

Tanner Nygren Natural Resource Specialist 575-234-5975

Amanda Lynch Natural Resource Specialist 575-234-5922

Legion Brumley Environmental Protection Specialist 575-234-5957

<u>Realty, Compliance</u> Randy Pair Environmental Protection Specialist 575-234-6240

Requirements for ground level dry hole markers <u>Well Identification Markers</u> Conditions of Approval (COA)

The BLM Carlsbad Field Office (CFO) Conditions of Approval (COA) Requires that ground level dry hole markers be placed on well within the Lesser Prairie Chicken habitat area. The dry hole markers will be to the following specifications. The operator will construct the markers as follows:

- 1. An 8 inch X 8 inch steel plate 1/8 to 3/16 of an inch thick is to be placed on the old dry hole marker stand pipe 2 inches from ground level, in the Lesser Prairie Chicken habitat area.
- 2. Steel plate may be welded or bolted approximately 2 inches from ground level on the stand pipes. If plates are bolted to the stand pipe, the person installing the plate will be required to weld a pipe collar on the plate and place a minimum of two set screws/bolt on each collar. Aluminum data plates may be bolted with minimum ¹/₄ inch bolt and locking nuts or self tapping fine threaded screws. A minimum of one in each corner is to be installed on each plate.
- 3. An 8 inch x 8 inch aluminum plate, which is 12 gauge or .080 sign material (1/8 inch aluminum plate may be used in place of the .080 plate) with the required information for that well stamped or engraved in a minimum 3/8 inch tall letter or number.
- 4. The following information will be stamped or engraved on the 8 inch X 8 inch aluminum plate in the following order.
 - a. First row: Operators name
 - b. Second row: Well name and number
 - c. Third row: Legal location to include ¹/₄ ¹/₄, Section, Township, and range. If the legal location cannot be placed on one row it can be split into two rows with the ¹/₄ ¹/₄ (example: 1980 FNL 1980 FWL) being on the top row.
 - d. Fourth row: Lease Number and API number.
 - i. Example marker plate: (attached)

NMOCD Order No. R-12965 also required the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a ground level dry hole marker was installed as required in the COA's from the BLM.

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.