

Submit 1 Copy To Appropriate District  
Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-35802
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator DAVID H. ARRINGTON OIL AND GAS,		6. State Oil & Gas Lease No.
3. Address of Operator P.O. BOX 2071 MIDLAND, TX 79702		7. Lease Name or Unit Agreement Name Double Hackle Peacock 31 State Com
4. Well Location Unit Letter <u>X</u> : 2380 feet from the <u>South</u> line and <u>958</u> feet from the <u>West</u> line Section <u>31</u> Township <u>16S</u> Range <u>36E</u> NMPM County <u>Lea</u>		8. Well Number 1
		9. OGRID Number 5898
		10. Pool name or Wildcat Shoe Bar; Chester, East (Gas)
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4020' GL		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) MIRU ND WH NU BOP. 2) POOH w/ production tbg. RU wire line & run gauge ring to 11,250'. Pull same. Run & set 5 1/2" CIBP @ 11,250', dump bail 35' cmt. 3) RIH open ended @ 11,200'. Circ hole 9.5 MLF. POOH ND BOP & WH. 4) NU to 5 1/2 csg, stretch & cut @ +/- 6,000' & LD same. 5) RIH to 6,050', spot 45 sx cmt plug. Pull up hole, WOC tag 50' above sub. 6) Pull up hole 5,015', spot 50 sx cmt plug. WOC & tag @ 4,900'. Pull up hole to 3,000'. Spot 35 sx cmt plug. Pull up to 500', spot 40 sx cmt plug. POOH. WOC & TAG. 7) Cut off WH, mast & anchors 3' below ground level. Install 10 sx cmt to surface and DHM. RD MO.

3B. 7 PERF SQZ 30 SX 5' H' CMT @ 9300' WOC & TAG  
60' TO SURF.  
L SPOT 35 SX 5' CMT @ 2000'

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE ENGINEERING TECH

DATE 10/14/2013

Type or print name DEBBIE WHITING

E-mail address: DEBBIE.WHITING@ARRINGTONPHONE: (505) 682-6685

For State Use Only

APPROVED BY:

TITLE Compliance Officer

DATE 10/18/2013

Conditions of Approval (if any):

OIL CONSERVATION DIVISION - Hobbs office Must Be Notified  
24 hours prior to the beginning of Plugging Operations.

OCT 22 2013


2380' FSL  
958' FWL  
S-31  
T16S  
R36E

Double Hackle Peacock 1  
Lea County, New Mexico  
Plug and Abandon Wellbore

KB: 4037'  
GL: 4020'

API: 30-025-35802

Spud: 06/27/02  
Rig Rel: 07/27/02



2380' FSL  
958' FWL  
S-31  
T16S  
R36E

Double Hackle Peacock 1  
Lea County, New Mexico  
Existing Wellbore

KB: 4037'  
GL: 4020'

API: 30-025-35802

Spud: 06/27/02  
Rig Rel: 07/27/02

