Submit 1 Copy To Appropriate District Office District I Energy, Minerals and Natural Resources	Form C-103 October 13, 2009
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-025-38149
District II 1301 W. Grand Ave., Artesia, NM 88210 HOBS OF CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE FEE
$\frac{1220}{\text{South St. Prancis Dr.}}$ 1000 Rio Brazos Rd., Aztec, NM 87410 District IV $\frac{1220}{\text{South St. Prancis Dr.}}$ OCT 2 3 2013 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.)	North Monument G/SA Unit Blk. 21 8. Well Number 346
1. Type of Well: Oil/Well Gas Well TA'd well	
2. Name of Operator Apache Corp.	9. OGRID Number 873
3. Address of Operator	10. Pool name or Wildcat
P O box Drawer D Monument NM 88265	Eunice Monument G/SA
4. Well Location	
Unit LetterE: 1330feet from theN line and _	1310feet from the
Wline	
Section 5 Township 20S Range 37E	
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
12. Charle Annue miste Den te Indiante Neture of Netice	Powert on Other Date
12. Check Appropriate Box to Indicate Nature of Notice	, Report or Other Data
NOTICE OF INTENTION TO: SUE	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK 🔲 PLUG AND ABANDON 🔲 🛛 REMEDIAL WO	
-	
OTHER: OTHER: E	
	Extend TA status
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, a	nd give pertinent dates, including estimated date
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> </ul>	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32</li> </ul>	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> </ul>	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32 Apache requests an extended TA status for this well.</li> </ul>	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of minutes with no pressure loss.
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32 Apache requests an extended TA status for this well.</li> </ul>	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of minutes with no pressure loss.
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32 Apache requests an extended TA status for this well.</li> </ul>	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of minutes with no pressure loss.
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32 Apache requests an extended TA status for this well.</li> </ul>	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of minutes with no pressure loss.
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32 Apache requests an extended TA status for this well.</li> </ul>	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32 Apache requests an extended TA status for this well.</li> </ul>	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of minutes with no pressure loss.
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32 Apache requests an extended TA status for this well.</li> </ul>	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of minutes with no pressure loss.
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32 Apache requests an extended TA status for this well.</li> </ul>	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of minutes with no pressure loss.
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32 Apache requests an extended TA status for this well.</li> </ul>	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of minutes with no pressure loss.
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32 Apache requests an extended TA status for this well.</li> <li>This Approv Abandonm</li> </ul>	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of minutes with no pressure loss.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.         Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32 Apache requests an extended TA status for this well.         This Approv Abandonm         Spud Date:       Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of minutes with no pressure loss. val of Temporary ent Expires 0-22 - 2017
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32 Apache requests an extended TA status for this well.</li> <li>This Approv Abandonm</li> </ul>	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of minutes with no pressure loss. val of Temporary ent Expires 0-22 - 2017
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.         Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32 Apache requests an extended TA status for this well.         This Approv Abandonm         Spud Date:       Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of minutes with no pressure loss. val of Temporary ent Expires 0-22 - 2017
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.         Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32 Apache requests an extended TA status for this well.         This Approv Abandonm         Spud Date:       Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of minutes with no pressure loss. val of Temporary ent Expires 0-22 - 2017
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.         Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32 Apache requests an extended TA status for this well.         This Approv Abandonm         Spud Date:       Rig Release Date:         I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE       Signature	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of minutes with no pressure loss. val of Temporary ent Expires 0-22 -2017 ent Expires 0-22 -2017 lge and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.         Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32 Apache requests an extended TA status for this well.         This Approv Abandonm         Spud Date:       Rig Release Date:         I hereby certify that the information above is true and complete to the best of my knowled         SIGNATURE       Jim Ellison         Type or print name       Jim Ellison	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of minutes with no pressure loss. val of Temporary ent Expires 0-22 -2017 ent Expires 0-22 -2017 lge and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.         Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32 Apache requests an extended TA status for this well.         This Approv Abandonm         Spud Date:       Rig Release Date:         I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE       Signature	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of minutes with no pressure loss. val of Temporary ent Expires 0-22 -2017 ent Expires 0-22 -2017 lge and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.         Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32 Apache requests an extended TA status for this well.         This Approv Abandonm         Spud Date:       Rig Release Date:         I hereby certify that the information above is true and complete to the best of my knowled         SIGNATURE       Jim Ellison         Type or print name       Jim Ellison         E-mail address:       JD.Ellison@a         For State Use Only       PHTLE         APPROVED BY:       PHTLE	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of minutes with no pressure loss. val of Temporary ent Expires 0-22 -2017 ent Expires 0-22 -2017 lge and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.         Move in Gandy truck and pressure the casing to 540 psi. Record the test on a chart for 32 Apache requests an extended TA status for this well.         This Approv About the test on a chart for 32 Apache requests an extended TA status for this well.         Spud Date:       Rig Release Date:         I hereby certify that the information above is true and complete to the best of my knowled         SIGNATURE       TITLE_Instrument Tech_         Type or print name       Jim Ellison         For State Use Only       Context	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of minutes with no pressure loss. val of Temporary ent Expires 0-22-2017 lge and belief. DATE 10-22-13 pacheccorp.com_PHONE:

