Form 3160-5 (March 2012)

Subsequent Report

Final Abandonment Notice

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Casing Repair

Convert to Injection

OCD Hobbs

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

Wother Countetia

MOBBS OC Lease Serial No.

Recomplete

Water Disposal

Temporarily Abandon

Oreon mama

Jf Indian, Allottee or Tribe Name

	Sl	JND	RY	NOTI	CES	SAND	REP	ORTS	ON	WELL	s or	T 9.	ฤ
Do	not L	ıse	this	form	for	propo	sals	to dri	ll or	to re-e	S inter an	1 4	C

abandoned well.	Use Form 3160-3 ((APD) for such prope	osals.				
, SUBM	IT IN TRIPLICATE - Oth	ner instructions on page 2.	RECEIV	ने? If Unit of CA/A	greement, Name ai	ıd/or No.	
1. Type of Well							
Oil Well Gas V	Well Other			8. Well Name and	No. 35 Federa	.(#IH/	,
2. Name of Operator OXY USA Inc	;	16696		9. API Well No.	રહ્યામ-		
3a. Address		3b. Phone No. (include are	ea code) , ·	10. Field and Pool	or Exploratory Arc	:a	
P.O. Box 50250 Midland, TX 79710		432-685-5717		W: Lecar	- Bone S	poins	
Location of Well (Footage, Sec., T.,	R.M., or Survey Description	on)		11. County or Paris	h, State		
400 FNL 329 FWI	- nmnm(0) <	ec 35 Ta65 R	34E "	lea	NM		
12. CHE	CK THE APPROPRIATE E	BOX(ES) TO INDICATE NA	TURE OF NOTE	CE, REPORT OR O	THER DATA		
TYPE OF SUBMISSION			TYPE OF ACT	ION			
Notice of Intent	Acidize	Deepen	Prod	uction (Start/Resume)	Water S	Shut-Off	
Konce of finem	Alter Casing	Fracture Treat	Recl	amation	Well In	tegrity	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

New Construction

Plug and Abandon


Plug Back

RUPU 8/5/13, RIH & tag DVT, drill out, , push down to 13000', RIH w/ CBL. TIH, drill and clean out to PBTD @ 16309'. Pressure test csg to 8562#, held for 30min, tested good. RIH & perf @ 16272-15831, 15684-15243, 15096-14655, 14508-14067, 13920-13479, 13332-12891' Total 235 holes. Frac in 6 stages w/ 93781g WaterFrac G-6 + 19500g 15% HCl acid + 291700g WaterFrac GR-20 + 685084g Delta Frac 140-R10 w/ 1134704# sand, RD HES. RIH with 2-7/8" tbg & pkr & set 11160'. Flow to clean up and test well for potential.

le Sr. Regulatory Advisor				
e aluliz	TROOLI TED FOR RECORD			
L OR STATE OFFICE	USE 0CT 2 0 2013			
Title	Date			
Office	CARLSBAD FIELD OFFICE			
	y			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

OXY USA.Inc. Madera 35 Federal #1H API No. 30-025-41083



550sx @ 12800-11278'