

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

Revised August 1, 2011

HOBBS OCD

OIL CONSERVATION DIVISION

OCT 31 2013

1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Klein #5
2. Name of Operator Read & Stevens, Inc	8. Well Number 001
3. Address of Operator P.O. Box 1518 Roswell, NM 88202-1518	9. OGRID Number 18917
4. Well Location Unit Letter <u>H</u> : <u>2020</u> feet from the <u>South</u> line and <u>330</u> feet from the <u>East</u> line Section <u>5</u> Township <u>20S</u> Range <u>3E</u> <u>6E</u> NMPM Lea County	10. Pool name or Wildcat North Osudo Devonian/Strawn
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3632' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10/11/2013 Moved in and rigged up
10/14/2013 Dug out cellar and installed BOP. Started picking up 2 7/8" workstring with a 5 1/2" CIBP on the end.
10/15/2013 Finished picking up workstring and tagged at 10559'. Called OCD. POOH to 9607' and set CIBP. Circulated MLF and spotted 25 sx class H cement on top of CIBP. POOH to 8966' and spotted 25 sx class H cement. POOH and spotted 25 sx class H cement at 5852'. POOH to 4650' and spotted 25 sx class H cement. SION. Will tag in the morning.
10/16/2013 Tagged at 4468'. POOH with tubing and nipples down wellhead, cut off bolts on wellhead and welded on 5 1/2" pull stub. Rigged up wireline and cut casing at 3500'. Casing did not move off slips after cutting. Shot wellhead with primer cord. Casing still not off the slips. SION
10/17/2013 Pulled 125,000# on casing and shot wellhead with primer cord again. Casing still not moving off the slips. Picked up 5 1/2" packer and set with 1 joint below pull stub. Loaded casing and pressured up to 1100#. Held for 30 minutes with no pressure drop. Released packer and called Read & Stevens office. Cut off pull stub and reinstalled wellhead and BOP. RIH to 3552' and spotted 25 sx cement. SION.
10/18/2013 RIH and tagged at 3354'. POOH and perforated at 1700'. Squeezed perfs with 25 sx cement. WOC and tagged at 1567'. Laid down remaining workstring and perforated at 458'. Circulated cement down 5 1/2" casing to perfs at 458' and up annulus to surface.
10/21/2013 Rigged down and cut off wellhead. Filled all casing strings to surface with cement, installed marker and cut off anchors.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tim Collier TITLE Sr VP, Exploration & Development DATE 10/30/2013

Type or print name Tim Collier E-mail address: tcollier@read-stevens.com PHONE: 575-622-3770
For State Use Only

APPROVED BY: [Signature] TITLE Dist. Mgr DATE 10-31-2013
Conditions of Approval (if any):

OCT 31 2013