HOBBS OCD

OCT 1 5 2013	
Submit 7 Conjes To Appropriate District State of Monte Monte of	/ Form C-103
District 1 Energy, Minerals and Natural Resources	October 25. 2007
District I District I	WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE STATE
District IV. Santa Fe, NM 8/505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	VO-5232
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.)	Cherry State •
I. Type of Well: Oil Well Gas Well Other	· 1
2. Name of Operator Mack Energy Corporation	9. OGRID Number 013837
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 960 Artesia, NM 88211-0960	Anderson Ranch; Wolfcamp West
4. Well Location	
Unit Letter E feet from the North line and 662 feet from the West line	
Section 9 Township 16S Range 32E NMPM County L	
1 1. Elevation (Show whether DR, RKB, RT, GR, etc	
4345' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUE	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
	ILLING OPNS 🗍 🍈 P ĂND A 👘 🗍
PULL OR ALTER CASING I MULTIPLE COMPL	ТЈОВ
OTHER:	s ready for OCD inspection after PLA
	erator's pit permit and closure plan.
All pits have been remediated in compliance with OCD rules and the terms of the Ope	erator's pit permit and closure plan. properly abandoned.
All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set	crator's pit permit and closure plan. properly abandoned. n concrete. It shows the
 All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER OF 	prator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/OUARTER LOCATION OR
All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set	prator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/OUARTER LOCATION OR
 All pits have been remediated in compliance with OCD rules and the terms of the Opd Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER QUINT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATI PERMANENTLY STAMPED ON THE MARKER'S SURFACE. 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/OUARTER LOCATION OR ON HAS BEEN WELDED OR
 All pits have been remediated in compliance with OCD rules and the terms of the Opd Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set i OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATI PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/OUARTER LOCATION OR ON HAS BEEN WELDED OR
 All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATI PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/OUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and
 All pits have been remediated in compliance with OCD rules and the terms of the Opd Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set i OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATI PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the <u>JARTER/OUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and and level.
 All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATI PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proceeding the second seco	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the <u>JARTER/OUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk. trash, flow lines and ind level.) have been remediated in compliance with
 All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATI PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proc from lease and well location. 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the <u>JARTER/OUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and and level.) have been remediated in compliance with luction equipment and junk have been removed
 All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATI PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the <u>JARTER/OUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and and level.) have been remediated in compliance with luction equipment and junk have been removed
 All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATI PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed.) All other environmental concerns have been addressed as per OCD rules. 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/OUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level.) have been remediated in compliance with luction equipment and junk have been removed oved. (Poured onsite concrete bases do not have
 All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATI PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/OUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level.) have been remediated in compliance with luction equipment and junk have been removed oved. (Poured onsite concrete bases do not have
 All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATI PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed.) All other environmental concerns have been addressed as per OCD rules. 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/OUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level.) have been remediated in compliance with luction equipment and junk have been removed oved. (Poured onsite concrete bases do not have
 All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATI PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proc from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b non-retrieved flow lines and pipelines. 	properly abandoned. n concrete. It shows the JARTER/OUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level.) have been remediated in compliance with luction equipment and junk have been removed oved. (Poured onsite concrete bases do not have
 All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATI PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) 	properly abandoned. n concrete. It shows the <u>JARTER/OUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and ind level.) have been remediated in compliance with luction equipment and junk have been removed oved. (Poured onsite concrete bases do not have) NMAC. All fluids have been removed from hedule an inspection. If more than one
 All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set is OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATI PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below groud If this is a one-well lease or last remaining well on lease, the battery and pit location (so OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proc from lease and well location. All metal bolts and other materials have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b non-retrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to sc inspection has to be made to a P&A location because it does not meet the criteria above, a 	properly abandoned. n concrete. It shows the JARTER/OUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level.) have been remediated in compliance with luction equipment and junk have been removed oved. (Poured onsite concrete bases do not have oved. (Poured onsite concrete bases do not have hedule an inspection. If more than one penalty may be assessed.
 All pits have been remediated in compliance with OCD rules and the terms of the Opd Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATI PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proc from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b non-retrieved flow lines and pipelines. 	properly abandoned. n concrete. It shows the <u>JARTER/OUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and ind level.) have been remediated in compliance with luction equipment and junk have been removed oved. (Poured onsite concrete bases do not have) NMAC. All fluids have been removed from hedule an inspection. If more than one
 All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set i OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATI PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grow If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proc from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b non-retrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to see inspection has to be made to a P&A location because it does not meet the criteria above, a SIGNATURE May May May May May May May May May May	properly abandoned. n concrete. It shows the JARTER/OUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level.) have been remediated in compliance with luction equipment and junk have been removed oved. (Poured onsite concrete bases do not have) NMAC. All fluids have been removed from hedule an inspection. If more than one penalty may be assessed. DATE <u>9/25/13</u>
 All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set is OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATI PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below groud If this is a one-well lease or last remaining well on lease, the battery and pit location (so OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proc from lease and well location. All metal bolts and other materials have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b non-retrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to sc inspection has to be made to a P&A location because it does not meet the criteria above, a 	properly abandoned. n concrete. It shows the JARTER/OUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level.) have been remediated in compliance with luction equipment and junk have been removed oved. (Poured onsite concrete bases do not have) NMAC. All fluids have been removed from hedule an inspection. If more than one penalty may be assessed. DATE <u>9/25/13</u>
 All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set i OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATI PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group if this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proc from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b non-retrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to sc inspection has to be made to a P&A location because it does not meet the criteria above, a SIGNATURE You Sherrell E-MAIL: jerrys@mec.com For State Use Only 	properly abandoned. n concrete. It shows the JARTER/OUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level.) have been remediated in compliance with luction equipment and junk have been removed oved. (Poured onsite concrete bases do not have) NMAC. All fluids have been removed from hedule an inspection. If more than one penalty may be assessed. DATE <u>9/25/13</u>
 All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATI PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proc from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b non-retrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to see inspection has to be made to a P&A location because it does not meet the criteria above, a SIGNATURE Yee OR PRINT NAME Jerry W. Sherrell 	properly abandoned. n concrete. It shows the JARTER/OUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level.) have been remediated in compliance with luction equipment and junk have been removed oved. (Poured onsite concrete bases do not have) NMAC. All fluids have been removed from hedule an inspection. If more than one penalty may be assessed. DATE <u>9/25/13</u>

NOV 0 4 2013

Jor