OCHORRS OCD

Form 3160-5 (September 2001)

UNITED STATES

FORM APPROVED OM B No. 1004-0135

. ,	DEPARTME				NOV	1220	13	Expires: Janua	ry 31, 2004
	BUREAU OF						5. Lease Ser		
	Y NOTICES					D 2011 #10079		063798 n, Allottee or T	eibo Noma
Do not use abandoned	this form for well. Use For	proposals m 3160-3	to drill or (APD) for s	to re-ei uch proj	nter 表定(posals.	SEIVEL	6. If India	n, Anonce of 1	noc Name
SUBMIT IN T	RIPLICATE	- Other ins	tructions o	n revers	se side.		7. If Unit o	or CA/Agreeme	ent, Name and/or No.
1. Type of Well Oil Well	Gas Well	✓ Other	Acid Gas I	Injection			8. Well N	ame and No.	
2. Name of Operator Agave En	ergy Company						9. API W	Red Hills At	31#1
3a Address 105 S. Fourth Street, Artesi	a, NM 88210		3b. Phone N 575-748-		area code)			s-40448 nd Pool, or Exp	nloratory Area
4. Location of Well (Footage, Se	ec., T., R., M., or Sur	vey Description)					4	ratory (Cher	•
At Surface: 1600 FSL, 150 At TD: Same as surface				lo, NM				or Parish. St	ile
							Leac	ounty, NM	
	APPROPRIATE	BOX(ES) TO	O INDICATE				EPORT. O	ROTHER I	DATA
TYPE OF SUBMISSION				TYP	E OF AC	IION			
Notice of Intent	Acidize After Ca	sing	Deepen Fracture T New Cons		Recla	action (Sta amation mplete	in/Resume)	Well In	Shut-Off tegrity BOPE Test
Subsequent Report	Change	•	Plug and /	•		orarily Ab	andon	 0	
Final Abandonment Notice		to Injection	Plug Back		·	r Disposal			
following completion of the testing has been completed. determined that the site is re Yates Petroleum R/U a was completed approxi Juan Galvan, Yates Co	Final Abandonmer ady for final inspect nd tested the BOI mately 0300, Octo	nt Notices shall be ion.) PE on Agave R	e filed only after	all requiren	nents, includ	ling reclam	ation, have be s on Octobe Mark Dayton	en completed. r 27, 2013, th n at 0208 on 0	and the operator has ne final of 10 tests October 27, 2013 by
						•	1 1	ادم	OR RECOR 7 2013 FORMAN AGENTS AND MANAGEMENT AD FIELD OFFICE
14. Thereby certify that the for Name (Printed/Typed)	oregoing is true ar	nd correct							
Tom Sharp, C	ieolex, Inc.			Title Co	nsultant t	o Agave E	nergy Com	pany	
Signature 76m	Share	,		Date /	0/28	3/20	13		
	THIS SP	ACE FOR	FEDERAL	. OR \$1	TATE O	FFICE	USE		
Approved by				Ti	tle			Date	
Conditions of approval, if any, a certify that the applicant holds le which would entitle the applicant	gal or equitable titl	e to those rights			Tice				
Title 18 U.S.C. Section 1001 and States any false, fictitious or frau	litte 43 U.S.C. Section	on 1212, make it	a crime for any	person kno r within its	wingly and	l willfully t	o make to an	y department o	or agency of the United

(Instructions on page 2)



Company Voltes	Date Charles Control of the Control
Lease Not Alb Ab#/	County Last Air Air.
Drilling Contractor Silver Conf	Plug & Drill Pipe Size
Accumulator Fun To Check - USABLE FLUID IN THE NITROG	ection Test - OO&GO#2 EN BOTTLES (III.A.2.c.i. or ii or iii)

- Make sure all rams and annular are open and if applicable HCR is closed.
- Ensure accumulator is pumped up to working pressure! (Shut off all pumps)
 - 1. Open HCR Valve. (If applicable)
 - 2. Close annular.
 - 3. Close all pipe rams.
 - 4. Open one set of the pipe rams to simulate closing the blind ram.
 - 5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems).
 - 6. Record remaining pressure 1900 psi. Test Fails if pressure is lower than required.
- a.{950 psi for a 1500 psi system} b. {1200 psi for a 2000 & 3000 psi system}
 - 7. If annular is closed, open it at this time and close HCR.

To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)

- Start with manifold pressure at, or above, maximum acceptable pre-charge pressure:
 - a. {800 psi for a 1500 psi system} b. {1100 psi for 2000 and 3000 psi system}
 - 1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)
 - 2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.
 - 3. Record pressure drop 750 psi. Test fails if pressure drops below minimum.
- Minimum: a. {700 psi for a 1500 psi system } b. {900 psi for a 2000 & 3000 psi system}

To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold.
- Open the bleed off valve to the tank, {manifold psi should go to 0 psi} close bleed valve.
 - 1. Open the HCR valve, {if applicable}
 - 2. Close annular
 - 3. With pumps only, time how long it takes to regain the required manifold pressure.
 - 4. Record elapsed time $\frac{1115}{115}$. Test fails if it takes over 2 minutes.
- a. {950 psi for a 1500 psi system} b. {1200 psi for a 2000 & 3000 psi system}



WELDING . BOP TESTING

WELDING SERVICES	8	AUD AND G	AS SEPARA • 575-3		Pg. /	_ of <u>/</u>
Company: Yates Lease: Red Hills AGI#/ Plug Size & Type: 12 CAR	Orill Pipe Siz	Drilling	XH	13 Silve? Oz 5000	Day Olive	8 63399 Kelanli
Required BOP: 2000 'Appropriate Casing Valve Must Be Open During BOP Test '		Insta	lled BOP	· Check	Vaive Must 8e Open/Disa	bied To Test Kill Line Valves '
Annular #15 Pipe Rams #12 Blind Rams #13 #11 #10 #9 Pipe Rams #14 Casing	#26 #2 #4 #4 #3 #11 #25 Super Ch	#8B Mud Gaug Valve		Kelly/ Top Drive	Pump Valve #20	Dart Valve #19 Stand Pipe Valve #24 TIW Valve #18 Pump Valve #21
TEST # ITEMS TESTED	TEST LENGTH	LOW PSI	HIGH PSI		REMARKS	
1 Truck	10/10	350	2000	Pulled ch	ech valve	Pe155
2/15,9,7		لم	1500	-		
3/2.9.7	لمسمر		3000)
4/2.10,8		1	Ka			
512.11.345.88		((-	2.tolar VI	I han Rock T	11

TEST #	I ITEMS TESTED	IEST LENGTH	LOW PSI	HIGH PSI	MEMANNS
1	Truck	10/10	350	3000	Pulled check Valve Pass
a	15,9,7		1	1500	' <
3	129,7	لمسمر	J	3000)
4	1/2./0,8		1	10	
5	12,163,4,5,88	ر		(Putcheck Wille Back IN
6	13.11.16.2))	
7	13.11,26,6	7	de la companya de la		(
8	18				
9	19	(J
10	affe : Kelly "		(
	Gleo Conside Kill	whe)		(
12	Remo. Kill line	1	A.	,	
	,				
			·		
1		1			











