Office	State of New Mexico	Form C-103
District I – (575) 393-6161 Ener	gy, Minerals and Natural Resources	Revised August 1, 2011
Office  District I – (575) 393-6161  1625 N. French Dr., Hobbs, NM 82 B3S OCD  District III – (575) 748-1283 811 S. First St., Artesia, NM 88210  District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410  District IV – (505) 676-3460  District IV – (505) 78-8014 Fg. NM		WELL API NO.
811 S. First St., Artesia, NM 88210	CONSERVATION DIVISION	30-025-40821 5. Indicate Type of Lease
District III - (505) 334-6178 NOV 1 8 2013	1220 South St. Francis Dr.	STATE STEE
1000 Rio Brazos Rd., Aztec, NM\\874\10^-	Santa Fe. NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		o. State Off & Gas Lease No.
87505 RECEIVED		
SUNDRY NOTICES AND		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DR		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PROPOSALS.)	PERMIT" (FORM C-101) FOR SUCH	Hickory 14 State
1. Type of Well: Oil Well  Gas Well	Other	8. Well Number
		01
2. Name of Operator		9. OGRID Number
COG Operat		229137
3. Address of Operator One Concho Center		10. Pool name or Wildcat
600 West Illinois Ave.,	Midland, TX 79701	Vacuum; Blinebry, Northeast 97021
4. Well Location		
Unit Letter A : 990 fee	et from the North line and 990	feet from the East line
	rnship 17S Range 35E	NMPM Lea County
	ation (Show whether DR, RKB, RT, GR, etc.	
Tr. Bleve	3930' GR	Company of the Compan
	3750 GK	
12 Charle Ammanuia	to Don to Indicate Nature of Nation	D O4l D-4-
12. Cneck Appropria	te Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTIO	NITO:   SLIB	SEQUENT REPORT OF:
	ND ABANDON ☐ REMEDIAL WOR	
TEMPORARILY ABANDON CHANGE	_	ILLING OPNS. P AND A
PULL OR ALTER CASING   MULTIPL	LE COMPL ☐   CASING/CEMEN	I JOB [_]
DOWNHOLE COMMINGLE		
_	П отигр.	Danis da 4. 04
OTHER:	OTHER:	Recomplete to SA
OTHER:  13. Describe proposed or completed opera	tions. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F		d give pertinent dates, including estimated date
OTHER:  13. Describe proposed or completed opera	tions. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.	tions. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488	tions. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid.
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 483 10/10/13 Acidize w/6000 gals 20% acid. Frac w	tions. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co 86 – 5140, 2SPF, 40 holes. Pumped 500 gal 1/40,278 gals gel, 21,073# 20/40 white sand	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid.
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488 10/10/13 Acidize w/6000 gals 20% acid. Frac w 10/27/13 RIH w/ 150jts 2-7/8 J55 6.5# tbg. EO	tions. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co $36-5140$ , 2SPF, 40 holes. Pumped 500 gal $1/40,278$ gals gel, 21,073# 20/40 white sand $1/40,278$ gals	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid.
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 483 10/10/13 Acidize w/6000 gals 20% acid. Frac w	tions. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co $36-5140$ , 2SPF, 40 holes. Pumped 500 gal $1/40,278$ gals gel, 21,073# 20/40 white sand $1/40,278$ gals	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid.
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488 10/10/13 Acidize w/6000 gals 20% acid. Frac w 10/27/13 RIH w/ 150jts 2-7/8 J55 6.5# tbg. EO	tions. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co $36-5140$ , 2SPF, 40 holes. Pumped 500 gal $1/40,278$ gals gel, 21,073# 20/40 white sand $1/40,278$ gals	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid.
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488 10/10/13 Acidize w/6000 gals 20% acid. Frac w 10/27/13 RIH w/ 150jts 2-7/8 J55 6.5# tbg. EO	tions. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co $36-5140$ , 2SPF, 40 holes. Pumped 500 gal $1/40,278$ gals gel, 21,073# 20/40 white sand $1/40,278$ gals	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid.
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488 10/10/13 Acidize w/6000 gals 20% acid. Frac w 10/27/13 RIH w/ 150jts 2-7/8 J55 6.5# tbg. EO	tions. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co $36-5140$ , 2SPF, 40 holes. Pumped 500 gal $1/40,278$ gals gel, 21,073# 20/40 white sand $1/40,278$ gals	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid.
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488 10/10/13 Acidize w/6000 gals 20% acid. Frac w 10/27/13 RIH w/ 150jts 2-7/8 J55 6.5# tbg. EO	tions. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co $36-5140$ , 2SPF, 40 holes. Pumped 500 gal $1/40,278$ gals gel, 21,073# 20/40 white sand $1/40,278$ gals	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid.
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488 10/10/13 Acidize w/6000 gals 20% acid. Frac w 10/27/13 RIH w/ 150jts 2-7/8 J55 6.5# tbg. EO	tions. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co $36-5140$ , 2SPF, 40 holes. Pumped 500 gal $1/40,278$ gals gel, 21,073# 20/40 white sand $1/40,278$ gals	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid.
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488 10/10/13 Acidize w/6000 gals 20% acid. Frac w 10/27/13 RIH w/ 150jts 2-7/8 J55 6.5# tbg. EO	tions. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co $36-5140$ , 2SPF, 40 holes. Pumped 500 gal $1/40,278$ gals gel, 21,073# 20/40 white sand $1/40,278$ gals	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid.
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488 10/10/13 Acidize w/6000 gals 20% acid. Frac w 10/27/13 RIH w/ 150jts 2-7/8 J55 6.5# tbg. EOT 10/28/13 RIH w/ 2-1/2x2x20' trash pump. Hang	tions. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co 36 – 5140, 2SPF, 40 holes. Pumped 500 gal 1/40,278 gals gel, 21,073# 20/40 white sand Γ @ 4910.	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid.
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488 10/10/13 Acidize w/6000 gals 20% acid. Frac w 10/27/13 RIH w/ 150jts 2-7/8 J55 6.5# tbg. EO	tions. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co $36-5140$ , 2SPF, 40 holes. Pumped 500 gal $1/40,278$ gals gel, 21,073# 20/40 white sand $1/40,278$ gals	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid.
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488 10/10/13 Acidize w/6000 gals 20% acid. Frac w 10/27/13 RIH w/ 150jts 2-7/8 J55 6.5# tbg. EOT 10/28/13 RIH w/ 2-1/2x2x20' trash pump. Hang	tions. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co 36 – 5140, 2SPF, 40 holes. Pumped 500 gal 1/40,278 gals gel, 21,073# 20/40 white sand Γ @ 4910.	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid.
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488 10/10/13 Acidize w/6000 gals 20% acid. Frac w 10/27/13 RIH w/ 150jts 2-7/8 J55 6.5# tbg. EO 10/28/13 RIH w/ 2-1/2x2x20' trash pump. Hang	tions. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co 36 – 5140, 2SPF, 40 holes. Pumped 500 gal 1/40,278 gals gel, 21,073# 20/40 white sand \$\Gamma\$ @ 4910.  g on.  Rig Release Date:	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid. d. Circ clean.
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488 10/10/13 Acidize w/6000 gals 20% acid. Frac w 10/27/13 RIH w/ 150jts 2-7/8 J55 6.5# tbg. EOT 10/28/13 RIH w/ 2-1/2x2x20' trash pump. Hang	tions. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co 36 – 5140, 2SPF, 40 holes. Pumped 500 gal 1/40,278 gals gel, 21,073# 20/40 white sand \$\Gamma\$ @ 4910.  g on.  Rig Release Date:	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid. d. Circ clean.
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488 10/10/13 Acidize w/6000 gals 20% acid. Frac w 10/27/13 RIH w/ 150jts 2-7/8 J55 6.5# tbg. EO 10/28/13 RIH w/ 2-1/2x2x20' trash pump. Hang	tions. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co 36 – 5140, 2SPF, 40 holes. Pumped 500 gal 1/2 40,278 gals gel, 21,073# 20/40 white sand Γ @ 4910.  Rig Release Date:	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid. d. Circ clean.
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488 10/10/13 Acidize w/6000 gals 20% acid. Frac w 10/27/13 RIH w/ 150jts 2-7/8 J55 6.5# tbg. EO 10/28/13 RIH w/ 2-1/2x2x20' trash pump. Hang	tions. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co 36 – 5140, 2SPF, 40 holes. Pumped 500 gal 1/40,278 gals gel, 21,073# 20/40 white sand \$\Gamma\$ @ 4910.  g on.  Rig Release Date:	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid. d. Circ clean.
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488 10/10/13 Acidize w/6000 gals 20% acid. Frac w 10/27/13 RIH w/ 150jts 2-7/8 J55 6.5# tbg. EO 10/28/13 RIH w/ 2-1/2x2x20' trash pump. Hang	RULE 19.15.7.14 NMAC. For Multiple Co  RULE 19.15.7.14 NMAC. For Multiple Co  ROULE 20.00 gal  Roule 21,073# 20/40 white sand  Good 4910.  Rig Release Date:  Rig Release Date:  TITLE Lead Regulatory Analysis	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid. d. Circ clean.  The control of the control
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488 10/10/13 Acidize w/6000 gals 20% acid. Frac w 10/27/13 RIH w/ 150jts 2-7/8 J55 6.5# tbg. EO 10/28/13 RIH w/ 2-1/2x2x20' trash pump. Hang	tions. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co 36 – 5140, 2SPF, 40 holes. Pumped 500 gal 1/2 40,278 gals gel, 21,073# 20/40 white sand Γ @ 4910.  Rig Release Date:	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid. d. Circ clean.  ge and belief.  DATE 11/14/13
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488 10/10/13 Acidize w/6000 gals 20% acid. Frac w 10/27/13 RIH w/ 150jts 2-7/8 J55 6.5# tbg. EO 10/28/13 RIH w/ 2-1/2x2x20' trash pump. Hang	RULE 19.15.7.14 NMAC. For Multiple Co  36 – 5140, 2SPF, 40 holes. Pumped 500 gal  1/ 40,278 gals gel, 21,073# 20/40 white sand  1/ @ 4910.  30 on.  Rig Release Date:  1/ Lead Regulatory Anal  1/ E-mail address:kcastillo@concho.	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid. d. Circ clean.  ge and belief.  Hyst DATE 11/14/13  Lean PHONE: 432-685-4332
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488 10/10/13 Acidize w/6000 gals 20% acid. Frac w 10/27/13 RIH w/ 150jts 2-7/8 J55 6.5# tbg. EO 10/28/13 RIH w/ 2-1/2x2x20' trash pump. Hans  Spud Date:  I hereby certify that the information above is true SIGNATURE  Type or print name Kanicia Castillo  For State Use Only	RULE 19.15.7.14 NMAC. For Multiple Co  36 – 5140, 2SPF, 40 holes. Pumped 500 gal  1/ 40,278 gals gel, 21,073# 20/40 white sand  1/ @ 4910.  2/ gon.  Rig Release Date:  1/ Lead Regulatory Anal  1/ E-mail address:kcastillo@concho.    Petroleum Engineer	de give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid. d. Circ clean.  de and belief.    Lyst
OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion.  10/09/13 Set plug @ 6420. Perf San Andres 488 10/10/13 Acidize w/6000 gals 20% acid. Frac w 10/27/13 RIH w/ 150jts 2-7/8 J55 6.5# tbg. EO 10/28/13 RIH w/ 2-1/2x2x20' trash pump. Hang	RULE 19.15.7.14 NMAC. For Multiple Co  36 – 5140, 2SPF, 40 holes. Pumped 500 gal  1/ 40,278 gals gel, 21,073# 20/40 white sand  1/ @ 4910.  30 on.  Rig Release Date:  1/ Lead Regulatory Anal  1/ E-mail address:kcastillo@concho.	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of s 20% acid. d. Circ clean.  ge and belief.  Hyst DATE 11/14/13  Lean PHONE: 432-685-4332