

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised July 18, 2013

WELL API NO. 30-025-03194	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. E7262	
7. Lease Name or Unit Agreement Name Northeast Pearl Queen Unit	
8. Well Number 015	
9. OGRID Number 243874	
10. Pool name or Wildcat Pearl; Queen	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3776' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
DOWNHOLE COMMINGLE <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>
CLOSED-LOOP SYSTEM <input type="checkbox"/>	OTHER: <input type="checkbox"/>
OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

11/15/13 MIRU plugging equipment.

11/18/13 Dig out cellar. ND wellhead. NU BOP. RIH w/ tbg and tag @ 4748'. Spotted 25 sx cement @ 4748-4500. Pull out of cement. WOC.

11/19/13 Tagged plug @ 4390'. POH. Perf'd 4 1/2 csg @ 3250'. Set 4 1/2 packer @ 2950'. Sqz'd 25 sx cement w/ 2 % CACL @ 3250-3150. WOC. NO TAG. Re-Sqz'd 40 sx cement @ 3250-3150. WOC.

11/20/13 Tagged plug @ 3143'. POH. Perf'd csg @ 1900'. Set packer @ 1550'. Sqz'd 30 sx cement @ 1900-1750. WOC. Tagged plug @ 1758'. Perf'd csg @ 380'. Set packer @ 63'. Sqz'd 130 sx cement @ 380 to surface. WOC.

11/21/13 Tagged plug @ 162'. Set packer @ 63'. Injection rate of 2 bbls/min @ 50 psi. Pull packer. RIH to 163'. Spotted 10 sx cement @ 163. POH. Set packer @ 63'. Sqz'd 30 sx cement to surface. ND BOP. RDMO.

Moved in backhoe and welder. cut off wellhead. Verified cement at surface. Welded on Above Ground Dry Hole Marker. Backfilled cellar. removed deadmen. Cleaned location. Moved off.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Celeste G. Dale TITLE Sr. Regulatory Analyst DATE 11/25/13

Type or print name Celeste G. Dale E-mail address: cdale@qracq.com PHONE: 432-683-1500

For State Use Only

APPROVED BY: Mark W. Finken TITLE Compliance Officer DATE 11-26-2013

Conditions of Approval (if any):

DEC 02 2013