State of New Mexico Energy, Minerals and Natural Resources Department

Revised 5-27-2004 HOBBS OF CONSERVATION DIVISION FILE IN TRIPLICATE WELL API NO. 1220 South St. Francis Dr. DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 30-025-31422 DEC 1 6 2013 Santa Fe, NM 87505 5. Indicate Type of Lease DISTRICT II STATE X FEE 1301 W. Grand Ave, Artesia, NM 88210 6. State Oil & Gas Lease No. DISTRICT III RECEIVED 1000 Rio Brazos Rd, Aztec, NM 87410 7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A South Hobbs (G/SA) Uni DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.) 8. Well No. 1. Type of Well: 233 Oil Well Gas Well Other Injector 9. OGRID No. 157984 2. Name of Operator Occidental Permian Ltd. 10. Pool name or Wildcat 3. Address of Operator Hobbs (G/SA) HCR 1 Box 90 Denver City, TX 79323 4. Well Location Feet From The Line Unit Letter G 2245 Feet From The North Line and 2420 East **NMPM** County Township 19-S Range 38-E Section Lea 11. Elevation (Show whether DF, RKB, RT GR, etc.) 3631' DF Pit or Below-grade Tank Application or Closure Distance from nearest fresh water well ______ Distance from nearest surface water Pit Type Depth of Ground Water Below-Grade Tank: Volume ______ bbls; Construction Material Pit Liner Thickness Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 12. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PERFORM REMEDIAL WORK TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. **PLUG & ABANDONMENT** CASING TEST AND CEMENT JOB PULL OR ALTER CASING Multiple Completion OTHER: OTHER: Coiled tubing job 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. RU coiled tubing unit. 1. RIH & clean out to 4222'. Pull up to 4080'. Ran perf clean tool and water wash perfs from 4086-4222'. 2. 3. Pumped 10 bbl gel sweep. Wash perfs from 4086-4222' w/2500 gal of 15% NEFE acid. 4. Pumped 10 bbl gel sweep. 5. POOH & RD coiled tubing unit. 6. Return well to injection. RU 12/04/2013 RD 12/04/2013 I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan SIGNATURE TITLE DATE Administrative Associate 12/13/2013 TYPE OR PRINT NAME mendy_johnson@oxy.com TELEPHONE NO Johnson 806-592-6280 Mendy A E-mail address: For State Use Only APPROVED BY CONDITIONS OF APPROVAL IF ANY:

Form C-103