Submit 1 Copy To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505			Form C-103 Révised August 1, 2011
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	Revised August 1, 2011
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210			30-025-03236 5 . Indicate Type	of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410			STATE	FEE XX
District IV = (505) 476-3460			6. State Oil & Ga	as Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name o	r Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			East Pearl Queen	Unit /
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Injection Well		8. Well Number	23	
Name of Operator State of New Mexico formerly Xeric Oil & Gas Corp			9. OGRID Numb 25482	per /
3. Address of Operator		10. Pool name or	· Wildcat	
- 1625 N French Drive Hobbs, NM 88240		Pearl Queen		
4. Well Location				
Unit LetterG:_	1980feet from theN	line and198	80feet from the	neEline /
Section 28 Township T19S Range 35E NMPM Lea County				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORLD			_	ALTERING CASING
TEMPORARILY ABANDON				P AND A XX
DOWNHOLE COMMINGLE				
_	_			
OTHER:	lated exerctions. (Clearly state all s	OTHER:	HOBBS OCD	an including actimated data
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Auach wellbore diagram of proposed completion or recompletion.				
12/23/2013 Moved in rigged up. 1	Dug out cellar and plumbed to pit.		RECEIVED	
12/26/2013 Installed BOP and worked packer loose.				
12/27/2013 POOH with packer and RIH to 4511' and tagged fill. Circulated hole with MLF and spotted 35 sx cement at 4511'.				
12/30/2013 RIH and tagged cement at 4302' POOH to 3390' and spotted 25 sx cement. POOH and perforated at 1800'. RIH with				
packer to squeeze perfs. Would not circulate and pressured up to 550#. Released packer and spotted cement across perfs from 1867'.				
WOC and tagged at 1481'. POOH and perforated at 200'. Rigged up on 4 1/2" casing and tried to circulated. Pressured up to 500#.				
12/31/2013_RIH to 250' and circulated cement to surface. Rigged down cut off wellhead and installed marker. Cut off anchors.				
12/3/1/2011 to 230 and enear	ated coment to surface. Rigged dow	vii cut on weimead i	and mataned marke	r. Cut off anchors.
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE	TITLE		D	ATE
			_	
Type or print name	E-mail address	S: ·	PF	HONE:
For State Use Only		کھے۔'ا	\mathcal{T}	TE 01/03/2014
APPROVED BY: Warble	Kitchen TITLE CO	mphanes G	Hicer DA	TE 01/03/2014
Conditions of Approval (if any):		1		_, /

DEC 0 6 2014 7