OCD Hobbs

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB NO. 1004-0135

HOBRE A	Expires: Jul
	ے. Lease Serial No.
	C/NMNM19859

ANDO	6.	If Indian,	Allottee	or T	ribe	Nan

abandoned wel	I. Use form 3160-3 (APD) for suc	ch proposals.	N 08 2014	If Indian, Allottee or Ti	ribe Name			
SUBMIT IN TRII	PLICATE - Other instructions on	reverse side	7. 1	If Unit or CA/Agreeme	nt, Name and/or No.			
1. Type of Well ☐ Other /				8. Well Name and No. TRISTE DRAW 3 FED 02				
2. Name of Operator	Contact: STAN WADRATEDE-Mail: stan_wagner@eogres	AGNER sources.com		9. API Well No. 30-025-34585-00-S1				
3a. Address	e No. (include area code) 2-686-3689		10. Field and Pool, or Exploratory JOHNSON RANCH					
MIDLAND, TX 79702					,			
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description)		11.	11. County or Parish, and State				
Sec 3 T25S R33E SENW 2310FNL 1980FWL				LEA COUNTY, NM				
12. CHECK APPR	ROPRIATE BOX(ES) TO INDICA	ATE NATURE OF N	OTICE, REPO	RT, OR OTHER I	DATA			
TYPE OF SUBMISSION		TYPE OF ACTION						
☐ Notice of Intent	☐ Acidize ☐	Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off			
_	☐ Alter Casing ☐	Fracture Treat	□ Reclamation	ſ	☐ Well Integrity			
Subsequent Report	☐ Casing Repair ☐	New Construction	☐ Recomplete	t	☐ Other			
☐ Final Abandonment Notice	_ = =	Plug and Abandon	□ Temporarily	Abandon				
	☐ Convert to Injection ☐	Plug Back	☐ Water Dispo	sal				
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple complete completion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 10/10/13 MIRU to P&A. 10/11/13 RIH to top of sandline fish at 12942'. Set 2-7/8" CIBP at 12942'. 10/12/13 Dump bail 2.25 sx Class H cement on CIBP. 10/15/13 RIH and tag cement at 12842'. Tag witnessed by BLM. RIH and set CIBP at 12842'. 10/25/13 RIH and jet cut tubing at 11495. Back off tubing at 7642'. POOH w/tubing to 7632'. Screw into tubing fish at 7642'. Perforate at 8618'. Attempt to circulate. 10/27/13 RIH and perforate at 8428'. Circulate out heavy mud. 10/28/13 Work tubing. Back off tubing at 8622'. Trip out with back off tubing. RIH and screw onto fish at 8622'.								
14. I hereby certify that the foregoing is true and correct. Electronic Submission #228594 verified by the BLM Well Information System For EOG RESOURCES INCORPORATED, sent to the Hobbs Committed to AFMSS for processing by JOHNNY DICKERSON on 12/05/2013 (13KCD0142S)								
Name (Printed/Typed) STAN WA	Title REGULA	Title REGULATORY ANALYST						
Signature (Electronic S	Submission)	Date 12/04/20	Date 12/04/2013					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
_Approved_By_ACCEPTED		(BLM Appro	(BLM Approver Not Specified) Title Date		Date 01/02/2014			
certify that the applicant holds legal or equ which would entitle the applicant to condu		office Hobbs						
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.								

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** MSB/OCD 1/9/2014



Additional data for EC transaction #228594 that would not fit on the form

32. Additional remarks, continued

10/29/13 RIH and perforate at 9506'. Attempt to circulate.

10/30/13 Continue attempt to circulate.

10/30/13 Continue attempt to circulate.
10/31/13 RIH and perforate at 9188'. Attempt to circulate.
11/01/13 Work tubing. Back off at 9292'. POOH. RIH and screw onto fish at 9292'.
11/05/13 Work stuck tubing. Parted tubing. POOH.
11/06/13 Prep to POOH w/ parted 2-7/8" tubing. RIH w/ jet cutter and cut tubing at 9599'. RIH w/ chemical cutter to 9281'. Cut tubing. POOH and lay down cut tubing.
11/08/13 Wash over tubing at 9281'. RIH w/ power swivel. Rotate over fish at 9281'. Work tubing.
11/16/13 Attempted to pump cement to fill cavity of 2-7/8" tubing left in hole. Unsuccessful.
Consult with BLM. Received permission to set CIBP at 9599'.
11/19/13 RIH and tag tubing stub at 9599'. Set CIBP at 9598'.
11/20/13 RIH and tag CIBP at 9598'. Then pumped 43 sx Class H cement plug.
11/21/13 RIH and tag cement plug at 9168'. Tag witnessed by BLM. POOH to 7600'. Pump 6.35 bbls Class H cement, 23 bbls mud, 6.35 bbls Class H cement, 35 bbls mud. POOH to 5160'. Pump 30 sx Class C cement, POOH to 4934'. WOC.
RIH and tag plug at 4991'. POOH to 4128'. Pump additional 20 sx Class C cement to bring plug up to 4789'.

11/22/13 RIH and perforate at 4329'. RIH and set CICR at 2625'. Pump 820 sx Class C and 60 sx Class

11/26/13 RIH and tag cement at 2578'. Pumped 60 bbls mud. POOH to 1208'.
11/27/13 Pump 50 sx Class C cement to 2578'. POOH to 747'. Pump 80 sx Class C cement to surface. POOH, lay down workstring and back fill casing w/ cement. 12/02/13 Cut off wellhead, weld on P&A marker. Clean location.

Well is P&A.