State of New Mexico Energy, Minerals and Natural Resources Department

						Revised 5-27-200)4	
FILE IN TRIPLICATE OIL	CONSERVA	TION DIV	VISION					
DISTRICT I HOBBS OCD				WELL API NO.				
1625 N. French Dr., Hobbs, NM 88240		NM 87505		30-025	-07600			
DISTRICT II IAN 28 2014				5. Indicate Type	of Lease		-	
DISTRICT II 1301 W. Grand Ave, Artesia, NM 88210N 2 8 2014 DISTRICT III				ST.	ATE	FEE X		
<u>District m</u>				6. State Oil & G	as Lease No.			
1000 Rio Brazos Rd, Aztec, NM 87410 RECEIVED								
SUNDRY NOTICES AND REPORTS ON WELLS					7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL DIFFERENT RESERVOIR. USE "APPLICATION FOR PI				South Hobbs	(G/SA) Unit	/		
1. Type of Well:					8. Well No. 33			
Oil Well Gas Well	Other Inje	ctor						
2. Name of Operator				9. OGRID No.	157984)		
Occidental Permian Ltd.								
3. Address of Operator				10. Pool name c	r Wildcat	Hobbs (G/SA	.)	
HCR I Box 90 Denver City, TX 79323 4. Well Location								
	Maath I	ine and 16	5 0 Feet	From The	West	Line	,	
Unit Letter <u>G</u> : <u>2310</u> Feet From The	North L		550 Feet		West	Line		
Section 4 Township	• • •	Ran	ge 38-E	NMPN	A	Lea Coun	ty 🗸	
11. Elevation (She 3623 KB	ow whether DF, RKB	3, RT GR, etc.)						
Pit or Below-grade Tank Application or Closure								
Pit Type Depth of Ground Water		arect frech wat	er well	Distance fr	om neorest sur	face water		
					in neurest sui	luce water		
Pit Liner Thickness mil Below-Grade Tan	k. volume	0018, C0		citat				
12. Check Appropriate Box	to Indicate Natu	are of Notice.	, Report, or O	ther Data				
NOTICE OF INTENTION TO:				EQUENT R	EPORT OF	:		
		REMEDIAL W	ORK	[]·	ALTERING	CASING		
TEMPORARILY ABANDON CHANGE PLANS		COMMENCE	DRILLING OPN	is.	PLUG & AB	BANDONMENT		
PULL OR ALTER CASING Multiple Completic			T AND CEMEN				L	
OTHER:		OTHER: (Coiled tubing	ioh			X	
	<u> </u>		*					
13. Describe Proposed or Completed Operations (Clearly sta proposed work) SEE RULE 1103. For Multiple Compl						arting any		
1. RU coiled tubing unit.								
2. RIH & clean out to 4205'. Pull up to 4190'. R	an perf clean tool	and water wa	ash perfs @412	28-4190'.				
3. Wash perfs from 4128-4190' w/2500 gal of 159	% NEFE acid.							

- Pump 10 bbl gel sweep. Circulate clean w/12 bbl brine.
 POOH and RD coiled tubing unit.
- 6. Return well to injection.

RU 01/15/2014 RD 01/15/2014

I hereby certify that the information above is true and con constructed or	plete to the best of my knowle	edge and belief. I further certify that any p	bit or below-grade tank has	been/will be
closed according to NMOCD guidelines	, a general permit	or an (attached) alternative OCD-a	pproved	
	All and	plan		
SIGNATURE	> nom	TITLE Administrative Associa	te DATE	01/24/2014
TYPE OR PRINT NAME Mendy A. Johnson	E-mail address:	mendy_johnson@oxy.com	TELEPHONE NO.	806-592-6280
For State Use Only M I A R		1	$\overline{01}$	11 - 1- 1
APPROVED BYAPPROVED BYAPPROVED BYAPPROVED BY	wn	_ TITLE COMPLIANCE	Here DATE	1/28/2014
CONDITIONS OF APPROVAL IF ANY		1	00	, ,
, i i i i i i i i i i i i i i i i i i i				
			JAN 29	2014
			JAN	

Form C-103