Submit 1 Copy To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources	Form C-103 Revised July 18, 2013
<u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Willerais and Natural Resources	WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30 - 025 - 03213 5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE X
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTI	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	East Pearl Queen Unit
	Gas Well Other	8. Well Number 30
2. Name of Operator State of NM former:	ly Xeric Oil & Gas Corp.	9. OGRID Number
3. Address of Operator		10. Pool name or Wildcat
1625 N French Drive	e Hobbs, NM 88240	Pearl Queen
4. Well Location Unit Letter I: 1980 feet from the South line and 660 feet from the East line		
Section 27 Township 19S Range 35E NMPM County Lea		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF IN	ITENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING A		
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☑ PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMENT JOB ☐		
DOWNHOLE COMMINGLE	_	_
CLOSED-LOOP SYSTEM OTHER:	□ OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
	•	den GIU and bar at ACEO.
5-18-13 MIRU Basic Plugging Services. POOH w/ tbg. GIH and tag at 4652'. Circ hole w/ mud laden fluid. Spot 25 sx cmt at 4652'. WOC.		
5-20-13 Tag at 4475'. POOH to 3393'. Spot 25 sx cmt. Perf at 1800'.		
Sqz w/ 25 sx cmt. WOC.		
5-21-13 Tag at 1653'. Perf at 358'. Circ 100 sx cmt to surface inside/		
outside 5 1/2" csg. RDMO. Install dry hole marker.		

Spud Date:	Rig Release Date:	
Noncolate display		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		
SIGNATURE Wash Whitalam TITLE Compliance Officer DATE 02/13/2014		
Type or print name E-mail address: PHONE:		
APPROVED BY: Alexy Stown TITLE Compliance Office DATE 2/14/2014 Conditions of Approval (if any): FED. # 0. 7017		
De Service (11 mil).		
		FEB 18 2014 6 6