Submit 3 Copies To Appropriate District Office 4	State of New Mexico     Energy, Minerals and Natural Resources		Form C-103 October 25, 2005	
<u>District I</u> 1625 N. French Dr.,Hobbs, NM 88240			WELL API NO. 30-025-05893	
District II 1301 W. Grand Ave., Artesia, NM SEATORS OCD OIL CONSERVATION DIVISION		5. Indicate Type of Lease		
Disrtict III			FEE 🔽	
1000 Rio Brazos Rd. Aztec, NM 874101220 South St. Francis Dr.District IVMAR 0 6 20141220 S. St. Francis Dr., Santa Fe, NM			6. State Oil & Gas Lease No.	
SUNDRY NOT REPORTS ON WELLS			7. Lease Name or Unit Agr	eement Name /
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				
PROPOSALS.) 1. Type of Well: Oil Well  Gas Well  Other			8. Well Number 2201	
2. Name of Operator			9. OGRID Number	/
Apache Corporation			873 10. Pool Name	
3. Address of Operator 303 Veterans Airpark Ln., Ste. 3000, Midland, TX, 79705			Eunice Monument: G/SA	
4. Well Location				_ /
Unit Letter <b>A</b> : Section <b>4</b> To	330 feet from the ownship 20S R	N line and ange 37E	990 feet from the NMPM Co	E line
	vation (Show whether DF			
	36	54' GR		
12. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data				
TEMPORARILY ABANDON	ND ABANDON	EMEDIAL WORK OMMENCE DRILLING OP ASING/CEMENT JOB	SUBSEQUENT REPO	
OTHER:		✓ Location is re	eady for OCD inspection after	P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.				
<ul> <li>Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.</li> <li>A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the</li> </ul>				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER / QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and				
<ul> <li>other production equipment.</li> <li>Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.</li> <li>If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed</li> </ul>				
from the lease and well location.  All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.)				
<ul> <li>All other environmental concrens have been addressed as per OCD rules.</li> <li>Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.</li> </ul>				
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.				
SIGNATURE Con Jollis	TITLE	P&A Tech	DATE	3/3/14
TYPE OR PRINT NAME Leon Selle		leon.sellers@apache	corp.com PHONE:	432-208-0349
APPROVED BY: Wahleht	In_TITLE	omptionce O	Ficer DATE 0	3/11/2014
Conditions of Approval (if any):				•

MAR 1 2 2014

t. De