## State of New Mexico HOBBS OCE nergy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE  7 2014 OIL CONSERVATION DIVISION	Revised 3-27-2004
DISTRICT 1 1625 N. French Dr., Hobbs, NM 88240 1 Santa Fe, NM 87505	WELL API NO. 30-025-07375
DISTRICT II	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210RECEIVED	STATE FEE X
<u>DISTRICT III</u>	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410  SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 20
1. Type of Well:	8. Well No. [[]
Oil Well X Gas Well Other  2. Name of Operator	9. OGRID No. 157984
Occidental Permian Ltd.	2.000010. 137764
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323  4. Well Location	
	et From The West Line
	***************************************
Section 20 Township 18-S Range 38-I	E NMPM Lea County
3660.8 GL	
Bis D. Land T. Ltd. S. C. C. C.	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Ma	iterial
12. Check Appropriate Box to Indicate Nature of Notice, Report, or C	Other Data
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	BOL TV
OTHER: OTHER: Return to pro	oduction/OAP/AT
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates	
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed	
1. RUPU & RU.	
<ol> <li>ND wellhead/NUBOP.</li> <li>RIH w/bit. Tag @3977'. Pooh w/bit.</li> </ol>	
4. RIH w/RBP set @624'. Dump 2 sacks of sand on top of RBP.	
5. ND BOP/NU wellhead.	
6. RDPU & RU. – wellhead change 10/21/2013	
7. RUPU & RU. 8. NU wellhead/NU BOP.	
9. Wash sand off of RPB @614' and POOH.	
10. RIH w/cone buster mill. Tag @4120'. RU power swivel and drill cement to CIBP @4192	Push plug to 4271'. RD power swivel. POOH
w/ cone buster mill.	,
****see attached sheet for addition	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or	that any pit or below-grade tank has been/will be
closed according to NMOCD guidelines , a general permit or an (attached) alternative	e OCD-approved
plan	
SIGNATURE TITLE Administrative	
TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy johnson@oxy.com	TELEPHONE NO. 806-592-6280
For State Use Only  Petrol	
1000	enam Hnommeer .MAD st. o.00
APPROVED BY TITLE	eum Engineer DATE MAR 18 20

## NHU 20-111 API 30-025-07375

- 11. RU wire line and perforate well @4192-4217' and 4181-83' at 4 JSPF. RD wire line.
- 12. RIH w/treating packer set @4050'. RU Rising Star and pump 2000 gal of 15% PAD acid over perfs. Flush w/25 bbl 10# brine. Pump scale squeeze of 100 gal of 6490 chemical mixed in 100 bbl fresh water. Flush w/200 bbl fresh water. RD Rising star. POOH w/treating packer.
- 13. RIH w/ESP equipment on 116 jts of 2-3/8" tubing. Intake set @3875'
- 14. ND BOP/NU wellhead.
- 15. RDPU & RU. Clean location and return well to production.

RUPU 10/18/2013 RDPU 10/21/2013 - wellhead change

RUPU 11/21/2013 RDPU 12/10/2013

Had to rig back up on 12/11/2013 to turn tubing one half of a turn for surface equipment hookup.