Submit 1 Copy To Appropriate District Office State of New Mexi	
Office District I - (575) 393-6161  HOBBS Officegy, Minerals and Natural Resources Revised August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 MAR 2 7 2014 CONSERVATION D	IVISION 300-025-30870
District III - (505) 334-6178 1220 South St. Franci	s Dr
District IV - (505) 476-3460 Santa Fe, NM 8750	STATE X FEE   6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM RECEIVED 87505	or our of this house 140.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG	BACK TO A 1/
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.)	V I Red Cloud
Type of the Ell cas went it care.	8. Well Number 002
2. Name of Operator	9. OGRID Number
McDonnold Operating, Inc.  3. Address of Operator  MAR	2 7 2014 14372  10. Pool name or Wildcat
505 N. Big Spring, Suite 204, Midland TX 79701	Jalmat Tansil Yates 7 Rivers (GAS)
4. Well Location RECEIVED	
( ) nit Letter M : 660 feet from the South line and 660 feet from the West line	
Section 3 Township 25S Rar	ge 37E NMPM Lea County
11. Elevation (Show whether DR, RI	(B, RT, GR, etc.)
12. Check Appropriate Box to Indicate Natu	ura of Notice Demont on Other Dete
12. Check Appropriate Box to indicate Nati	ire of Notice, Report of Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
	EMEDIAL WORK
_	OMMENCE DRILLING OPNS. □ P AND A X
PULL OR ALTER CASING  MULTIPLE COMPL  C DOWNHOLE COMMINGLE	ASING/CEMENT JOB
DOWN TOLE GOTTINITOLE	
	THER:
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
8/18/2011 Move in rig up and spot equipment on location.	
8/19/2011 Install BOP. POH with tubing and tally. RIH to 2709' and spot 25 sx class C Cement.	
8/22/2011 RIH and tag at 2502'. Tag high enough as per Hobbs OCD. Circulated hole with brine and mud. Shut casing valve and tested easing. Held 425 psi for 15 minutes. Laid down tubing to 1322' and spotted 25 sx class C cement. WOC and tag at 982'. POH to	
423' and circulate cement to surface with 30 sx class C. POH and SION.	
8/23/2011 Rig down. Cut off anchors, remove wellhead, and install marker.	
:	
I hereby certify that the information above is true and complete to the best	of my knowledge and belief.
-	
SIGNATURE (M. Mc.) AND AND E-mail address:  PHONE: 433-683-3499	
Type or print name Wals M. McDanold E-mail address: PHONE: 433-682-3469	
APPROVED BY: Majur Stown TITLE COmpliance Office DATE 3/27/2014	
Conditions of Approval (if any): Line original ask for Copy.	
unable to find oughter and for copy.	
U U	— Λ'4τΩ