
Form 3160-5 (August 2007) DEP	UNITED STATES PARTMENT OF THE R	3	Hobbs	0	ORM APPROVED MB No. 1004-0137 xpires: July 31, 2010
BUR	EAU OF LAND MANA	AGEMENT HOBBS		5. Lease Serial No. LC-069052	
	IOTICES AND REPO	RTS ON WELLS		6. If Indian, Allottee o	r Tribe Name
Do not use this f abandoned well.	orm for proposals to Use Form 3160-3 (AF	o drill or to re-enter an PD) for such proposa	s2014		
	r IN TRIPLICATE ~ Other i	nstructions on page 2.	7873		ement, Name and/or No.
1. Type of Well Oil Well Gas W	Vell Veller INJE			8. Well Name and No.	
2. Name of Operator CHAPARRAL ENERGY, LLC				9. API Well No. 30-025-30355	1
701 CEDAR LAKE BLVD OKLAHOMA CITY, OK 73114		3b. Phone No. (include area con 405-478-8770	clude area code) 10. Field and Pool or Exploratory Area DOLLARHIDE QUEEN		
4. Location of Well (Footage, Sec., T., R., M., or Starvey Description) 400 FNL & 1120 FWL, UNIT D, SECTION 31-T24S-R38E			·	11. Country or Parish, State LEA COUNTY, NM	
12 CHEC	K THE APPROPRIATE BOX	(ES) TO INDICATE NATURE			ЕР ПАТА
TYPE OF SUBMISSION			PE OF ACT		
	Acidize	Deepen		uction (Start/Resume)	Water Shut-Off
✓ Notice of Intent	Alter Casing	Fracture Treat		amation	Well Integrity
Subsequent Report	Casing Repair	New Construction	Reco	unplete	Other REPAIR TBG LEA
Final Abandonment Notice	Change Plans	Plug and Abandon Plug Back		porarily Abandon er Dísposal	
Attach the Bond under which the w following completion of the involve testing has been completed. Final A determined that the site is ready for	ork will be performed or prov ed operations. If the operation Abandonment Notices must be final inspection.)	r results in a multiple completio filed only after all requirement	LM/BIA. F n or recomp s, including	Required subsequent rep letion in a new interval.	orts must be filed within 30 days a Form 3160-4 must be filed once
Attach the Bond under which the w following completion of the involve testing has been completed. Final <i>A</i> determined that the site is ready for 1. PREPARE LOCATION. RIG UP V 2. RELEASE PACKER AND TOOH V 3. TH W/BIT TO CHECK PB&D TES 4. TOOH W/BIT. 5. TIH W/PKR INJECTION TBG. 6. ATTEMPT TO SET PACKER 20' H 7. CONDUCT MECHANICAL INTEG 8. RDMO WORKOVER RIG. 9. PLACE WELL ON ACTIVE INJEC 10. SUBMIT REPORT	ork will be performed or prov ed operations. If the operation Abandonment Notices must be final inspection.) VORKOVER RIG. NIPPLE W/TBG & PKR. STING TBG. CLEAN OUT F DEEPER SO PACKER WIL SRITY TEST.	ide the Bond No. on file with B a results in a multiple completio filed only after all requirement UP BOP & ENVIRONMENT/ PERFS IF NECESSARY.	LM/BIA. F n or recomp s, including AL PAN.	Required subsequent rep letion in a new interval, reclamation, have been	orts must be filed within 30 days , a Form 3160-4 must be filed once completed and the operator has INULUS W/PACKER FLUID.
Attach the Bond under which the w following completion of the involve testing has been completed. Final A determined that the site is ready for 1. PREPARE LOCATION. RIG UP V 2. RELEASE PACKER AND TOOH V 3. TH W/BIT TO CHECK PB&D TES 4. TOOH W/BIT. 5. TIH W/PKR INJECTION TBG. 6. ATTEMPT TO SET PACKER 20' I 7. CONDUCT MECHANICAL INTEG 8. RDMO WORKOVER RIG. 9. PLACE WELL ON ACTIVE INJEC	ork will be performed or prov ed operations. If the operation Abandonment Notices must be final inspection.) VORKOVER RIG. NIPPLE W/TBG & PKR. STING TBG. CLEAN OUT F DEEPER SO PACKER WIL SRITY TEST. STION	ide the Bond No. on file with B a results in a multiple completio filed only after all requirement UP BOP & ENVIRONMENT/ PERFS IF NECESSARY.	LM/BIA. F n or recomp s, including AL PAN.	Required subsequent rep letion in a new interval, reclamation, have been	orts must be filed within 30 days , a Form 3160-4 must be filed once completed and the operator has INULUS W/PACKER FLUID.
Attach the Bond under which the w following completion of the involve testing has been completed. Final A determined that the site is ready for 1. PREPARE LOCATION. RIG UP V 2. RELEASE PACKER AND TOOH V 3. TIH W/BIT TO CHECK PB&D TES 4. TOOH W/BIT. 5. TIH W/PKR INJECTION TBG. 6. ATTEMPT TO SET PACKER 20' I 7. CONDUCT MECHANICAL INTEG 8. RDMO WORKOVER RIG. 9. PLACE WELL ON ACTIVE INJEC 10. SUBMIT REPORT ANTICIPATED START DATE 2-12-2	ork will be performed or prov ed operations. If the operation Abandonment Notices must be final inspection.) VORKOVER RIG. NIPPLE W/TBG & PKR. STING TBG. CLEAN OUT F DEEPER SO PACKER WIL SRITY TEST. STION	ide the Bond No. on file with B a results in a multiple completio filed only after all requirement UP BOP & ENVIRONMENT/ PERFS IF NECESSARY.	LM/BIA. F n or recomp s, including AL PAN.	Required subsequent rep letion in a new interval, reclamation, have been	orts must be filed within 30 days , a Form 3160-4 must be filed once completed and the operator has INULUS W/PACKER FLUID.
Attach the Bond under which the w following completion of the involve testing has been completed. Final <i>A</i> determined that the site is ready for 1. PREPARE LOCATION. RIG UP V 2. RELEASE PACKER AND TOOH V 3. TH W/BIT TO CHECK PB&D TES 4. TOOH W/BIT. 5. TIH W/PKR INJECTION TBG. 6. ATTEMPT TO SET PACKER 20' H 7. CONDUCT MECHANICAL INTEG 8. RDMO WORKOVER RIG. 9. PLACE WELL ON ACTIVE INJEC 10. SUBMIT REPORT ANTICIPATED START DATE 2-12-2 ANTICIPATED COMPLETION DATE	rork will be performed or prov ed operations. If the operation Abandonment Notices must be final inspection.) VORKOVER RIG. NIPPLE W/TBG & PKR. STING TBG. CLEAN OUT F DEEPER SO PACKER WIL SRITY TEST. STION 2014 E 2-18-2014	ide the Bond No. on file with B a results in a multiple completio filed only after all requirement UP BOP & ENVIRONMENT/ PERFS IF NECESSARY.	LM/BIA. F n or recomp s, including AL PAN. PERFORA	Required subsequent repletion in a new interval, reclamation, have been	orts must be filed within 30 days , a Form 3160-4 must be filed once completed and the operator has
Attach the Bond under which the w following completion of the involve testing has been completed. Final A determined that the site is ready for 1. PREPARE LOCATION. RIG UP W 2. RELEASE PACKER AND TOOH V 3. TIH W/BIT TO CHECK PB&D TES 4. TOOH W/BIT. 5. TIH W/PKR INJECTION TBG. 6. ATTEMPT TO SET PACKER 20' H 7. CONDUCT MECHANICAL INTEG 8. RDMO WORKOVER RIG. 9. PLACE WELL ON ACTIVE INJEC 10. SUBMIT REPORT ANTICIPATED START DATE 2-12-2 ANTICIPATED COMPLETION DATE NTICIPATED COMPLETION DATE	rork will be performed or prov ed operations. If the operation Abandonment Notices must be final inspection.) VORKOVER RIG. NIPPLE W/TBG & PKR. STING TBG. CLEAN OUT F DEEPER SO PACKER WIL SRITY TEST. STION 2014 2 2-18-2014 use and correct.	ide the Bond No. on file with B results in a multiple completio filed only after all requirement UP BOP & ENVIRONMENT/ PERFS IF NECESSARY. L BE WITHIN 100' OF TOP Title ENGINE Date 02/06/20	LM/BIA. F n or recomp s, including AL PAN. PERFORA ERING TE	Required subsequent repletion in a new interval, reclamation, have been TION. DISPLACE AN SEE ATTAC CONDITIC	orts must be filed within 30 days , a Form 3160-4 must be filed once completed and the operator has INULUS W/PACKER FLUID.
Attach the Bond under which the w following completion of the involve testing has been completed. Final / determined that the site is ready for 1. PREPARE LOCATION. RIG UP W 2. RELEASE PACKER AND TOOH V 3. TIH W/BIT TO CHECK PB&D TES 4. TOOH W/BIT. 5. TIH W/PKR INJECTION TBG. 6. ATTEMPT TO SET PACKER 20' I 7. CONDUCT MECHANICAL INTEG 8. RDMO WORKOVER RIG. 9. PLACE WELL ON ACTIVE INJEC 10. SUBMIT REPORT ANTICIPATED START DATE 2-12-2 ANTICIPATED START DATE 2-12-2 ANTICIPATED COMPLETION DATE V 14. I hereby certify that the foregoing is transition Signature Signature	rork will be performed or prov ed operations. If the operation Abandonment Notices must be final inspection.) VORKOVER RIG. NIPPLE W/TBG & PKR. STING TBG. CLEAN OUT F DEEPER SO PACKER WIL SRITY TEST. STION 2014 2 2-18-2014 use and correct.	ide the Bond No. on file with B a results in a multiple completio filed only after all requirement UP BOP & ENVIRONMENT/ PERFS IF NECESSARY. L BE WITHIN 100' OF TOP	LM/BIA. F n or recomp s, including AL PAN. PERFORA ERING TE	Required subsequent repletion in a new interval, reclamation, have been TION. DISPLACE AN SEE ATTAC CONDITIC	orts must be filed within 30 days , a Form 3160-4 must be filed once completed and the operator has INULUS W/PACKER FLUID. CHED FOR APPROVAL
Attach the Bond under which the w following completion of the involve testing has been completed. Final / determined that the site is ready for 1. PREPARE LOCATION. RIG UP W 2. RELEASE PACKER AND TOOH V 3. TIH W/BIT TO CHECK PB&D TES 4. TOOH W/BIT. 5. TIH W/PKR INJECTION TBG. 6. ATTEMPT TO SET PACKER 20' I 7. CONDUCT MECHANICAL INTEG 8. RDMO WORKOVER RIG. 9. PLACE WELL ON ACTIVE INJEC 10. SUBMIT REPORT ANTICIPATED START DATE 2-12-2 ANTICIPATED START DATE 2-12-2 ANTICIPATED COMPLETION DATE Name (Printed/Typed) LINDSAY REAMES Signature	rork will be performed or proved operations. If the operation Abandonment Notices must be final inspection.) VORKOVER RIG. NIPPLE W/TBG & PKR. STING TBG. CLEAN OUT F DEEPER SO PACKER WILD SRITY TEST. STION 2014 E 2-18-2014 THIS SPACE F Approval of this notice does not be to those rights in the subject of	ide the Bond No. on file with B results in a multiple completio filed only after all requirement UP BOP & ENVIRONMENT/ PERFS IF NECESSARY. L BE WITHIN 100' OF TOP Title ENGINE Date 02/06/20 OR FEDERAL OR ST/ Title of warrant or certify	LM/BIA. F n or recomp s, including AL PAN. PERFORA ERING TE	Required subsequent repletion in a new interval, reclamation, have been TION. DISPLACE AN SEE ATTAC CONDITIC	orts must be filed within 30 days a Form 3160-4 must be filed once completed and the operator has INULUS W/PACKER FLUID. CHED FOR APPROVAL INS OF APPROVAL
Attach the Bond under which the w following completion of the involve testing has been completed. Final / determined that the site is ready for 1. PREPARE LOCATION. RIG UP W 2. RELEASE PACKER AND TOOH V 3. TIH W/BIT TO CHECK PB&D TES 4. TOOH W/BIT. 5. TIH W/PKR INJECTION TBG. 6. ATTEMPT TO SET PACKER 20' I 7. CONDUCT MECHANICAL INTEG 8. RDMO WORKOVER RIG. 9. PLACE WELL ON ACTIVE INJEC 10. SUBMIT REPORT ANTICIPATED START DATE 2-12-2 ANTICIPATED START DATE 2-12-2 ANTICIPATED COMPLETION DATE V 14. I hereby certify that the foregoing is tre Name (Printed/Typed) LINDSAY REAMES Signature	rork will be performed or proved operations. If the operation Abandonment Notices must be final inspection.) VORKOVER RIG. NIPPLE W/TBG & PKR. STING TBG. CLEAN OUT F DEEPER SO PACKER WILE RITY TEST. STION 2014 2 2-18-2014 THIS SPACE F Approval of this notice does n the to those rights in the subject f thereon. J.S.C. Section 1212, make it a compared to the section of the section	ide the Bond No. on file with B results in a multiple completio filed only after all requirement UP BOP & ENVIRONMENT/ PERFS IF NECESSARY. L BE WITHIN 100' OF TOP Title ENGINE Date 02/06/20 OR FEDERAL OR ST/ of warrant or certify lease which would Title Office Time for any person knowingly an	LM/BIA. F n or recomp s, including AL PAN. PERFORA ERING TE 14 ATE OFf	Required subsequent repletion in a new interval, reclamation, have been strength of the second secon	orts must be filed within 30 days , a Form 3160-4 must be filed once completed and the operator has INULUS W/PACKER FLUID. CHED FOR APPROVAL INS OF APPROVAL

APR 07 2014

×4



# West Dollarhide Queen Sand Unit 30-025-30355 Chaparral Energy, LLC March 03, 2014 Conditions of Approval

### Work to be completed by June 03, 2014.

١,

## 1. Notify BLM if casing integrity test fails.

- 2. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Surface disturbance beyond the originally approved pad must have prior approval.
- 4. Closed loop system required.
- 5. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 6. Operator to have H2S monitoring equipment on location.
- 7. A minimum of a **2000** (**2M**) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

### 8. Subsequent sundry required detailing work done.

### JAM 030314