

Submit 1 Copy To Appropriate District State of New Mex	
District I – (575) 393-6161 Energy, Minerals and Natur	al Resources Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	20.025.25720
811 S. First St., Artesia, NM 88210, OIL CONSERVATION	DIVISION 5. Indicate Type of Lease
1000 Rio Brazos Rd Aztec NM 87410	STATE FEE
District IV – (505) 476-3460 Santa Fe, NM 87	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, APIR 1 1 2014 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSATISTIO DRILL OR TO DEEPEN OR PLU- DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOI	G BACK TO A CENTRAL VACUUM UNIT
PROPOSALS.) 1. Type of Well: Oil Well 🖉 Gas Well 🛛 Other INJECTOR	8. Well Number 45
2. Name of Operator	9. OGRID Number 4323
CHEVRON U.S.A INC. 3. Address of Operator	10. Pool name or Wildcat
15 SMITH ROAD, MIDLAND, TEXAS 79705	VACUUM G/B SAN ANDRES
4. Well Location	
Unit Letter <u>C</u> : <u>121</u> feet from the <u>NORTH</u> line and <u>2475</u> feet from the <u>WEST</u> line	
Section 31 Township 17-S Range 35-E NMPM County LEA /	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3,977' (GL) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. P AND A
PULL OR ALTER CASING  MULTIPLE COMPL  DOWNHOLE COMMINGLE	
OTHER: OTHER: OTHER: OTHER: OTHER:	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Chevron USA intends to PA the above well as follows: This well was down for MIT failure and was rigged up on 3/23/14 to run a liner and restore the mechanical integrity of the wellbore. It was discovered that the casing was parted from 595 – 610'. The wellbore is beyond repair and P&A operations are underway. Contacted NMOCD and spoke to Maxey Brown, Verbal Approval was given to proceed as follows: Attached wellbore diagram.	
<ol> <li>TIH with 2-3/8" workstring (bent joint, orange-peeled bottom with ¼" slits) and wash down to 3900'. Contact engineer and NMOCD if we can't reach 3900'.</li> </ol>	
<ol> <li>At 3900', establish circulation and spot 235 sks Class C neat cement, flush lines and TOH to surface. Shut in and</li> </ol>	
allow cement to cure.	
3. TIH and tag TOC. Confirm depth with NMOCD.	
4. Continue spotting cement to surface.	
5. ND wellhead and install dryhole cap.	
6. Notify NMOCD and production when finished.	
7. RDMO pulling unit and surface equipment.	
Cand Data:	
Spud Date: Rig Release Dat	e.
I hereby certify that the information above is true and complete to the best	st of my knowledge and belief.
signature and here Muillo title permitting specialist Date04/11/2014	
Type or print name <u>CINDY HERRERA-MURILLO</u> E-mail address:	Cherreramurillo@chevron.com PHONE: 575-263-0431
For State Use Only Mal AMR.	
APPROVED BY: MULLING DATE 4/16/CULL Conditions of Approval (if any):	
V	APR 16 2014

.

## Current Wellbore Diagram CVU 45



## **CVU 45**



## Wellbore Diagram