

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
August 1, 2011

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <b>30-025-37205</b> ✓
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator <b>Rust Oil Corp</b>		6. State Oil & Gas Lease No.
3. Address of Operator <b>6300 Ridglea Place, Ste. 904, Ft. Worth, TX 76116</b>		7. Lease Name or Unit Agreement Name <b>State 22</b> ✓
4. Well Location Unit Letter <b>J</b> : <b>2293</b> feet from the <b>S</b> line and <b>1569</b> feet from the <b>E</b> line Section <b>22</b> Township <b>13-S</b> Range <b>37-E</b> NMPM <input checked="" type="checkbox"/> County <b>Lea</b>		8. Well Number <b>001</b>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number <b>163160</b> <b>162106</b>
		10. Pool name or Wildcat <b>King; Wolfcamp</b>

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

01/16/14 MIRU plugging equipment. Dug out cellar. ND wellhead. NU BOP. 01/17/14 RIH and tag CIBP @ 9400'. Circulate hole w/ mud laden fluid. Spot 25 sx cement @ 9400-9252. POH to 7400'. 01/20/14 Circulate 120 bbls of mud laden fluid. Spot 25 sx cement @ 7400-7147. POH w/ tbg. 01/21/14 Cut casing @ 4780'. ND BOP. POH w/115 jts 5 1/2 csg. NU BOP. 01/22/14 RIH w/ tbg and spotted 45 sx cement @ 4825-4621'. Pull out of cement. WOC. Tagged plug @ 4600'. POH w/ tbg to 3300'. Spotted 40 sx cement @ 3300-3181. POH w/ tbg. 01/23/14 Tagged plug @ 3150'. POH w/ tbg to 2100'. Spotted 40 sx cement @ 2100-1980. Pull out of cement. WOC. Tagged plug @ 1947'. POH w/ tbg. ND BOP. RIH w/ tbg to 480' and spotted 160 sx cement and circulated to surface. 01/24/14 Tagged plug @ 20'. Spotted 15 sx cement @ 20 to surface. rigged down and moved off. 01/28/14 Moved in welder and backhoe. Dug out cellar. Cut off wellhead. Welded on "Above Ground Dry Hole Marker". Backfilled cellar. Cut off and removed deadmen. Cleaned location and moved off.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE CB Rust TITLE President DATE 4/21/14  
Type or print name CB Rust E-mail address: rustoilcorp@gmail.com PHONE: 817-732-9783  
**For State Use Only**  
APPROVED BY: Mary Brown TITLE Dist Supervisor DATE 5/1/2014  
Conditions of Approval (if any):

MAY 01 2014