Submit 1 Copy To Appropriate District State of New Mexico	Farma C 102
Submit 1 Copy To Appropriate District Office District I (575) 393-6161 1625 N. French Dr., Hobbs, NM 595 District II (575) 748-1283 811 S. First St., Artesia, NM 88210 State of New Mexico Energy, Minerals and Natural Resources	Form C-103 Revised August 1, 2011
1625 N. French Dr., Hobbs, NM SSOS	WELL API NO.
District II - (575) 748-1283 District III - (575) 748-1283 District III - (575) 748-1283 OIL CONSERVATION DIVISION District III - (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd, Aztec, NM 8410 Santa Fe, NM 87505 1220 S St Francis Dr. Santa Fe, NM Santa Fe, NM 87505	<u>30-025-20986</u> 5. Indicate Type of Lease
District III – (505) 334-6178 1220 South St. Francis Dr.	STATE STATE
<u>District IV</u> – (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	E-7723
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	State AF
PROPOSALS.) 1. Type of Well: Oil Well \Box Gas Well X Other $S\omega\rho$	8. Well Number 3
2. Name of Operator	9. OGRID Number 222759
BUCKEVE DISPOSAL SWD	
3. Address of Operator PO Box 2724 Lubbock Texus 29408	10. Pool name or Wildcat
4. Well Location	Wolfcamp SWD
Unit Letter <u>L</u> : <u>1980</u> feet from the <u>South</u> line and <u>990</u> feet from the <u>West</u> line	
Section 8 Township /8 5 Range 35 E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUB	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR	
PULL OR ALTER CASING 🛛 MULTIPLE COMPL 🗌 CASING/CEMEN	Т ЈОВ 🗌
OTHER: RUN CASING LINCE	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
1 Rigup pulling with 2 Run Work strong & casing sceaper to 10,400 3 Bill out of hole	
2 RUN WORK STRONG & CASING SCRAPER TO 10, 200	
3 Bill out of hole	
I PIN IN KOLO WITH CAST LEON BRIDGE PING SET AT 10, 400	
5 RUN 4" CASING to 10,350	
6 Cement CASING	
7 RUN INtegrity Test	
7 KUN INTEGNIT TEN	
[] []	
Spud Date: 7-8-14 Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledg	e and helief
Thereby certify that the information above is the and complete to the best of my knowledge and bench.	
SIGNATURE 10 Sour TITLE MANAGER	DATE 10-5-14
Type or printmame <u>3107</u> <u>5A PRF</u> E-mail address: <u>Jum@ the stand And every</u> , <u>co</u> PHONE: <u>575-390-6006</u> For State Use Only A 1 A A A A A A A A A A A A A A A A A	
1000000000000000000000000000000000000	
Conditions of Approval (if any):	

MAY 07 2014

Buckeye Disposal Inc. State "AF" #3

Current Wellbore Sketch

Proposed Wellbore Sketch

