
State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-200

FILE IN TRIPLICATE OIL CONSERVATION DIVISION	
FILE IN TRIPLICATE DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 MAY 1 9 2014 CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO. 30-025-07490
<u>DISTRICT II</u>	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210 RECEIVED	STATE FEE X
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	North Hobbs (G/SA) Unit Section 31
Type of Well: Oil Well X Ga's Well Other	8. Well No. 411
2. Name of Operator Occidental Permian Ltd.	9. OGRID No. 157984
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR I Box 90 Denver City, TX 79323 4. Well Location	1
Unit Letter A : 330 Feet From The North Line and 330 Feet From The East Line	
Section 31 Township 18-S Range 38-1	NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3645' GR	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Ma	terial
12. Check Appropriate Box to Indicate Nature of Notice, Report, or NOTICE OF INTENTION TO: SUB	Other Data SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	X ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP	NO DILIO A ADANDONIMENT
	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the propos	IT JOB, including estimated date of starting any
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. 2. RU wire line and shoot drain holes. RD wire line.	IT JOB, including estimated date of starting any
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed I. RUPU & RU.	IT JOB, including estimated date of starting any
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. 2. RU wire line and shoot drain holes. RD wire line. 3. ND well head/NU BOP 4. POOH and lay down ESP equipment. Hole was found in ESP. 5. R1H w/bit. Chemical treat hole w/500 gal of Xylene pill mixed w/100 gal of 6496 and 20 gal of the state of th	including estimated date of starting any completion or recompletion.
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. 2. RU wire line and shoot drain holes. RD wire line. 3. ND well head/NU BOP 4. POOH and lay down ESP equipment. Hole was found in ESP. 5. R1H w/bit. Chemical treat hole w/500 gal of Xylene pill mixed w/100 gal of 6496 and 20 grant Continue in hole to 4288'. POOH w/bit.	including estimated date of starting any completion or recompletion. al of 6495 chemical. Flush w/25 bbl 10# brine.
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. 2. RU wire line and shoot drain holes. RD wire line. 3. ND well head/NU BOP 4. POOH and lay down ESP equipment. Hole was found in ESP. 5. R1H w/bit. Chemical treat hole w/500 gal of Xylene pill mixed w/100 gal of 6496 and 20 grant Continue in hole to 4288'. POOH w/bit. 6. R1H w/treating packer set @4006'. RU Warrior acid truck and pump 3000 gal of 15% PAI and pump scale squeeze w/100 gal of 6490 chemical mixed w/100 bbl fresh water. Flush w	including estimated date of starting any completion or recompletion. al of 6495 chemical. Flush w/25 bbl 10# brine. D acid in 2 stages. RD acid truck. RU pump truck
PULL OR ALTER CASING	including estimated date of starting any completion or recompletion. al of 6495 chemical. Flush w/25 bbl 10# brine. D acid in 2 stages. RD acid truck. RU pump truck
PULL OR ALTER CASING	including estimated date of starting any completion or recompletion. al of 6495 chemical. Flush w/25 bbl 10# brine. Dacid in 2 stages. RD acid truck. RU pump truck ith 100 bbl fresh water. RD pump truck. POOH
PULL OR ALTER CASING	including estimated date of starting any completion or recompletion. al of 6495 chemical. Flush w/25 bbl 10# brine. acid in 2 stages. RD acid truck. RU pump truck ith 100 bbl fresh water. RD pump truck. POOH
PULL OR ALTER CASING	including estimated date of starting any completion or recompletion. al of 6495 chemical. Flush w/25 bbl 10# brine. acid in 2 stages. RD acid truck. RU pump truck ith 100 bbl fresh water. RD pump truck. POOH 04/17/2014 RDPU 04/25/2014 that any pit or below-grade tank has been/will be
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. 2. RU wire line and shoot drain holes. RD wire line. 3. ND well head/NU BOP 4. POOH and lay down ESP equipment. Hole was found in ESP. 5. RIH w/bit. Chemical treat hole w/500 gal of Xylene pill mixed w/100 gal of 6496 and 20 g Continue in hole to 4288'. POOH w/bit. 6. R1H w/treating packer set @4006'. RU Warrior acid truck and pump 3000 gal of 15% PAI and pump scale squeeze w/100 gal of 6490 chemical mixed w/100 bbl fresh water. Flush w w/treating packer. 7. R1H w/ESP equipment on 119 jts of 2-7/8" tubing. Intake set @3934'. 8. ND BOP/NU well head. 9. RDPU & RU. Clean location and return well to production. RUPU I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative	including estimated date of starting any completion or recompletion. al of 6495 chemical. Flush w/25 bbl 10# brine. acid in 2 stages. RD acid truck. RU pump truck ith 100 bbl fresh water. RD pump truck. POOH 04/17/2014 RDPU 04/25/2014 that any pit or below-grade tank has been/will be
PULL OR ALTER CASING	including estimated date of starting any completion or recompletion. al of 6495 chemical. Flush w/25 bbl 10# brine. acid in 2 stages. RD acid truck. RU pump truck ith 100 bbl fresh water. RD pump truck. POOH 04/17/2014 RDPU 04/25/2014 that any pit or below-grade tank has been/will be
PULL OR ALTER CASING Multiple Completion OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. 2. RU wire line and shoot drain holes. RD wire line. 3. ND well head/NU BOP 4. POOH and lay down ESP equipment. Hole was found in ESP. 5. R1H w/bit. Chemical treat hole w/500 gal of Xylene pill mixed w/100 gal of 6496 and 20 g Continue in hole to 4288'. POOH w/bit. 6. R1H w/treating packer set @4006'. RU Warrior acid truck and pump 3000 gal of 15% PAI and pump scale squeeze w/100 gal of 6490 chemical mixed w/100 bbl fresh water. Flush w w/treating packer. 7. R1H w/ESP equipment on 119 jts of 2-7/8" tubing. Intake set @3934'. 8. ND BOP/NU well head. 9. RDPU & RU. Clean location and return well to production. RUPU constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan	including estimated date of starting any completion or recompletion. al of 6495 chemical. Flush w/25 bbl 10# brine. acid in 2 stages. RD acid truck. RU pump truck ith 100 bbl fresh water. RD pump truck. POOH 04/17/2014 RDPU 04/25/2014 that any pit or below-grade tank has been/will be
PULL OR ALTER CASING	including estimated date of starting any completion or recompletion. al of 6495 chemical. Flush w/25 bbl 10# brine. Dacid in 2 stages. RD acid truck. RU pump truck ith 100 bbl fresh water. RD pump truck. POOH 04/17/2014 RDPU 04/25/2014 that any pit or below-grade tank has been/will be COCD-approved Associate DATE 05/16/2014
PULL OR ALTER CASING	including estimated date of starting any completion or recompletion. al of 6495 chemical. Flush w/25 bbl 10# brine. Dacid in 2 stages. RD acid truck. RU pump truck ith 100 bbl fresh water. RD pump truck. POOH 04/17/2014 RDPU 04/25/2014 that any pit or below-grade tank has been/will be COCD-approved Associate DATE 05/16/2014
PULL OR ALTER CASING	including estimated date of starting any completion or recompletion. al of 6495 chemical. Flush w/25 bbl 10# brine. Dacid in 2 stages. RD acid truck. RU pump truck ith 100 bbl fresh water. RD pump truck. POOH 04/17/2014 RDPU 04/25/2014 that any pit or below-grade tank has been/will be COCD-approved Associate DATE 05/16/2014 TELEPHONE NO. 806-592-6280

Work Plan Report for Well:NHSAU 411-31



Survey Viewer