Form 3160-5 (August 2007) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT OC HODDS SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandone@ well. Use form 3160-3 (APD) for such proposals.					FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMLC060199A 6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agree	ement, Name and/or No.	
I. Type of Well Gas Well Other						8. Well Name and No. CUTTHROAT FEDERAL 5	
2. Name of Operator Contact: JERRY W SHERRELL MACK ENERGY CORPORATION E-Mail: jerrys@mackenergycorp.com						9. API Well No. 30-025-41557-00-X1	
3a. Address	3b. Phone No. (include area code) Ph: 505-748-1288				10. Field and Pool, or Exploratory WC025G06S173230A		
ARTESIA, NM 88211-0960 4. Location of Well (Footage, Sec., T	Fx: 505-746-9539 HOBBS OCD				11. County or Parish, and State		
Sec 29 T17S R32E SWNE 16 32.808247 N Lat, 103.787029	50FNL 2310FEL	· · ·	MAY	212	014	LEA COUNTY, I	•
12. CHECK APPI	ROPRIATE BOX(ES) TO) INDICATE NATU	RE OR	CEIVE	, Dre	PORT, OR OTHE	R DATA
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	🗖 Acidize	🗖 Deepen		🗖 Pro	ductio	on (Start/Resume)	□ Water Shut-Off
Subsequent Report	Alter Casing	Fracture Tre		🗖 Rec			UWell Integrity
	Casing Repair	New Constru			-		Other
Final Abandonment Notice	 Change Plans Convert to Injection 	🗖 Plug and Ab 🔀 Plug Back	andon	🗖 Va	•	rily Abandon isposal	·
 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Mack Energy proposes to plugback well as follows: Squeeze perfs from 9556-9587' w/100 Class H. Set CIBP @ 9500' w/25' cement cap. Perf Abo from 9020-9140'. Acidize well w/2500 gals acid. Put well on pump. 							
14. I hereby certify that the foregoing is	true and correct.						
	Electronic Submission #2	RGY CORPORATION	. sent to	the Hobl	os		
Name(Printed/Typed) JERRY W	SHERRELL	Title	PRODU		CLEI	RK	
Signature (Electronic S	ubmission)	Date	03/17/2	<u>0</u> 14		ACCEPTED F	OR RECORD
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By Conditions of approval, if any, are attached certify that the applicant holds legal or equ which would entitle the applicant to condu Title 18 U.S.C. Section 1001 and Title 43 I States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a	crime for any person know	vingly and		_	CARLSBAD/	6 2015 Data UMAN GEMENT EIELD OFFICE agency of the United
** BLM REVISED **							

MAY	22	2014
-----	----	------

Cutthroat Federal 5 30-025-41557 Mack Energy Corporation May 16, 2014 Conditions of Approval

Notify BLM at 575-393-3612 a minimum of 24 hours prior to commencing work.

Work was done without approval and the following plug back must be completed:

- 1. Operator shall place a minimum of 25 sx Class H Cement on top of the CIBP at 9,520' to seal the top of the Wolfcamp formation. WOC and tag at approximately 9,296'.
- 2. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails.
- 3. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 4. Surface disturbance beyond the originally approved pad must have prior approval.
- 5. Closed loop system required.
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Operator to have H2S monitoring equipment on location.
- 8. A minimum of a **3000** (**3M**) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

9. Subsequent sundry required detailing work done, a C-102 form, and completion report for the new formations. Operator to include well bore schematic of current well condition when work is complete.

10. See attached for general requirements.

JAM 051614

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

General Requirements for Plug Backs

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. **Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat** Class "C", for up to 7,500 feet of depth or **Neat** Class "H", for deeper than 7,500 feet plugs.

6. <u>Subsequent Plug back Reporting</u>: Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed</u>.

7. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.