Form 3160-5 (March 2012)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

5. Lease Serial No. NMLC-030174B

6. If Indian, Allottee or Tribe Name

#### SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

		(PD) for such prop				
· ·	T IN TRIPLICATE – Other	r instructions on page 2.	HORRS OCD	7. If Unit of CA/Agreen	nent, Name and/or No.	
1. Type of Well  Oil Well  Gas Well  Other Injection  MAY 2 1 20			MAY 21 2014	/8. Well Name and No. W H Rhodes B Federal NCT 1 #010		
2. Name of Operator PPC OPERATING COMPANY LLC				9. API Well No. 30-025-12056		
3a. Address 1500 Industrial Blvd, Ste. 102 Abilene, TX 79602		3b. Phone No. (include area <b>REGETVED</b> 325-267-6046		10. Field and Pool or Exploratory Area Rhodes; Yates-Seven Rivers		
4. Location of Well (Footage, Sec., T., 660' FSL & 1980' FWL, UNIT LETTER "N", SEC	ij		11. County or Parish, State LEA COUNTY, NEW MEXICO			
12. CHE	CK THE APPROPRIATE BO	OX(ES) TO INDICATE NA	TURE OF NOTIC	E, REPORT OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
✓ Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Produ	ction (Start/Resume)	Water Shut-Off  ✓ Well Integrity	
Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abando		plete erarily Abandon	Other Repair we	ll
Final Abandonment Notice	Convert to Injection	Plug Back	Water	Disposal		
Attach the Bond under which the variable following completion of the involvatesting has been completed. Final determined that the site is ready for the site is to notify that this well was probeen awaiting approval of the operation of the operation of the operation of the well is equipped as follows:  8 5/8" surface casing set at 1193' or 5 1/2" production casing set at 3118' to 3324' at 318' to 3324' at 318' to 3324' and a solution of the well we will not be solved by the site of the solution of the well we will not be solved by the solution of the so	red operations. If the operations Abandonment Notices must refinal inspection.) essure tested on 4/5/2013 after change to PPC Operations of the operation of th	ion results in a multiple combe filed only after all requir  (NMOCD was notifed 48 ting Company LLC which was cement (28#, H-40 gr	pletion or recomple ements, including r B hours prior). The was approved in rade, 8 rd)	tion in a new interval, a eclamation, have been c e well failed and was i December 2013.	a Form 3160-4 must be fi ompleted and the operato immediately shut-in. W	led once or has
14. I hereby certify that the foregoing is t Jana Spraberry	rue and correct. Name (Printe		ce Adminstrator	APPF	ROVED	
Signature Ana Op	rabenue	Date 01/6	02/2014	A	1 sham	1
()	THIS SPACE	FOR FEDERAL OR	STATE OFF	DE USE/MAI	9. 11 M	
Approved by		Title		BUKEAU OF LA	AD MANAGEMENT refield office	V
Conditions of approval, if any, are attached hat the applicant holds legal or equitable tentile the applicant to conduct operations	itle to those rights in the subject	s not warrant or certify	ee	Unitedipa		Jel

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## Conditions of Approval PPC Operating Company LLC W H Rhodes B Fed NCT 1 - 10 API 30-025-12056 T26S-R37E, Sec 26 May 16, 2014

#### Notify BLM at 575-393-3612 a minimum of 24 hours prior to commencing work.

### Work to be completed by August 16, 2014.

- 1. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 2. Subject to like approval by the New Mexico Oil Conservation Division.
- 3. Surface disturbance beyond the existing pad shall have prior approval.
- 4. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 5. Functional H<sub>2</sub>S monitoring equipment shall be on location.
- 6. 2000 (2M) Blow Out Prevention Equipment to be used. All BOPE and workover procedures shall establish fail safe well control. A ram system including a blind ram and pipe ram(s) designed to close on all of the work string(s) used is required equipment. Manual BOP closure (hand wheels) equipment shall be installed regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) shall be employed when needed for reasonable well control requirements.
- 7. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 8. Determine top of cement behind the 5 1/2" casing. Provide BLM with an electronic copy (Adobe Acrobat Document) cement bond log record from 3000 or below to top of cement. The CBL may be attached to a <a href="mailto:pswartz@blm.gov">pswartz@blm.gov</a> email.
- 9. Confirm that the 5 1/2" casing will hold pressure from 50ft above top perf to TOC.
- 10. If casing leak is located, submit a sundry with repair procedure for BLM approval. No repair work is to be done without approval

#### Well with a Packer - Operations

- 1) Conduct a Mechanical Integrity Test of the tubing/casing annulus after a tubing, packer or casing seal is established. Repair that seal any time more than five barrels of packer fluid is replaced within 30 days.
- 2) The minimum test pressure should be 500 psig for 30 minutes or 300 psig for 60 minutes, with minimum 200 psig differential between tubing and casing pressure (at test time) but no more than 70% of casing burst pressure as described by Onshore Order 2.III.B.1.h. (The tubing or reservoir pressure may need to be reduced). An alternate method for a BLM approved MIT is to have the fluid filled system open to atmospheric pressure and have a loss of less than five barrels in 30 days witnessed by a BLM authorized officer.
- 3) Document the pressure test on a one hour full rotation calibrated recorder chart registering within 25 to 85 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed MIT. Less than 10% pressure leakoff will be evaluated site specifically and may restrict injection approval.
- 4) Make arrangements 24 hours before the test for BLM to witness. In Lea County phone 575-393-3612. If no answer, leave a voice mail or email with the API#, workover purpose, and a call back phone number. Note the contact, time, & date in your subsequent report.
- 5) Submit a subsequent Sundry Form 3160-5 relating the MIT activity. Include a copy of the recorded MIT pressure chart. List the name of the BLM witness, or the notified person and date of notification. NMOCD is to retain the original recorded MIT chart.
- 6) Use of tubing internal protection, tubing on/off equipment just above the packer, a profile nipple, and an in line tubing check valve below the packer or between the on/off tool and packer is a "Best Management Practice". The setting depths and descriptions of each are to be included in the subsequent sundry. List (by date) descriptions of daily activity of any previously unreported wellbore workover.
- 7) Submit the original subsequent sundry with three copies to BLM Carlsbad.
- 8) Compliance with a NMOCD Administrative Order is required, submit documentation of that authorization.
  - a) Approved injection pressure compliance is required.
  - b) If injection pressure exceeds the approved pressure you are required to reduce that pressure and notify the BLM within 24 hours.
  - c) When injection pressure is within 50 psig of the maximum pressure, install automation equipment that will prevent exceeding that maximum. Submit a subsequent report (Sundry Form 3160-5) describing the installed automation equipment within 30 days.
- 9) Unexplained significant variations of rate or pressure to be reported within 5 days of notice.
- 10) The casing/tubing annulus is required to be monitored for communication with injection fluid or loss of casing integrity. A BLM inspector may request verification of a full annular fluid level at any time.
- 11) A "Best Management Practice" is to maintain the annulus full of packer fluid at atmospheric pressure. Equipment that will display on site, continuous open to the air fluid level is necessary to achieve this goal.

- 12) Loss of packer fluid above five barrels per month indicates a developing problem. Notify BLM Carlsbad Field Office, Petroleum Engineering within 5 days.
- 13) A suggested format for monthly records documenting that the casing annulus is fluid filled is available from the BLM Carlsbad Field Office.
- 14) Gain of annular fluid requires notification within 24 hours. Cease injection and maintain a production casing pressure of 0 psia. Notify the BLM's authorized officer ("Paul R. Swartz" cpswartz@blm.gov>, cell phone 575-200-7902). If there is no response phone 575-361-2822.

Submit a original and three copies of (Sundry Form 3160-5) subsequent report (daily reports) describing all wellbore activity and Mechanical Integrity Test as per item 1) above. Include the date(s) of the well work, and the setting depths of installed equipment: internally corrosive protected tubing, tubing on/off equipment just above the packer, and an in line tubing check valve below the packer or between the on/off tool and packer. The setting depths and descriptions of each are to be included in the subsequent sundry. List daily descriptions of any previously unreported wellbore workover(s) and reason(s) the well annular fluid was replaced.

#### JAM/PRS 051614