## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103


FILE IN TRIPLICATE  HOBBS OCD OIL CONSERVATION DIVISION	Revised 5-27-2004
DISTRICTI 1220 South St. Francis Dr.	WELL API NO.
1625 N. French Dr., Hobbs, NM 88240  DISTRICT II  Santa Fe, NMS 8000  HOBBS 8000	30-025-29754 5. Indicate Type of Lease
	STATE FEE X
2 1 1 7 1 1 4 1 7 1 1 4 1 7 1 1 4 1 7 1 1 4 1 7 1 1 4 1 7 1 1 4 1 1 1 1	6. State Oil & Gas Lease No.
1000 Kio Blazos Kd, Aziec, Nivi 67410 BM -	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	South Hobbs (G/SA)
1. Type of Well:	8. Well No. 216
Oil Well Gas Well Other Injector  2. Name of Operator	9. OGRID No. 157984
Occidental Permian Ltd.	9. OGRID No. 157984
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323  4. Well Location	
Unit Letter C: 1166 Feet From The North Line and 2411 Feet From The West Line	
Section 4 Township 19-S Range 38-E	NMPM Lea County
3628' KB	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT	
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	IT JOB
OTHER: Deepen/ OAP	/AT X
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates,	
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
<ol> <li>RU wire line &amp; set blanking plug @3918'. Tested tbg to 2000#. Tested OK. POOH blanking plug.</li> <li>RUPU &amp; RU.</li> </ol>	
3. ND wellhead/NU BOP.	
4. POOH w/injection packer.	
5. RIH w/bit and drill collars. Tag @4168'. NU stripper head & power swivel. Drill from 4168-4200'. Started getting new formation at 4210'. Drill new formation from 4210-4240' (new TD). Circulate clean. ND power swivel and stripper head. POOH w/bit & drill collars.	
6. RU Renegade wire line & perforate @4090-93', 4109-17', 4121-36'. RD wire line.	
7. RIH w/treating packer set @4050'. RU Warrior Energy and acid treat perfs in 3 stages w/4500 gal of 15% NEFE HCL acid & 1500# gelled rock salt block. Flushed w/50 bbl of 10# brine. RD Warrior Energy. POOH w/treating packer	
8. RIH w/bit. Tag @4240'. POOH w/bit.	
9. RIH w/Arrowset 1-X Double Grip Packer set on 120 jts of IPC tubing. Packer set @4059	
***see attached sheet for additional information***  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be	
constructed or	
closed according to NMOCD guidelines , a general permit or an (attached) alternative	e OCD-approved
Mandy 73 ( Ash and	
TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO. 806-592-6280	
For State Use Only	
APPROVED BY MALLY DOWN TITLE DIST. SUPLIMISATE 6/16/2014	
CONDITIONS OF APPROVAL IF ANY:	
	•

JUN 16 2014


## SHU 216 API #30-025-29754

- 10. Test casing to 560 PSI for 30 minutes and chart for the NMOCD.
- 11. ND BOP/NU wellhead.
- 12. RDPU & RU. Clean location and return well to injection.

RUPU 05/01/2014 RDPU 05/07/2014



## Work Plan Report for Well:SHOU-216C04



## **Survey Viewer**